

CITY (No. PW071002-09 | ITY

Engineering Division

300 Sixth Street
Rapid City, SD 57701-2724
Telephone: 605-394-5377-227
FAX: 605-394-6636
Douglas Adelman
doug.adelman@rcgov.org

July 3, 2002

RE: Crosswalk request on Cathedral Drive between 5th Street and Mt. Rushmore Rd.

Per the June 26, 2002 Public Works Session of the Council, the following is a summary of alternatives, the associated cost estimates, and a relative safety rating (5 is highest level of safety).

I would like to emphasize three points:

- 1) The installation of a crosswalk with or without flashing lights is not appropriate for this roadway, given the lack of adequate gaps in traffic.
- 2) Pedestrian counts indicate insufficient pedestrian volumes to warrant a crosswalk.
- 3) A signalized intersection at the hi-rise apartment building should only be considered when pedestrian or vehicular warrants are met at this location because of the resulting close signal spacing.

