

INSPECTOR'S REPORT

CITY OF RAPID CITY

300 SIXTH STREET RAPID CITY SD 57701
(605) 394-4157

PERMIT NUMBER SUBSTANDARD

ADDRESS 1309 MILWAUKEE

OWNER
CONTRACTOR(S)

DATE 09/22/2006

TIME 9:53

9:30 AM THU 22 SEPT / COOL 46° /
RAIN / CLOUDY

INSPECTION(S) NEEDED:

- | | |
|---|---------------------------------------|
| <input type="checkbox"/> Electrical | <input type="checkbox"/> Excavation |
| <input type="checkbox"/> Plumbing | <input type="checkbox"/> Framing |
| <input type="checkbox"/> Mechanical | <input type="checkbox"/> Final |
| <input type="checkbox"/> Concrete | <input type="checkbox"/> JOB COMPLETE |
| <input type="checkbox"/> Checklist Used | |
| <input checked="" type="checkbox"/> Other SUBSTANDARD | |

DESCRIPTION OF INSPECTION 2098 SUBSTANDARD
PREMISES USED FOR E

CORRECTIONS/COMMENTS PRESENT: DE GLOOSE KURTENBACH, SOWN, 1 OFFICER OUTSIDE, 2 ADULTS INSIDE, 1 CHIN 3065/3065

- 1) SERVICE 12" FLOW CAR - NEEDS ATTENTION 605.1
- 2) 60 AMP PANEL IN CABINET - WOULD NOT MEET CURRENT LOAD 604.3
- 3) EXT ELEC FIXTURES LOOSE - WIRES EXPOSED (GARAGE) 604.3
- 4) LOOSE SIDING/TRIM
- 5) PEELING PAINT / ROTTED TRIM ON WINDOWS + TRIM
- 6) GUTTER PLUGGED NOT FUNCTIONAL
- 7) APPARENTLY ENOUGH HEAT - HOWEVER SW BEDROOM 50° - NO STEAMER ON CEILING
- 8) BLACK MOLD VISIBLE IN WALLS @ SW BEDROOM
- 9) ROOF REPAIRED - SHINGLE SPICE IMPROPERLY DONE
- 10) SOME WATER DAMAGE EVIDENCE VISIBLE ON BOTTOM OF PLYWOOD IN ATTIC
- 11) SHED @ REAR FULL OF JUNK + OPEN
- 12) FILTHY CONDITIONS INSIDE CALL 394-4157 TO SCHEDULE RE-INSPECTION.
- 13) FILTHY YARD / JUNK / DEBRIS / TRASH / TURDS / BULKY MATERIALS
- 14) ADDRESS # MISSING

B/S 9-22-06

FILE COPY

INSPECTOR

DATE