



- ① No Concrete Support
- ② Enclosure held water causing dry rot.
- ③ Columns were 2 PC and buckled at midway