

SOUTH DAKOTA HISTORIC INVENTORY

Historic Name Unknown
 Location 923 Fulton St.
 Historic Function residence

Historic Context(s)
 Topic V. Depression and Rebuilding
 Study Unit 1 A. Changing Urban Patterns
 Study Unit 2 3. Residential Changes...

Owner's Name Michael & Connie McDaniel
 Owner's Address 911 1st St. South
Bemidji, MN 56601

Owner's Phone # _____

Dates of Construction and Founding
1911

Roll # 12; 23 Frame # 32, 33; 6

Attach Photos Here ↓



Gable-fronted dwelling with bracketed eaves and leaded glass windows. Dormers east and west, bay window east.

Site Number

PN		RC		18
County	Township Name	City (Urban)	Neighborhood (Urban)	Number

U.S.G.S. Quad Map Name _____

Legal Description W 1/2 of Lot 12, All of Lot 13, E 1/2 of Lot 14, Block 27, Boulevard

			Addition	
Q1	Q2	Sec	T	R

Surveyors Michael Koop

Date August 1990

NR Eligible

Historic Significance Local

Architect. Sign State

Archaeological Sign Nat'l

Urban only

A B C D

Site Number/Code	Date of Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Photo Info.
Materials	FOUNDATION								
Method of Construction									
Design Details									
Condition		deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____
Materials	WALLS								
Method of Construction									
Design Details									
Condition		deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____
Materials	ROOF								
Method of Construction									
Design Details									
Shape									
Condition		deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____
Interior Features - Moldings, Fireplaces, Org. cabinets, Wall decoration	INTERIOR								
Condition		deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____

Site Number/Code	Date of Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Photo Info.
PN-RC-18	1911	residence							
Materials	FOUNDATION	stone							
Method of Construction		rock-faced coursed							
Design Details									
Condition		deteriorated _____ poor maint. _____ altered _____	deteriorated _____ poor maint. _____ altered _____	deteriorated _____ poor maint. _____ altered _____					
Materials	WALLS	clapboards							
Method of Construction		wood frame							
Design Details									
Condition		deteriorated _____ poor maint. _____ altered _____	deteriorated _____ poor maint. _____ altered _____	deteriorated _____ poor maint. _____ altered _____					
Materials	ROOF	wood shingle							
Method of Construction									
Design Details									
Shape		gable							
Condition	deteriorated _____ poor maint. _____ altered _____	deteriorated _____ poor maint. _____ altered _____	deteriorated _____ poor maint. _____ altered _____						
Interior Features - Moldings, Fireplaces, Org. cabinets, Wall decoration	INTERIOR								
Condition		deteriorated _____ poor maint. _____ altered _____	deteriorated _____ poor maint. _____ altered _____	deteriorated _____ poor maint. _____ altered _____					

PLANNING

Site Number/Code PW-RC-18

Preservation Strengths of Site

- In use and not threatened
- In good structural condition
- Owners protecting site
- Appreciated by public
- Valuable to research

Preservation Threats

- Abandonment
- Deterioration through lack of resources
- Vandalism or looting
- Inappropriate alterations
- Inappropriate or poor maintenance
- Fragile or deteriorating construction materials
- Unsound fragile condition
- Lack of support (specify by whom)

Environmental situation(s) effecting site (specify what; may include mining, flooding erosion, pollution, acid rain, weather, isolation, settlement, etc.)

CONTEXT

Site Number/Code PN-RC-18

Statement of Significance As It Relates to the Context Topics & Study Units.

In the context of Depression & Rebuilding, this house contributes to the significance of the district because it represents a change in the architectural design of Rapid City's residential architecture.

Sources of Information

Oral Interview
(name & dates)

Atlas
(date & publisher)

County History
(name & pages)

Deed Abstract

Tax Records

Equ. Division Office records

Sanborn-Ferris
Maps (dates)

1923, 1937

Census Records

Historic Photos
(description & date)

Manuscripts
(name & date)

HISTORY

Date of founding of institution or of settlement _____

Previous owners of the site _____

First owners _____
and dates _____
of ownership _____

Place of origin of owners _____

Date owners came to SD (& USA) _____

Occupation of owners _____

Historic owners: religious affiliation _____

Historic owners: social (fraternal) affiliations _____

Historic uses of the site (& buildings) residence _____

Builder's name unknown _____

Architect's name unknown _____

Date of commission _____ Date of construction 1911 _____

History (attach research materials to file)

