

SOUTH DAKOTA HISTORIC INVENTORY

Historic Name Lampert House

Location 914 West Boulevard St.

Historic

Function residence

Historic Context(s)

Topic v. Depression & Rebuilding

Study Unit 1 A. Changing Urban Patterns

Study Unit 2 3. Residential Changes...

Owner's Name James + Beverly Shaw

Owner's Address 914 West Boulevard St.
RC. 57701

Owner's Phone # unlisted

Dates of Construction and Founding

1913

Roll # 10; 33 Frame # 14-16; 33

Attach Photos Here ↓



Site Number

PN		RC		113
----	--	----	--	-----

County

Township Name

City (Urban)

Neighborhood (Urban)

Number

U.S.G.S. Quad Map Name

Lots 17-21, Block 121, Original Townsite

Legal Description

--	--	--	--	--

Q1

Q2

Sec

T

R

Surveyors Michael Koop

Date August 1990

NR Eligible

Historic Significance

Local

Architect. Sign

State

Archaeological Sign

Nat'l

Urban only

A

B

C

D



One-story vernacular dwelling with 1/2 double hung sash, side passage, and turned baluster at entry.

CONTEXT

Site Number/Code PN-RC-113

Statement of Significance As It Relates to the Context Topics & Study Units.

In the context of Depression and Rebuilding, this house contributes to the significance of the district because it represents a change in the architectural design of Rapid City's residential architecture.

Sources of Information

Oral Interview
(name & dates)

Atlas
(date & publisher)

County History
(name & pages)

Deed Abstract

Tax Records *Equalization Office records*

Sanborn-Ferris
Maps (dates) *1909, 1915, 1923, 1930*

Census Records

Historic Photos
(description & date)

Manuscripts
(name & date)

Preservation Strengths of Site

- In use and not threatened
- In good structural condition
- Owners protecting site
- Appreciated by public
- Valuable to research

Preservation Threats

- Abandonment
- Deterioration through lack of resources
- Vandalism or looting
- Inappropriate alterations
- Inappropriate or poor maintenance
- Fragile or deteriorating construction materials
- Unsound fragile condition
- Lack of support (specify by whom)

Environmental situation(s) effecting site (specify what; may include mining, flooding erosion, pollution, acid rain, weather, isolation, settlement, etc.)

Site Number/Code	Date of Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Photo Info.
PN-RC-113	1913	residence							
Materials	FOUNDATION	stone							
Method of Construction		rock-faced coursed							
Design Details									
Condition		deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____		
Materials	WALLS	clapboards							
Method of Construction		wood frame							
Design Details									
Condition		deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____		
Materials	ROOF	wood shingle							
Method of Construction									
Design Details									
Shape		hipped							
Condition	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____			
Interior Features - Moldings, Fireplaces, Org. cabinets, Wall decoration	INTERIOR								
Condition		deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____	deteriorated _____ altered _____	poor maint. _____		

HISTORY

Date of founding of institution or of settlement _____

Previous owners of the site _____

First owners Arthur A. Lampect
and dates
of ownership _____

Place of origin of owners _____

Date owners came to SD (& USA) _____

Occupation of owners vice president of the Rapid City Lumber Company

Historic owners: religious affiliation _____

Historic owners: social (fraternal) affiliations _____

Historic uses of the site (& buildings) residence

Builder's name unknown

Architect's name unknown

Date of commission _____ Date of construction 1913

History (attach research materials to file)

