

View A



SW view
View B



view ^{S view} C



VIEW D



Exhibits 1-4



Exhibit 1



Exhibit 2



Exhibit 3




Exhibit 4

original brick freight building [north side]



	estimated cost	labor	materials	total
--	----------------	-------	-----------	-------

pressure wash / blast doors, railing and minor paint on wall				
---	--	--	--	--

remove plywood, repair glass, stain and seal doors				
---	--	--	--	--


prime, paint metal door track stain, seal wood behind track				
--	--	--	--	--

make new lattice vent grates to match original and install under doors				
--	--	--	--	--

Exhibit 5

notes


front brick [not original] adjust color




front brick painted to match original brick
[grayer]




example of foam board on sign
sculpted and painted to match building



original brick on freight building



non original remodel brick wall
[front]



front brick painted to match original brick

estimated cost labor materials total

repaint front brick to match original brick

notes

Exhibit 6

GRACE RESTORATIONS
2014

Exhibit 6