

To City Counsel,

I would like to remove ^(near) the structure at 908 south street. Rebuilding of the structure is not feasible because of a tree root system growing up under the exterior walls. All of the lumber is at least partially rotten. Some is entirely rotten. Roof trusses are fatigued and sagging under the weight of the roof system. The window frames are deteriorated and cracked from the building leaning to the side. Nearly all fasteners are loose or missing entirely. To ^(rebuild would be the same existing structure) rebuild would be labor intensive, costly, and would result in a less than desirable result.

Thanks,

Lynn Uhrig + Nicole Harvieux



6-4-12