

Inspections for June/July/August 2010

Permit No	Site Name	Inspection Date	Reason
08-AQ-036	Homestead Subdivision Phase I	6/4/2010	Routine
Inspection Details			
Inspected site for sediment transport into the street. Sediment was present at the corner of Ziebach and Homestead Street.			
Action	Call Contractor/Applicant		
Followup			
Left message for Dan Wilson regarding the cleanup of the mud in the street.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-003	First Evangelical Free Church	6/4/2010	Routine
Inspection Details			
Inspected site for sediment transport into the street. Mud was tracked out from the site parking lot entrance along Shelby Ave to Sandra to Parkview all the way to 5th Street.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Todd Wirth regarding the cleanup of the mud and the tracking into the streets. Requested that the streets be swept.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-024	Tish Blvd Extension & E. Mall Drive Widening	6/4/2010	Follow up
Inspection Details			
Tish Blvd has been cleaned up since last inspection. Addition wattles were placed along the west side of Tish Blvd. Tractor is onsite - seeding appears to have been started.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-028	Telco Federal Credit Union	6/4/2010	Follow up
Inspection Details			
Street has been cleaned up and addition erosion and sediment controls are in place.			
Action	None		
Followup			
Continue regular inspections.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-032	Word of Hope Church	6/4/2010	Follow up
Inspection Details			
Parking lot and Jolly Lane were clean. The north portion of the site has been stabilized with mulch and the sediment cleaned up.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-034	RC Fire Department Fire Station #7	6/4/2010	Routine
Inspection Details			
Grass is starting to grow in the seeded areas.			
Action	None		
Followup			
Continue regular inspections.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-015	Marlin Storage Units	6/4/2010	New Project
Inspection Details			
Rock construction entrance is in place. Fill material has been hauled to the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-016	Mountain View Apt.	6/4/2010	New Project
Inspection Details			
Portion of project in the City limits of Rapid City has been disturbed. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-025	Dakota Discount Site	6/7/2010	Completion
Inspection Details			
Northwest corner of site is mostly vegetated or graveled.			
Action	Completion Form		
Followup			
Close Permit			

Permit No	Site Name	Inspection Date	Reason
08-AQ-036	Homestead Subdivision Phase I	6/7/2010	Follow up
Inspection Details			
Inspected site to determine if cleanup of sediment in the street was complete. Appeared that site had not been cleaned up.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Dan Wilson and he said it would be taken care of later this afternoon or tomorrow morning.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-003	First Evangelical Free Church	6/7/2010	Follow up
Inspection Details			
Inspected site to determine if mud and tracking had been cleaned up. The clean up was not done.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Todd Wirth about cleaning up the area.			

Permit No	Site Name	Inspection Date	Reason
08-AQ-028	Hilltop Business Park Subdivision	6/10/2010	Routine
Inspection Details			
In the process of removing the stockpiles from the site. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-036	Homestead Subdivision Phase I	6/10/2010	Follow up
Inspection Details			
Inspected site to determine if clean up of sediment in street was complete. Site had not been cleaned up.			
Action	Call Contractor/Applicant		
Followup			
Called Dan Wilson and he said it was suppose to be taken care of but he will clean it up right away. Inspected site - the majority of the sediment was cleaned up.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-003	First Evangelical Free Church	6/10/2010	Follow up
Inspection Details			
Site has not been cleaned up.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Todd Wirth about the clean up. He said that it was suppose to have been cleaned up yesterday. He will call me back and let me know when it will be cleaned up. Todd called back and said that the site had been cleaned up. They have one more day of grading left on the site.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-024	Tish Blvd Extension & E. Mall Drive Widening	6/10/2010	Routine
Inspection Details			
Project appears to be mostly complete. Tractor is on site for seeding.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Terry Larson from Heavy Constructors, they are planning to finish up the seeding and mulching this week weather permitting. The reclamation should be completed prior to the expiration of the permit.			

Permit No	Site Name	Inspection Date	Reason
07-AQ-057	Fairfield Inn & Suites	6/17/2010	Routine
Inspection Details			
No new activity.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-009	Eagle Ridge Apartments	6/17/2010	Routine
Inspection Details			
An erosion and sediment control blanket is in place in the unstable area of the site. Additional wattles are in place. The parking lot was free of sediment.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-034	Lot 2 Huffman - On the Border	6/17/2010	Routine
Inspection Details			
New grass starting is starting to fill in the disturbed areas. Some of the stockpile has been removed from the site. New silt fence has been installed along the northwest side of the lot.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-043	Swander's Addition	6/17/2010	Routine
Inspection Details			
Outer edges of the lot on the west side of Biernbaum Lane have been graded. The remaining areas on the east lot have been graveled. No visible emissions or trackout from the site were noted at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-016	Rapid City 2nd Ward LDS Meetinghouse	6/17/2010	Routine
Inspection Details			
All landscaping appears to be complete.			
Action	Follow-up Inspection		
Followup			
Inspect for growth prior to closing permit.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-022	Site Prep for CSMS Expansion	6/17/2010	Routine
Inspection Details			
Appears that a small amount of dirt work was done on site. The National Guard will no longer be involved in the project.			
Action	Call Contractor/Applicant		
Followup			
According to John Leahy the National Guard has reclaimed most of the area with wood chips. Work will start soon using the area as borrow for a landfill capping project. Rapid Construction will be the contractor so a new air quality construction permit will be obtained for the work.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-024	Tish Blvd Extension	6/17/2010	Completion
Inspection Details			
Seeding and mulching are complete along Tish Boulevard. Area north of E. Mall Drive has been seeded and the mulching is in progress. Hay bales are on site to finish mulching.			
Action	Follow-up Inspection		
Followup			
Conduct follow up inspection for growth prior to closing permit.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-025	PLM Subdivision Phase 1B1	6/17/2010	Completion
Inspection Details			
Grass is established.			
Action	Completion Form		
Followup			
Close Permit			

Permit No	Site Name	Inspection Date	Reason
09-AQ-026	Reservoir Road & Longview Road	6/17/2010	Routine
Inspection Details			
Construction entrance in the staging area along Longview Road is in good condition. Gravel along Longview and Reservoir Road has been recently wet down. Appear to be working on preparing the intersection and a portion of Reservoir Road for pavement. Active excavation along Reservoir Road north of the intersection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-028	Telco Federal Credit Union	6/17/2010	Routine
Inspection Details			
No work has been done on site. No visible emissions were observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-031	West River Electric	6/17/2010	Routine
Inspection Details			
Vegetation is starting to establish on the stockpile. Actively working on building construction. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-032	Word of Hope Church	6/17/2010	Routine
Inspection Details			
Grass is starting to grow on the north portion of the site that was previously seeded. Working on seeding and mulching the remainder of the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-034	RC Fire Station #7	6/17/2010	Routine
Inspection Details			
Landscaping appears to be complete. Remaining areas have been hydroseeded.			
Action	None		
Followup			
Conduct follow up inspection for growth prior to closing permit.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-037	Catron Boulevard Sanitary Sewer	6/17/2010	Routine
Inspection Details			
Vegetation is established on most of the project area.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-038	Sam's Club	6/17/2010	Routine
Inspection Details			
Actively working on site. A backhoe was observed loading a truck with minimal visible emissions observed from trucks traveling over the haul roads. A water truck was on site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-001	Jackson Springs Water Transmission Mains	6/17/2010	Routine
Inspection Details			
Working along Beach Drive and grading site east of Park entrance. Parking lot at Canyon Lake is partially disturbed. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-002	Storage Place	6/17/2010	Routine
Inspection Details			
Appears that only minor site work has been done since last inspection. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-003	Outlot 4	6/17/2010	Routine
Inspection Details			
All stockpiles have been removed from the site. Paving is complete on west and south sides of the building.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-006	Dakotah Steak House	6/17/2010	Routine
Inspection Details			
Additional fill has been hauled in to the site. No active hauling or visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-007	Hartland Court Relocation	6/17/2010	Routine
Inspection Details			
Placing top soil along old Hartland Court. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-008	Pizza Ranch	6/17/2010	Routine
Inspection Details			
Actively preparing site for pavement. No visible emissions or trackout were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-010	Gikling & Meier Warehouse	6/17/2010	Routine
Inspection Details			
Appear to be preparing site on south side of building for paving. Stockpile is present on the southeast corner of the site. No trackout or visible emissions were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-013	Toyota	6/17/2010	Routine
Inspection Details			
A backhoe, grader and dozer were observed actively working on site with no visible emissions observed. The rock construction entrance is in place along Tish Boulevard.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-016	Mountian View Apt.	6/17/2010	Routine
Inspection Details			
No active work was observed in the portion of the project in the Rapid City limits. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-018	Eglin Street Extension	6/17/2010	New Project
Inspection Details			
Appears that minor grading has started on the project. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-019	Land Development - 4590 Elk Vale Road	6/17/2010	Routine
Inspection Details			
Equipment is on site with some minor work started. Gravel access road into site is in good condition. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-044	Hanson-Larsen Memorial Park	6/24/2010	Routine
Inspection Details			
Active trail construction was not observed at the time of inspection. Visible emissions from the project area were not observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-029	Elm Avenue Reconstruction - Phase 3	6/24/2010	Routine
Inspection Details			
Actively pouring the replacement sidewalk along Elm Avenue with pavement in place in some areas on the north end of the project. No visible emission or trackout from the site were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-036	Park Meadows Subdivision - Phase 4	6/24/2010	Routine
Inspection Details			
The paving of Smith Avenue is complete to connect Smith Avenue through the Park Meadows Subdivision. Equipment is still on site. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-004	E. St. Francis/E. St. Anne & Birch Ave Reconstruct	6/24/2010	Routine
Inspection Details			
Construction along Birch Avenue is complete and sod is in place. Work is beginning on the next phase of the project.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-005	11th Street Alley Sewer Project	6/24/2010	Routine
Inspection Details			
Sidewalks are replaced on the northern end of the project area and working on surface materials on the northern end of project. Actively working on sewer main replacement in the alley from Franklin Street to Saint Charles Street. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-009	Oak Avenue, Oak Drive & Oakland Drive	6/24/2010	Routine
Inspection Details			
Excavating at the intersection of Oak Drive and Oakland Street. No visible emissions were observed at the time of the inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-012	Saint Andrew Street Reconstruction	6/24/2010	Routine
Inspection Details			
Actively working on Saint Andrew Street across Elm Avenue and near the intersection of Saint Andrew Street and Lincoln Avenue. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School Addition	6/24/2010	Routine
Inspection Details			
Actively working in the parking lot north of Central High School. The detention ponds along Rapid Creek have been graded. Trackout control devices are in place along N Mount Rushmore Road. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-015	Marlin Storage Units	6/24/2010	Routine
Inspection Details			
Observed site from Elk Vale Road. The stockpiles on the site were graded. No current activity or visible emissions were observed from the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-017	Street Rehabilitation Project Saint Cloud Street	6/24/2010	New Project
Inspection Details			
Actively excavating along the north lane of Saint Cloud Street. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-020	Black Hills - Car Wash	6/24/2010	New Project
Inspection Details			
A portion of the site has been rough graded. No activity, visible emissions or trackout were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-021	West Chicago Area Water Main Reconstruction	6/24/2010	New Project
Inspection Details			
Actively working along West Chicago Street on the water service lines. Small stockpile of dirt was located along W Chicago Street with no visible emissions observed from the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
06-AQ-014	Canyon Springs	6/25/2010	Follow up
Inspection Details			
No activity was observed at the time of inspection.			
Action	Follow-up Inspection		
Followup			
Contacted the County regarding the project.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-038	Sam's Club	6/25/2010	Routine
Inspection Details			
Observed site due to the recent dry conditions. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-013	Toyota	6/25/2010	Routine
Inspection Details			
Observed a tractor with a disc actively working. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-028	Hilltop Business Park Subdivision	7/1/2010	Routine
Inspection Details			
One vegetated stockpile remains on site. Loader and truck were staged on site with no activity or visible emissions observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-003	First Evangelical Free Church	7/1/2010	Routine
Inspection Details			
Appears that site grading is complete and topsoil has been hauled in to the site. Some topsoil has been spread on the south side of the lot. Visible emissions and mud tracking were not observed at the time of the inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-015	Tower Road Reconstruction Project	7/2/2010	Completion
Inspection Details			
Erosion from the site is occurring and requires maintenance of the erosion and sediment controls. Areas of the site require permanent revegetation. A sweeper was observed sweeping Tower Road at the time of the inspection.			
Action	Send Letter		
Followup			
Send letter for permit renewal and additional reclamation letter.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-002	Storage Place	7/2/2010	Routine
Inspection Details			
No activity was observed at the time of inspection. A small gravel stockpile is on site north of the newly constructed storage unit. No visible emissions or trackout from the site were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-022	Knollwood Drainage Outfall	7/6/2010	New Project
Inspection Details			
Two scrapers were actively working on the Tract 1 and Tract 2 lots of the Bradsky #2 Subdivision. The rock construction entrance along Creek Drive is in place. No trackout from the site was observed on Creek Drive. A water truck was on site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
07-AQ-057	Fairfield Inn & Suites	7/9/2010	Routine
Inspection Details			
No new activity.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-009	Eagle Ridge Apartments	7/9/2010	Routine
Inspection Details			
No change since last inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-028	Hilltop Business Park Subdivision	7/9/2010	Routine
Inspection Details			
Site is mostly gravel. One vegetated stockpile remains onsite. No activity or visible emissions were observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-034	Lot 2 Huffman Sub. - On The Border Restaurant	7/9/2010	Routine
Inspection Details			
Grass is starting to grow on the stockpile. Vegetation is growing in on the disturbed areas. No site activity or visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-003	First Evangelical Free Church	7/9/2010	Routine
Inspection Details			
Topsoil has been hauled to the site for parking lot island landscaping. Appears that minor dirt work has been done since the last inspection. A small stockpile of rock was present at the end of Shelby Avenue. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-026	Reservoir Road & Longview Road	7/9/2010	Routine
Inspection Details			
Reservoir Road up through the intersection with Longview Road has been paved. Actively working on Reservoir Road north of the intersection. Gravel on Reservoir Road was recently wet down to control dust.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-031	West River Electric	7/9/2010	Routine
Inspection Details			
Working on WREA building. No visible emissions or trackout were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-032	Word of Hope Church	7/9/2010	Routine
Inspection Details			
The site is mostly stable. Grass is starting to grow in seeded areas. No visible emissions or trackout were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-035	Murphy Ranch Estates Subdivision	7/9/2010	Routine
Inspection Details			
Some vegetation is starting to fill in the bare areas.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-037	Catron Boulevard Sanitary Sewer	7/9/2010	Routine
Inspection Details			
Vegetation is established and the site is appears to be mostly stable.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-006	Dakotah Steak House	7/9/2010	Routine
Inspection Details			
The stockpiles on the site have been rough graded. No activity or visible emissions were observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-010	Gikling & Meier Warehouse	7/9/2010	Routine
Inspection Details			
Area around the warehouse appears to have been mostly leveled out. A small dirt stockpile is located on the west end of the lot. No trackout or visible emissions were observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-016	Mountain View Apt.	7/9/2010	Routine
Inspection Details			
No activity or visible emissions were observed on the portion of the property in Rapid City Limits. Silt fence is in place.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-018	Eglin Street Extension	7/9/2010	Routine
Inspection Details			
Area has been rough graded and a water truck was observed onsite. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-019	Land Development	7/9/2010	Routine
Inspection Details			
Bobcat and small dirt stockpiles are located onsite. No activity or visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-001	Jackson Springs Water Transmission Mains	7/15/2010	Routine
Inspection Details			
Grass is established in area around Park Drive east to the Canyon Lake Park entrance. Pavement is also in place in the parking lot east of the park entrance. The pavement along Beach Drive has been removed. The project is currently on hold.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-007	Hartland Court Relocation	7/15/2010	Routine
Inspection Details			
Hartland Court has been paved. Grass is starting to grow in disturbed area along Dover Street and 32nd Street.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-021	West Chicago Area Water Main Reconstruction	7/15/2010	Routine
Inspection Details			
Sidewalk removed as part of the project along West Chicago Street has been replaced. The project area along West Chicago Street appears to be ready for sod. No activity or visible emissions were observed from the project area at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-005	11th Street Alley Sewer Project	7/16/2010	Complaint
Inspection Details			
A complaint was received regarding traffic on Kansas City Street between West Boulevard and 11th Street causing fugitive dust. The road was dirty and part of the pavement has been removed as part of the project.			
Action	Call Contractor/Applicant		
Followup			
Staff contacted the engineering inspector and he spoke with the contractor. The contractor will clean up the area. The road is expected to be patched in about a week.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-005	11th Street Alley Sewer Project	7/19/2010	Follow up
Inspection Details			
Conducted follow up inspection of Kansas City Street due to complaint received. Appears that barricades were moved to cover more of the area under construction and some material was cleaned up off of the road. Observed vehicles traveling over Kansas City Street and did not observe visible emissions created by the traffic.			
Action	Follow-up Inspection		
Followup			
Continue to monitor area			

Permit No	Site Name	Inspection Date	Reason
10-AQ-013	Toyota	7/19/2010	Routine
Inspection Details			
Backhoe was observed stockpiling dirt. The trackout control device along E. Mall Drive appears to be in good condition. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-038	Sam's Club	7/20/2010	Routine
Inspection Details			
Working on construction of Sam's Club building. Base layer for parking lot is down. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-003	Outlot 4	7/20/2010	Routine
Inspection Details			
Some of the landscaping for the lot is complete. No visible emissions or trackout from the site were observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-036	Homestead Subdivision Phase 1	7/21/2010	Routine
Inspection Details			
Vegetation is established on the site.			
Action	Completion Form		
Followup			
Close Permit			

Permit No	Site Name	Inspection Date	Reason
08-AQ-044	Hanson-Larsen Memorial Park	7/21/2010	Routine
Inspection Details			
Active trail construction was not observed at the time of inspection. Visible emissions from the project area were not observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-024	Tish Blvd Extension	7/21/2010	Routine
Inspection Details			
Vegetation is starting to grow in the seeded areas. No visible emissions were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-028	Telco Federal Credit Union	7/21/2010	Routine
Inspection Details			
No work has been done since the last inspection. Erosion and sediment controls appear to be in good condition and are sufficient to prevent major sediment transport from the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-029	Elm Avenue Reconstruction- Phase 3	7/21/2010	Routine
Inspection Details			
Elm Avenue has been paved. Actively working on landscaping & sidewalk ramps. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-034	RC Fire Department Fire Station #7	7/21/2010	Routine
Inspection Details			
Small topsoil stockpile is present on the south side of Fire Station #7. Some areas appear to need additional reclamation.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-036	Park Meadows Subdivision - Phase 4	7/21/2010	Routine
Inspection Details			
Some vegetation is starting to grow on newly graded areas. Appears that additional wattles were recently installed onsite.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-005	11th Street Alley Sewer Project	7/21/2010	Follow up
Inspection Details			
Conducted follow up inspection due to complaint. One lane of Kansas City Street is open and clean.			
Action	Follow-up Inspection		
Followup			
Continue frequently inspecting the area			

Permit No	Site Name	Inspection Date	Reason
10-AQ-008	Pizza Ranch	7/21/2010	Routine
Inspection Details			
The Pizza Ranch parking lot has been paved. Working on site sidewalk installation along Luna Avenue. No visible emissions or trackout from the site were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-009	Oak Avenue, Oak Drive & Oakland Drive	7/21/2010	Routine
Inspection Details			
Oak Drive has been paved. Actively working on Oak Avenue. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-011	Landfill Gas Collection System	7/21/2010	Routine
Inspection Details			
Working on eastern portion of project area. No visible emissions were observed from the project area at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School Addition	7/21/2010	Routine
Inspection Details			
Excavating in parking lot area north of Central High School. Actively grading parking lot addition on the east side of Central High School. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-015	Marlin Storage Units	7/21/2010	Routine
Inspection Details			
Rock construction entrance is insufficient to prevent tracking. Significant mud tracking observed on Marlin Drive from the fill site.			
Action	Call Contractor/Applicant		
Followup			
Left a message for Bob Scull regarding improving the construction entrance and cleaning up Marlin Drive.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-020	Black Hills - Car Wash	7/21/2010	Routine
Inspection Details			
Two large stockpiles are stored on the western side of the lot. Wattles are up around the site. No visible emissions or trackout were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-023	Central High School Stockpiling	7/21/2010	New Project
Inspection Details			
Rock construction entrance is in place at site entrance along Philadelphia Street. No active hauling was observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-043	Swander's Addition	7/22/2010	Routine
Inspection Details			
Additional gravel and grading on east side of Biernbaum Lane. No visible emissions or trackout were observed from the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-016	Rapid City 2nd Ward LDS Meeting House	7/22/2010	Completion
Inspection Details			
Site has been reclaimed and grass is established.			
Action	Completion Form		
Followup			
Close permit			

Permit No	Site Name	Inspection Date	Reason
10-AQ-002	Storage Place	7/22/2010	Routine
Inspection Details			
No activity onsite. Some vegetation is starting to grow on the stockpiles. No visible emissions or trackout observed from the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-004	E. St Francis/E. St. Anne & Birch St Reconstruct	7/22/2010	Routine
Inspection Details			
Grading observed on E. Saint Francis Street and working on E. Saint Anne Street. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-012	Saint Andrew Street Reconstruction	7/22/2010	Routine
Inspection Details			
Base layer of pavement down on west end of project area. Actively excavating at the intersection of Maple Avenue and Saint Andrew Street. No visible emissions observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-017	Street Rehabilitation Project Saint Cloud Street	7/22/2010	Routine
Inspection Details			
Grading a portion of the alley north of St. Cloud Street between 5th and 6th Street. Other work in project area. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School Addition	7/23/2010	Complaint
Inspection Details			
Inspected site due to complaint received. Fugitive dust was generated from traffic driving over the dry surface on project area north of Central High School.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Ken Kern of Gustafson Builders regarding the use of additional water on the site to control fugitive dust.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-005	11th Street Alley Sewer Project	7/26/2010	Follow up
Inspection Details			
Patch work on Kansas City Street between 11th Street and West Blvd is complete. Street has been swept.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School Addition	7/26/2010	Follow up
Inspection Details			
Some fugitive dust was observed generated from site grading activities and traffic on site. Temperature in the 90s.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Ken Kern from Gustafson Builders about putting more water on the site and better fugitive dust control.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-006	Dakotah Steak House	7/29/2010	Routine
Inspection Details			
Preparing site for foundation of building. Stockpile on northeast corner of site. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-008	Pizza Ranch	7/29/2010	Routine
Inspection Details			
Actively working on landscaping. Starting to lay sod along Luna Ave.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-010	Gikling & Meier Warehouse	7/29/2010	Routine
Inspection Details			
Grader onsite to level base layer for parking lot. Stockpile of extra material and bobcat on north side of building.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-033	Catron Crossing Subdivision	7/30/2010	Routine
Inspection Details			
Conducted inspection of area after rainfall and observed sediment transport off of the lots into the roads. Appears that seeding and additional stabilization has not taken place. Bendt Drive and the corner of Sourdough Road and Bendt Drive need to be swept.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Chad Lewis regarding the cleanup of sediment in the street. He said he would take care of it.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-036	Park Meadows Subdivision Phase 4	7/30/2010	Routine
Inspection Details			
Inspected site after a storm event. Sediment deposits were observed at the intersection of Smith Avenue and Hoefer Avenue.			
Action	Refer to other City Staff		
Followup			
Stormwater specialist contacted the owner to clean up the material.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School Addition	8/3/2010	Follow up
Inspection Details			
Observed site activity - no visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-002	Storage Place	8/5/2010	Routine
Inspection Details			
Vegetative cover is established on the stockpiles. Storage building in place on southern portion of building site and northern portion appears to be at final grade.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
07-AQ-057	Fairfield Inn & Suites	8/6/2010	Routine
Inspection Details			
No new activity.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-009	Eagle Ridge Apartments	8/6/2010	Routine
Inspection Details			
Additional erosion and sediment controls have been installed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-028	Hilltop Business Park Subdivision	8/6/2010	Routine
Inspection Details			
No activity observed on site. Four hay bales stored on site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-034	Lot 2 Huffman Sub. - On The Border Restaurant	8/6/2010	Routine
Inspection Details			
Vegetation is established on most of the site.			
Action	Follow-up Inspection		
Followup			
Inspect stockpile area for additional growth.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-003	First Evangelical Free Church	8/6/2010	Routine
Inspection Details			
Rock stockpile in place along Parkview Drive for landscaping. No visible emissions from the site were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-026	Reservoir Road & Longview Road	8/6/2010	Routine
Inspection Details			
Working on Reservoir Road. Reservoir Road north of the intersection with Longview Road is gravel. Road recently wet down with some trackout of the gravel at the entrance due to the wetting down. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-031	West River Electric	8/6/2010	Routine
Inspection Details			
Small backhoe excavating along south side of building. Vegetation is established on stockpile and construction entrance is in good shape. No visible emissions or trackout were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-032	Word of Hope Church	8/6/2010	Completion
Inspection Details			
Construction of parking lot and church are complete. Site is stable.			
Action	Completion Form		
Followup			
Close Permit			

Permit No	Site Name	Inspection Date	Reason
09-AQ-035	Murphy Ranch Estates Subdivision	8/6/2010	Routine
Inspection Details			
No new activity observed on site. Vegetation is starting to establish on the site. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-037	Catron Boulevard Sanitary Sewer	8/6/2010	Completion
Inspection Details			
Project area is stable.			
Action	Completion Form		
Followup			
Close permit			

Permit No	Site Name	Inspection Date	Reason
09-AQ-038	Sam's Club	8/6/2010	Routine
Inspection Details			
Actively working on grading parking lot. Observed minor dirt work on east side of construction area with no visible emissions observed from the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-001	Jackson Springs Water Transmission Mains	8/6/2010	Routine
Inspection Details			
No activity observed at the construction site. No visible emissions were observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-003	Outlot 4	8/6/2010	Routine
Inspection Details			
Grass starting to come in on landscaped areas of the lot. Wattles in place to prevent sediment transport from the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-007	Hartland Court Relocation	8/6/2010	Routine
Inspection Details			
Project is complete. Some vegetation is starting to grow in project area.			
Action	None		
Followup			
Inspect for additional growth prior to closing permit.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-010	Gikling & Meier Warehouse	8/6/2010	Routine
Inspection Details			
Pavement is in on the south side of the warehouse. Working on sidewalk installation along Dakota Craft Drive. No visible emissions were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-013	Toyota	8/6/2010	Routine
Inspection Details			
Working on building foundation. A water truck was observed on site. No visible emissions or trackout were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School	8/6/2010	Routine
Inspection Details			
Actively excavating on site. Fugitive dust was observed from vehicle traffic on site traveling over dry haul roads.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Dave D. from Gustafson Builders at approximately 11:30 about the dust. Dave said he would get more water on the site.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-016	Mountain View Apt.	8/6/2010	Routine
Inspection Details			
Working on apartment buildings. No activity or visible emissions were observed on the portion of the project in Rapid City limits.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-018	Eglin Street Extension	8/6/2010	Routine
Inspection Details			
Eglin Street closed to through traffic. Water truck was observed on site. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-019	Land Development	8/6/2010	Routine
Inspection Details			
No major activity since last inspection. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-021	West Chicago Area Water Main Reconstruction	8/6/2010	Routine
Inspection Details			
Actively working on the 3800 block of W. Saint Louis Street. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-022	Knollwood Drainage Outfall	8/6/2010	Routine
Inspection Details			
Silt fences are in place to protect Rapid Creek. Scraper working on southern portion of project area. Construction entrance along Creek Drive is in good shape. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-024	Elks Crossing	8/6/2010	New Project
Inspection Details			
Work starting on project in the northern portion near the intersection with Willowbend Road. Rock construction entrance and erosion and sediment controls are in place. A water truck was observed on site. No visible emissions were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-025	Westhills Village Commons Remodel & Addition	8/6/2010	New Project
Inspection Details			
Work started in the southeastern portion of the project area. A small disturbed area was present at the time of inspection with no visible emissions observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-026	Silver Street Area Utility Improvements	8/6/2010	New Project
Inspection Details			
Silver Street closed for project work. Stockpile of milled asphalt and berms of soil are surrounded by silt fence and stored on the west side of West Blvd N. No visible emissions were observed from the project area at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-027	Hilton Garden Inn	8/6/2010	New Project
Inspection Details			
Scraper working on site. Water source is available on site and filter socks are in place along E. Mall Drive. No visible emissions or trackout from the site were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-033	Catron Crossing Subdivision	8/11/2010	Follow up
Inspection Details			
Active erosion of sediment from the lots into the streets and sediment observed in the streets. Additional reclamation of inactive lots and maintenance of temporary erosion and sediment controls required.			
Action	Send Letter		
Followup			
Sent certified letter on 8/13 requesting compliance with Rapid City Municipal Code and Permit. Sweeping requested within 24 hours. Reclamation and stabilization deadline September 13, 2010.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School Addition	8/11/2010	Follow up
Inspection Details			
Inspected site for fugitive emissions. A water truck was observed on site and haul route in use appeared to be recently wet down.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-029	Elm Avenue Reconstruction- Phase 3	8/13/2010	Routine
Inspection Details			
Landscaping is mostly complete with the exception of a few locations. Filter socks in place in areas without landscaping.			
Action	Follow-up Inspection		
Followup			
Inspect for final landscaping prior to closing permit			

Permit No	Site Name	Inspection Date	Reason
10-AQ-004	E. St. Francis/E. St. Anne & Birch Ave Reconstruct	8/13/2010	Routine
Inspection Details			
Working near intersection of Birch Ave and E. Saint Anne Street. E. Saint Francis Street has been paved. No visible emissions from the project area were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-005	11th Street Alley Sewer Project	8/13/2010	Completion
Inspection Details			
Project is complete. Streets appear to have been recently swept.			
Action	Completion Form		
Followup			
Close Permit			

Permit No	Site Name	Inspection Date	Reason
10-AQ-009	Oak Avenue, Oak Drive & Oakland Drive	8/13/2010	Routine
Inspection Details			
Oak Avenue is closed just past intersection with Indiana Street. Actively excavating along Oakland Street loading into truck. No visible emissions were observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-012	Saint Andrew Street Reconstruction	8/13/2010	Routine
Inspection Details			
A water truck was observed on site. Actively excavating on Saint Andrew Street between Elm and Maple Avenue. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-015	Marlin Storage Units	8/13/2010	Routine
Inspection Details			
Rock Construction entrance has been improved. Observed truck with tarp hauling dirt to the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-017	Street Rehabilitation Project Saint Cloud Street	8/13/2010	Completion
Inspection Details			
Project including landscaping is complete.			
Action	Completion Form		
Followup			
Close Permit			

Permit No	Site Name	Inspection Date	Reason
10-AQ-011	Landfill Gas Collection System	8/19/2010	Routine
Inspection Details			
The installation of the HDPE collection piping and gas wells is complete. Most areas have been covered with mulch and will be seeded this fall. Some additional project work needs to be done in the area by the flare. No visible emissions or trackout from the project area were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
07-AQ-057	Fairfield Inn & Suites	8/20/2010	Routine
Inspection Details			
Vegetation is established over most of the site. A small gravel area exists next to the parking lot.			
Action	Completion Form		
Followup			
Close permit.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-029	Elm Avenue Reconstruction Phase 3	8/20/2010	Completion
Inspection Details			
Landscaping is complete.			
Action	Completion Form		
Followup			
Close Permit			

Permit No	Site Name	Inspection Date	Reason
09-AQ-038	Sam's Club	8/20/2010	Routine
Inspection Details			
Some areas of the parking lot have been paved. Traffic traveling onsite was observed creating fugitive dust emissions.			
Action	Call Contractor/Applicant		
Followup			
Left message for Dan Wilson with Site Works Specialists regarding additional dust control for the site.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-008	Pizza Ranch	8/20/2010	Routine
Inspection Details			
Project is complete. Landscaping around the building appears to be complete and the other disturbed areas have been hydroseeded.			
Action	None		
Followup			
Inspect for growth prior to closing permit.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-008	Pizza Ranch	8/20/2010	Completion
Inspection Details			
Project is complete. All of the landscaping is done and the other disturbed areas have been hydroseeded.			
Action	None		
Followup			
Inspect for growth prior to closing permit.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-015	Marlin Storage Units	8/20/2010	Routine
Inspection Details			
Observed dozer working onsite. A water truck was actively being used to wet down the site. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			