

Inspections for September/October/November 2010

Permit No	Site Name	Inspection Date	Reason
09-AQ-031	West River Electric Association	9/3/2010	Routine
Inspection Details			
Curb and first layer of pavement are down in the parking lot on the south and west sides of the WREA building. No visible emissions or trackout from the site were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-029	Rapid City Landfill Cell #12 Closure	9/3/2010	New Project
Inspection Details			
Clearing has started in the borrow area. Equipment is located onsite. No activity or visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-028	Hill top Business Park Subdivision	9/8/2010	Routine
Inspection Details			
Gravel covers most of the exposed areas on the site. One vegetated stockpile remains onsite. Site is stable to prevent wind erosion.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-038	Sam's Club	9/8/2010	Routine
Inspection Details			
The two entrances off Eglin Street have been paved. Gravel is down on the east side of the Sam's Club building. Active excavation was observed with minimal fugitive emissions observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-006	Dakotah Steak House	9/8/2010	Routine
Inspection Details			
Working on foundation site for building. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-010	Gikling & Meier Warehouse	9/8/2010	Routine
Inspection Details			
Building appears to be complete and the sidewalks are installed. Some of the landscaping is done.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-013	Toyota	9/8/2010	Routine
Inspection Details			
Working on foundation of building. Backhoe also observed working onsite with no visible emissions observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School Addition	9/8/2010	Routine
Inspection Details			
Some of the parking lots have been paved. Actively excavating on the northwest portion of the site. Dirt stockpile located is south of the school. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-018	Eglin Street Extension	9/8/2010	Routine
Inspection Details			
Excavating in project area near East North Street. No visible emissions from the site were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-020	Black Hills - Car Wash	9/8/2010	Routine
Inspection Details			
Working to install floor of car wash. Two stockpiles remain on the site. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-023	Central High School Stockpiling	9/8/2010	Routine
Inspection Details			
Observed truck hauling material onsite. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-026	Silver Street Area Utility Improvements	9/8/2010	Routine
Inspection Details			
Actively working at the intersection of Silver Street and Van Buren Street. Excess material is stored in the staging area along West Blvd N. Silt fence is in place around the material stockpiles. No visible emissions were observed from the project area at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-027	Hilton Garden Inn	9/8/2010	Routine
Inspection Details			
Scrapers observed hauling onsite creating fugitive dust from the dry haul roads.			
Action	Call Contractor/Applicant		
Followup			
Spoke with Zandstra Construction regarding adding more water to the site to control the dust.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-028	Omaha Street Storm Water Quality Project	9/8/2010	New Project
Inspection Details			
Construction entrance off of Omaha Street is in place. Construction started on west end of project area. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspection			

Permit No	Site Name	Inspection Date	Reason
08-AQ-034	Lot 2 Huffman Sub - On The Border Restaurant	10/27/2010	Completion
Inspection Details			
Site appears to be stable to prevent wind erosion. Inspect in the spring for additional growth prior to closing permit.			
Action	None		
Followup			
Inspect in spring			

Permit No	Site Name	Inspection Date	Reason
09-AQ-034	RC Fire Department Fire Station #7	10/27/2010	Completion
Inspection Details			
Site is stable to prevent wind erosion. Inspect for adequate growth in the spring prior to closing permit.			
Action	None		
Followup			
Inspect in spring			

Permit No	Site Name	Inspection Date	Reason
09-AQ-038	Sam's Club	10/27/2010	Routine
Inspection Details			
Appears that most of the parking lot is paved. Some areas have been mulched and some of the landscaping is in. No visible emissions were observed from the site at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-003	Outlot 4	10/27/2010	Completion
Inspection Details			
Site is mostly stabilized. Inspect for additional growth in spring prior to closing permit.			
Action	None		
Followup			
Inspect in spring			

Permit No	Site Name	Inspection Date	Reason
10-AQ-008	Pizza Ranch	10/27/2010	Completion
Inspection Details			
Check for growth on hydroseeded areas in the spring prior to closing permit.			
Action	None		
Followup			
Inspect in spring			

Permit No	Site Name	Inspection Date	Reason
10-AQ-010	Gikling & Meier Warehouse	10/27/2010	Routine
Inspection Details			
Work on site is complete and site appears to have been seeded. Inspect for growth in spring.			
Action	None		
Followup			
Inspect for growth in spring			

Permit No	Site Name	Inspection Date	Reason
10-AQ-013	Toyota	10/27/2010	Routine
Inspection Details			
Working on foundation of building, some base material for the parking lot is down. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School Addition	10/27/2010	Routine
Inspection Details			
The storm water treatment ponds have been seeded. Actively working in the area of the addition on the south side of the school. Inspected site during a period of high winds with gusts up to 60 mph and observed minimal visible emissions.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-018	Eglin Street Extension	10/27/2010	Completion
Inspection Details			
Project is complete. The disturbed areas have been seeded and mulched. Inspect for growth in spring prior to closing permit.			
Action	None		
Followup			
Inspect in spring			

Permit No	Site Name	Inspection Date	Reason
10-AQ-020	Black Hills - Car Wash	10/27/2010	Routine
Inspection Details			
Building structure is up and curbs for the paved area are in place. Actively hauling base material for the pavement to the site. A water truck was on site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-023	Central High School Stockpiling	10/27/2010	Routine
Inspection Details			
Entrance to the site is currently blocked off to restrict access. No active hauling was observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-027	Hilton Garden Inn	10/27/2010	Routine
Inspection Details			
Actively working on the north side of the project site. A water truck was working on site to minimize the emissions due to the windy conditions.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-032	Rainbow Ridge Water Main Ext.	10/27/2010	New Project
Inspection Details			
Mass grading of the site has started. No active work was observed at the time of inspection. Minimal visible emissions were observed at the time of inspection with the 60 mph wind gusts.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-024	Tish Blvd Extension	10/28/2010	Completion
Inspection Details			
Vegetation has been established over most of the site. Inspect for additional growth in the spring prior to closing permit.			
Action	None		
Followup			
Inspect in spring			

Permit No	Site Name	Inspection Date	Reason
10-AQ-026	Silver Street Area Utility Improvements	10/28/2010	Routine
Inspection Details			
Actively working along Silver Street with staging area located along West Blvd N. Some visible emissions were observed during the high wind gusts up to 60 mph.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-003	First Evangelical Free Church	10/29/2010	Completion
Inspection Details			
Site has been hydroseeded and the landscaping rock along Parkview is in place.			
Action	None		
Followup			
Inspect for growth in spring prior to closing permit.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-026	Reservoir Road & Longview Road	10/29/2010	Routine
Inspection Details			
Reservoir Road paving is complete. Actively working in staging area and on driveway and sidewalk placement. A crew was observed cutting the pavement with a wet saw and no visible emissions were observed. ROW along Longview Road has been seeded.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-031	West River Electric	10/29/2010	Routine
Inspection Details			
Paving of the site appears to be complete. The remaining disturbed areas have been hydroseeded. Irrigation is set up for the seeded portion along Twilight Drive.			
Action	None		
Followup			
Inspect for vegetation growth in spring prior to closing permit.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-033	Catron Crossing Subdivision	10/29/2010	Follow up
Inspection Details			
Work as requested by letter has not been complete. Erosions and sediment control maintenance and permanent reclamation has not been done.			
Action	Call Contractor/Applicant		
Followup			
Left message for Chad Lewis 11/3			

Permit No	Site Name	Inspection Date	Reason
09-AQ-035	Murphy Ranch Estates Subdivision	10/29/2010	Follow up
Inspection Details			
Vegetation is starting to establish in most areas on the site.			
Action	None		
Followup			
Inspect for additional growth in spring.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-002	Storage Place	10/29/2010	Routine
Inspection Details			
No additional work appears to have been completed.			
Action	None		
Followup			
Inspect for additional vegetative cover in spring.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-006	Dakotah Steak House	10/29/2010	Routine
Inspection Details			
A portion of the north parking lot on the site has been paved. Actively working on the building foundation. No visible emissions or trackout from the site were observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-015	Marlin Storage Units	10/29/2010	Routine
Inspection Details			
Foundations for the storage units have been poured and the retaining walls have been constructed. Observed active excavation with a water truck on site. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-016	Mountain View Apt.	10/29/2010	Routine
Inspection Details			
No active work or visible emissions were observed in the portion of the project in the Rapid City Limits.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-019	Land Development	10/29/2010	Routine
Inspection Details			
Gravel entrance off of Elk Vale Road has been constructed and pond excavation has begun. Silt fence is up at the site. No active work was observed at the time of inspection. No visible emissions or trackout were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-024	Elks Crossing	10/29/2010	Routine
Inspection Details			
Observed active excavation and hauling on site with some visible emissions that appeared to be within the permit limits observed. No visible emissions were observed traveling off of the construction site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-028	Omaha Street Storm Water Quality Project	10/29/2010	Routine
Inspection Details			
Actively working in the storm water quality area 'B'. Trackout control device is in place. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-029	Rapid City Landfill Cell #12 Closure	10/29/2010	Routine
Inspection Details			
Actively excavating in the borrow area with no fugitive emissions observed.			
Action	None		
Followup			
Continue regular inspections.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-030	Eagle Ridge Apartments Phase 2	10/29/2010	New Project
Inspection Details			
Construction has not started on site. Appears to be no change.			
Action	None		
Followup			
Conduct inspection when construction starts - BP application submitted week of 11/1			

Permit No	Site Name	Inspection Date	Reason
08-AQ-043	Swander's Addition	11/8/2010	Routine
Inspection Details			
Building permit for additional storage units issued. Working on the construction of the additional storage units. No visible emissions or trackout from the site were observed.			
Action	None		
Followup			
Inspect site in spring for permit closure			

Permit No	Site Name	Inspection Date	Reason
09-AQ-036	Park Meadow Subdivision - Phase 4	11/8/2010	Routine
Inspection Details			
Working on paving road on north side of Smith Avenue. The base material is down and appears to have been recently watered. No visible emissions were observed from the site.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-004	E. St. Francis,E. St. Anne & Birch Ave Reconstruct	11/8/2010	Routine
Inspection Details			
Project is complete including all reclamation.			
Action	Completion Form		
Followup			
Close permit			

Permit No	Site Name	Inspection Date	Reason
10-AQ-009	Oak Avenue, Oak Drive and Oakland Drive	11/8/2010	Routine
Inspection Details			
Paving for the project appears to be complete. Actively working in the area of Oakland Street. Oak Drive and Oak Avenue are complete and the landscaping is also complete.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-012	Saint Andrew Street Reconstruction	11/8/2010	Completion
Inspection Details			
Project is complete. Areas along Saint Andrew Street have been reclaimed. The staging area to the east of Elm Avenue has been hydroseeded.			
Action	None		
Followup			
Inspect for vegetation establishment in staging area in the spring.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-022	Knollwood Drainage Outfall	11/8/2010	Routine
Inspection Details			
Actively working on the project north of Centre Street. Most of the project area south of Centre Street has been seeded and mulched. Turf reinforcement mats are in place along the drainage channel.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-025	Westhills Village Commons Remodel & Addition	11/8/2010	Routine
Inspection Details			
Small stockpile of gravel is present northwest of the Centennial Street cul-de-sac. Erosion control wattles are in place with snow fence around the project area. No visible emissions were observed from the project area at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-021	West Chicago Area Water Main Reconstruction	11/9/2010	Routine
Inspection Details			
Project appears to be mostly complete. The disturbed areas have been seeded or sod has been put down.			
Action	None		
Followup			
Inspect the seeded area along West Omaha Street for growth in spring prior to closing permit.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-001	Jackson Springs Water Transmission Mains	11/10/2010	Routine
Inspection Details			
Beach Drive has been paved. The parking lot at Canyon Lake is partially tore up with a portion of the lot unpaved. Equipment and materials are staged on the west side of the fish hatchery lot.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-031	Downtown Street Reconstruction - Sixth Street	11/10/2010	Routine
Inspection Details			
Working on the underground utilities on Sixth Street between Main Street and Omaha Street. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-033	Cliff Drive Sanitary Sewer Extension	11/10/2010	Routine
Inspection Details			
Falls Drive is closed to through traffic from the intersection of Red Road Drive. Grader working on Cliff Drive south of the intersection with Farview Drive. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
08-AQ-028	Hilltop Business Park Subdivision	11/19/2010	Routine
Inspection Details			
Topsoil stockpile has been spread out over the lot.			
Action	None		
Followup			
Conduct a follow-up inspection for reclamation of the area			

Permit No	Site Name	Inspection Date	Reason
08-AQ-044	Hanson-Larson Memorial Park	11/19/2010	Completion
Inspection Details			
No work was observed at the time of inspection. Appears that project is complete.			
Action	Call Contractor/Applicant		
Followup			
Permit is expired. Spoke with Jeff Denison on 11/24 and the permitted portion of the project is complete. There may be some additional work in the future and if the disturbance is over an acre a new permit will be obtained. Close Permit.			

Permit No	Site Name	Inspection Date	Reason
09-AQ-026	Reservoir Road and Longview Road	11/19/2010	Routine
Inspection Details			
Large stockpile of material is located in the staging area. Portions of the sidewalk along Reservoir Road need to be completed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
09-AQ-038	Sam's Club	11/19/2010	Routine
Inspection Details			
All disturbed areas of the project are seeded and mulched or have sod. Site is stable.			
Action	None		
Followup			
Inspect for growth in spring prior to closing			

Permit No	Site Name	Inspection Date	Reason
10-AQ-006	Dakotah Steak House	11/19/2010	Routine
Inspection Details			
Working on the construction of the steak house. Backhoe observed excavating material on site. No visible emissions or trackout from the site were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-013	Toyota	11/19/2010	Routine
Inspection Details			
Active building construction and preparation of the parking lot. No visible emissions or trackout onto Eglin Street observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-014	Central High School Addition	11/19/2010	Routine
Inspection Details			
Working on construction of the addition. Stockpiles of dirt are stored on site. Construction entrance along Mt. Rushmore Road is in good condition and no visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-015	Marlin Storage Units	11/19/2010	Routine
Inspection Details			
Working on storage unit foundations. Some paving is complete and actively working on preparing other areas for pavement. No visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-016	Mountain View Apt.	11/19/2010	Routine
Inspection Details			
No work in the portion of the project in the Rapid City limits was observed.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-019	Land Development	11/19/2010	Routine
Inspection Details			
Additional excavation of the pond has been done since last inspection. Active work was not observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-020	Black Hills - Car Wash	11/19/2010	Routine
Inspection Details			
Parking lot is paved and building appears to be mostly complete. Reclamation and landscaping still need to be done.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-023	Central High School Stockpiling	11/19/2010	Routine
Inspection Details			
The entrance to the site is blocked off. No recent hauling appears to have taken place.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-024	Elks Crossing	11/19/2010	Routine
Inspection Details			
Paving of the road appears to be complete. Recent work on the sidewalk ramps. Erosion and sediment controls are in place and reclamation still needs to be done.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-027	Hilton Garden Inn	11/19/2010	Routine
Inspection Details			
Working on construction of building. Rock trackout control entrance is in good shape.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-028	Omaha Street Storm Water Quality Project	11/19/2010	Routine
Inspection Details			
No activity observed on site. Appear to be replacing a small portion of the sidewalk where traffic to the site crossed. Silt fence is up along Rapid Creek.			
Action	None		
Followup			
Continue regular inspections.			

Permit No	Site Name	Inspection Date	Reason
10-AQ-029	Rapid City Landfill Cell #12 Closure	11/19/2010	Routine
Inspection Details			
A backhoe was observed loading a truck in the borrow area. The material was wet so no visible emissions were observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			

Permit No	Site Name	Inspection Date	Reason
10-AQ-032	Rainbow Ridge Water Main Ext.	11/19/2010	Routine
Inspection Details			
Semi observed traveling on site to unload material, no other work observed. No visible emissions or trackout was observed at the time of inspection.			
Action	None		
Followup			
Continue regular inspections			