STAFF REPORT

March 8, 2001

No. 01UR006 - Use on Review to allow a caretakers residence in ITEM 20 the Light Industrial Zoning District

GENERAL INFORMATION:

PETITIONER	Samuel J. and Faye E. Bice
REQUEST	No. 01UR006 - Use on Review to allow a caretakers residence in the Light Industrial Zoning District
LEGAL DESCRIPTION	Lot 2 of Lot K of Bice Subdivision located in the NW1/4 of the SW1/4 of Section 5, T1N, R8E, BHM, Rapid City, Pennington County, South Dakota
PARCEL ACREAGE	Approximately 4.262 Acres
LOCATION	1220 1/2 Creek Drive
EXISTING ZONING	Light Industrial District
SURROUNDING ZONING North: South: East: West:	Light Industrial District Flood Hazard District Flood Hazard District General Agriculture District
PUBLIC UTILITIES	Well and septic system
REPORT BY	Lisa Seaman

- <u>RECOMMENDATION</u>: Staff recommends that the Use on Review to allow a caretakers residence in the Light Industrial Zoning District be continued to the April 5, 2001 Planning Commission meeting to allow the applicant time to submit additional required information.
- <u>GENERAL COMMENTS</u>: A 3480 square foot building containing offices and a shop is currently located on this property. Mastel Precision Surgical Instruments Inc. is currently leasing this building and utilizing the shop to construct display structures. A recent fire destroyed the 25 foot by 100 foot caretaker's residence that has been located on this property since July, 1972. The applicant has indicated that vandalism has been an on going problem in this area and that the caretaker's residence provides security for the property. The applicant wishes to locate a new 25 foot by 100 foot mobile home on the property and is requesting Use on Review approval to allow a caretaker's residence in the Light Industrial Zoning District.
- <u>STAFF REVIEW</u>: Staff has reviewed the Use on Review request and identified the following major issues:

Fire Safety: The Fire Department reviewed this request and has noted that the applicant

STAFF REPORT

March 8, 2001

No. 01UR006 - Use on Review to allow a caretakers residence in ITEM 20 the Light Industrial Zoning District

must provide information regarding hydrant locations, access and circulation to the residence as well as the shop and office.

Flood Hazard Zone: The site plan submitted by the applicant shows that the proposed existing caretakers residence will be partially located within the Rapid Creek hydraulic floodway. The Rapid City Municipal Code identifies the floodway as an extremely hazardous area and "prohibits encroachments, including fill, new construction, substantial improvements and other development unless a technical evaluation by a professional engineer demonstrates that encroachments shall not result in any increase in flood levels during the occurrence of the base flood discharge". Therefore the Engineering Division has requested that the applicant provide a detailed topographic map showing the exact location of the floodway boundary and the proposed and existing improvements. The proposed location must be outside of the hydraulic floodway.

Parking and access: The applicants site plan identified a graveled driveway that serves as access for the caretaker's residence as well as the shop and office located on the subject property. The Parking Ordinance requires that when a building is erected and in excess of twenty percent of the gross square footage of the existing structures parking must be provided for all buildings and that access and parking facilities must be paved to city minimum construction standards. The caretaker's residence will require two parking spaces and the Planning Division is requesting that the applicant provide a detailed floor plan of the existing shop and office building to determine the number of parking spaces required for that structure.

As of this writing, the receipts from the certified mailings have not been returned and the Use on Review sign has not been posted on the property. No inquiries have been received regarding this proposal.