STRUCTURAL SITE LAYOUT 10SV003 LOTS 1 AND 2 OF MONTE VISTA SUBDIVISION, (formerly Lot 9 and N25' of Lot 10 of Block 3 of Lot 3 of NE1/4 of the NW1/4 Section 9, T1N, R7E) LOCATED IN THE NE1/4 OF THE NW1/4. SECTION 9, T1N, R7E, BHM RAPID CITY, PENNINGTON COUNTY, SOUTH DAKOTA LOT 8 LS 2652 LOI OF THE NW1/4 NE1/4 PORTION TO BE DEDICATED TO PUBLIC RIGHT-OF-WAY S00'13'19"E 120.00 (R&M) 0.024 Ac.± 24.0 S89'52'27"W 150.04" (M) 150.00 (R) 33.0'± 58.7 0.120 Ac.± LOT 28 ۵ 20.0 PREVIOUS LOT LIN 0 LOT 2 R 0.114 Ac.± 33.0 z 136.02 0 LOT 27 150.02' (M) 150.00' 3 S25' OF LOT 10 LOT 25 PROFESSIONA 9213 ERIC D HOWAR *3 LOT 11 MARCH 15, 2010 Renner & Associates, LLC. SCALE 616 Sixth St. * Rapid City, SD 57701 * 605/721-7310 FAX: 605/721-7313 * E-MAIL: Gary@RennerAssoc.com * Spearfish 605/717-0016 * CITY HALL 1903

PMM