

**From:** Trevor Schmidt <[blackhillsexteriors@gmail.com](mailto:blackhillsexteriors@gmail.com)>

**Date:** August 26, 2014 at 10:09:05 PM MDT

**To:** [rana.1978@hotmail.co.uk](mailto:rana.1978@hotmail.co.uk)

**Subject:** Roof Leak

Rana,

I have inspected your roof on 8/26/14 at your Mandalay Ln address in Rapid City due to the leak you have found in your garage. I could not tell exactly where your leaking from. There was no visible damage on rooftop to guarantee a specific location or error. I did notice that some shingles are not sealed and it would be possible for a leaky roof. If you had high winds and heavy rain the shingles would be able to lift high enough for wind driven rain to get behind the shingle and cause a leak. That is one possible way but would have to inspect when heavy rain and wind is available or wait until the leak is in progress.

Thank you,

Trevor A. Schmidt  
Project Manager

**Black Hills Exteriors**  
260 Bengal Drive  
Rapid City, SD 57701  
**605.593.3358**

[BlackHillsExteriors@gmail.com](mailto:BlackHillsExteriors@gmail.com)