

Mitchell Sharlene

From: Fred Thurston [fthursto@rushmore.com]
Sent: Friday, January 30, 2009 3:39 PM
To: Mitchell Sharlene
Subject: pictures of Motor service
Attachments: IMG_0446.JPG; IMG_0457.JPG; IMG_0448.JPG

Sharleen

There are problems with the bricks on the west portion of the building with spalling faces and moisture damage on the west side north end. The enclosed pictures hopes to show the damage to be repaired. There are three color of bricks to be used.

There will be a major renovation of the Sweeney House and I want to discuss the process. It is to be renovated back to it's original magnificence and we will be putting an addition onto the back of it.

Fred Thurston