SOUTH DAKOTA HISTORIC SITES INVENTORY	Site Number
Historic Name	PN RC RC WB 255
Address/ 1016 12 TH ST.	CTY TWP CIT NBH NUM DBASE ————————————————————————————————————
Common Name	U.S.G.S. Quad Map Name
Historic Function ————————————————————————————————————	Legal Description
Historic Context(s)	
Owner's	Only ADD
Owner's Address ———————————————————————————————————	
Owner's Phone #	Date — NR Eligible Yes — No —
Date(s) of ———————————————————————————————————	
Photographer —————	——— □ _{HIST} □ _{ARCH} □ _{ARCE}
Roll # — Frame #'s — (Attach Photographs Below)	DNATL STAT LOCL

SOUTH DAKOTA HISTORIC SITES INVENTORY

Historic

Name Charles & Elsie Sisk House

Address/

Location 1016 12th Street

 ${\tt Common}$

Name

Historic

Function House

Historic

Context(s) V. Depression & Rebuilding: A.

Changing Urban Patterns: 3.

Residential Changes

Owner's Name Dean Steinberg

Owner's Address 1016 12th Street

Rapid City, SD 57701

Owner's Phone # (605) 342-8492

Date(s) of Construction 1923

Photographer L. Johnson

Roll # 1; 2 Frame #'s 33-34; 10,20-21

(Attach Photographs Below)

Site Number

PN- RC -RC -WB-00255

CTY TWP CIT NBH NUM

DBASE 0000000000

U.S.G.S. Quad Map Name

Legal Description

0

Q1 Q2 SEC TWP RNG

Urban Only BLK 21

LOT 26-27

ADD Boulevard

Surveyors

L. Johnson/RTI

Date 07/16/1991

NR Eliqible Y

Future NR Y

Significance HIST, ARCH,

LOCL









Preservation Strengths of the Site

In Use and Not Threatened

X In Good Structural Condition
Owners Protecting Site
Appreciated by Public

X Valuable to Research

Preservation Threats of the Site

Abandonment

Deterioration Through Lack of Resources

Vandalism or Looting

Inappropriate Alterations

Inappropriate or Poor Maintenance

Fragile or Deteriorating Construction Materials

Unsound Condition

Lack of Support (Specify by Whom)

Environmental Situations Effecting Site (Specify What: May Include Mining, Flooding, Erosion, Pollution, Acid Rain, Weather, Isolation, Development, Etc.)

Site No. PN-RC -RC-WB-00255

Dates:

Founding of Institution or Settlement 1876

Town and Addition Platted 1877 1885 Initial Construction of Structure 1923

Original Owners:

Name (Include Spouse if Known) Charles & Elsie Sisk Place of Origin Date Arrived in S.D. 0000 In USA 0000

Occupation(s) Charles: building contractor

Religious Affiliation Social/Fraternal Affiliation

Other Previous Owners: Names and Dates of Occupation

Structural History:
Architect's Name and
Date of Commission

Builder's Name Charles Sisk Pattern, Book and Number/Name

Historic Uses of the Site House

Changes in Use

Statement of Historical Significance: (Including Relation to Historic Context Topics and Study Units)

This property has the potential to contribute to the West Boulevard Historic District. It is significant for its association with the growth of and development of the West Boulevard neighborhood in Rapid City from 1878 to 1942. Built in 1923, the house corresponds with the rebuilding phase of residential development in Rapid City (1898 to 1929), a period in which the West Boulevard neighborhood rapidly grew in response to tremendous population growth in the city. The property illustrates the varied economic status of the neighborhood's inhabitants during this period and serves as a representative example of residential architecture popular at the time.

Site No. PN-RC -RC-WB-00255

Miscellaneous Historical Information:

This house was built in 1923 by Charles Sisk, a building contractor who constructed several other homes in Rapid City in the 1920s. Sisk and his family occupied the house for several years, at least until WWII.

Bibliography:

Oral Interview (Name, Date & Relationship to Site)
Viola Sisk; 7-19-91; Charles Sisks' daughter-in-law and current
property owner at WB-224

Atlas (Date & Publisher)

County History (Title & Pages)

Deed Abstract

Tax Records Assessors' Card: 1923

Sanborn-Ferris Maps (Dates) 1923 (first map of area)

Census Records

Historical Photos (Description & Date)

Manuscripts (Name & Date)

Directories (Type & Date) R.L. Polk: 1928, 1930-31

Other Sources Rapid City Public Works, Water Permit #1350: C. Sisk, 1923

ARCHITECTURAL EVALUATION/PRINCIPAL STRUCTURE

General Information:

Building # 1

Site No. PN-RC -RC-WB-00255 Date of Construction 1923

Photos 33

Function House

Plan Form Square

Height (Stories) 1.5

Method of

Overall

Style Craftsman Bungalow

Construction Wood-frame

Condition E

Additions & Alterations (Types & Dates)

New deck on rear

Evaluation of Specific Elements:

Foundation: Materials Concrete

Condition E Condition E

Walls: Cladding 4" Clapboard

Windows: General/ Type

Glazing

Condition Location

Unique

Pattern

Double-hung, wood-sash 1/1 E

Doors: Type Glazing Pattern Condition Location

Condition E

Craftsman

Vertical lights

E West

Roof: Form Gable

Materials Asphalt shingles

Condition E

Dormer: Type Shed

Location(s) West

Chimneys/Ventilators: Materials Brick chimney

Condition E

Location(s) Interior: off ridge

Porches: Materials

Condition Height Roof Location

(Stories) Configuration

Enclosed: clapboard & windows

E

1 Front gable

West

Bays/Towers: Form

Condition

Height(Stories) Location(s)

ARCHITECTURAL EVALUATION/PRINCIPAL STRUCTURE

Site No. PN-RC -RC-WB-00255 Building #

Significant Exterior Details:

Cladding: wood shingles on gable ends & dormers

Knee braces in gables

Significant Interior Details:

Interior not accessed

ARCHITECTURAL EVALUATION/ANCILLARY STRUCTURES Site No. PN-RC -RC-WB-00255 Bldg# Date C/NC Function Photo# Construction Method Height 21 c.1990 NC Garage Wood-frame 1 Individual Element Cond. Overall Condition E Foundation: Materials - Concrete Walls: Cladding- Shiplap E Windows: Type & Glazing Pattern-Doors: Type & Glazing Pattern- Fiberglass overhead Ε Roof: Form & Materials - Low gable; rolled roofing Chimney/Vent: Material & Location-

Significant Exterior Details

Significant Interior Details Not accessed

Alterations & Dates

Change in Use

Site Plan: Indicate all door and window openings, roof shapes, and landscape features. Indicate North O