SOUTH DAKOTA HISTORIC SITES INVENTORY	Site Number
Historic Name	PN RC RC WB 281 CTY TWP CIT: NBH NUM
Address/ 1123 FULTON ST.	DBASE ————
Common Name —	U.S.G.S. Quad Map Name
Historic Function ————————————————————————————————————	Legal Description
Historic Context(s)	Q1 Q2 SEC TWP RNG
Owner's Name	Urban LOT BLK BLK
Owner's Address	Surveyors
Owner's Phone #	Date ————————————————————————————————————
Date(s) of ———————————————————————————————————	Significance
Photographer	□ _{HIST} □ _{ARCH} □ _{ARCE}
Roll # — Frame #'s — (Attach Photographs Below)	□ _{NATL} □ _{STAT} □ _{LOCL}

SOUTH DAKOTA HISTORIC SITES INVENTORY

Historic

Name The James Clark House

Address/

1123 Fulton Street Location

Common ' Name

Historic

Function House

Historic

V. Depression & Rebuilding: A. Context(s) Changing Urban Patterns: 3.

Residential Changes

Owner's Name John & Patricia Hill

c/o Patricia Damon Owner's Address

1123 Fulton Street

Rapid City, SD 57701

Owner's Phone # (605) 342-4988

Date(s) of Construction Circa 1909

Photographer L. Johnson

Frame #'s 12-16 Roll # 1

(Attach Photographs Below)





Site Number PN- RC -RC -WB-00281 CTY TWP CIT NBH NUM

DBASE 0000000000

U.S.G.S. Quad Map Name

Legal Description Q1 Q2 SEC TWP RNG Urban Only BLK 29 LOT 19-21 ADD Boulevard

Surveyors L. Johnson/RTI

Date 07/17/1991

NR Eligible Y

Future NR Y

Significance HIST, ARCH,

LOCL

PLANNING

Preservation Strengths of the Site

In Use and Not Threatened

- X In Good Structural Condition Owners Protecting Site Appreciated by Public
- · X Valuable to Research

Preservation Threats of the Site

Abandonment

Deterioration Through Lack of Resources

Vandalism or Looting

Inappropriate Alterations

Inappropriate or Poor Maintenance

Fragile or Deteriorating Construction Materials

Unsound Condition

Lack of Support (Specify by Whom)

Environmental Situations Effecting Site (Specify What: May Include Mining, Flooding, Erosion, Pollution, Acid Rain, Weather, Isolation, Development, Etc.)

HISTORY AND CONTEXT

Site No. PN-RC -RC-WB-00281

Dates:

Founding of Institution or Settlement 1876
Town and Addition Platted 1877 1885 Initial Construction of Structure 1909

Original Owners:

Name (Include Spouse if Known) James Clark Place of Origin Date Arrived in S.D. 0000 In USA 0000

Occupation(s)

Religious Affiliation Social/Fraternal Affiliation

Other Previous Owners:

Names and Dates of Occupation John & Daisy Newcomer (R.L. Polk: 1928-31; John listed as traveling salesman)

Structural History:
Architect's Name and
Date of Commission

Builder's Name Pattern, Book and Number/Name

Historic Uses of the Site House

Changes in Use

Statement of Historical Significance: (Including Relation to Historic Context Topics and Study Units)

This property has the potential to contribute to the West Boulevard Historic District. It is significant for its association with the growth of and development of the West Boulevard neighborhood in Rapid City from 1878 to 1942. Built circa 1909, the house corresponds with the rebuilding phase of residential development in Rapid City (1898 to 1929), a period in which the West Boulevard neighborhood rapidly grew in response to tremendous population growth in the city. The property illustrates the varied economic status of the neighborhood's inhabitants during this period and serves as a representative example of residential architecture popular at the time.

Site No. PN-RC -RC-WB-00281

Miscellaneous Historical Information:

This house was presumably built in 1909, around the time that James Clark received a water permit for the property. According to the current property owners, "Big Hat" Clark built the house as his home. They also report that it is of log construction.

Bibliography:

Oral Interview (Name, Date & Relationship to Site)
John & Patricia Hill, 7-17-91, current occupants

Atlas (Date & Publisher)

County History (Title & Pages)

Deed Abstract

Tax Records Assessors' Card: 1915

Sanborn-Ferris Maps (Dates)
1923 (first map of area)

Census Records

Historical Photos (Description & Date)

Manuscripts (Name & Date)

Directories (Type & Date) R.L. Polk: 1928, 1930-31

Other Sources Rapid City Public Works, Water Permit #575: J. Clark, 1909

ARCHITECTURAL EVALUATION/PRINCIPAL STRUCTURE Page 1 General Information: Building # 1 Site No. PN-RC -RC-WB-00281 Date of Construction c.1909 Photos 16 Function House Plan Form Rectangular Height (Stories) 2 Method of Overal1 Style Neo-Colonial Revival Construction Log Condition E Additions & Alterations (Types & Dates) Evaluation of Specific Elements: Foundation: Materials Sandstone; coursed Condition G Walls: Cladding 8" Clapboard Condition E Windows: General/ Type Glazing Condition Location Unique Pattern Double-hung, wood-sash G 6/6 Ū Double-hung, wood-sash 4/4G North; Bay U Fixed, wood-sash Full light; storms E North Doors: Type Glazing Pattern Condition Location Oak 3/4 light; beveled E North Roof: Form Gable Materials Asphalt shingles Condition E Dormer: Type Condition Location(s) Chimneys/Ventilators: Materials Two brick chimneys Condition E Location(s) Interior: east & west ridge

Condition Height

Ε

Condition

Ε

Roof

(Stories) Configuration

Height(Stories)

Gable

Location

North

Porch

Location(s)

Porches: Materials

Bays/Towers: Form

Open: full-length, round columns

Hexagonal bay

ARCHITECTURAL EVALUATION/PRINCIPAL STRUCTURE
Site No. PN-RC -RC-WB-00281 Building # 1

Significant Exterior Details:

Foundation sandstone is ashlar-faced

Porch has lattice skirt

Window shutters have decorative arrow motif

Significant Interior Details:

Interior not accessed

ARCHITECTURAL EVALUATION/ANCILLARY	STRUCTURES	Site No. PN-RC -RC-WI	3-00281
Bldg# Date C/NC Function 2 c.1935 C Garage	Photo# 12	Construction Method Wood-frame	Height 1
Overall Condition G Foundation: Materials - Concrete Walls: Cladding - Shiplap Windows: Type & Glazing Pattern			
Doors: Type & Glazing	Pattern- (2 aterials- G	2) Overhead; vertical board able; wood shingles	G G

Significant Exterior Details Galvanized ridge with balls

Significant Interior Details Not accessed

Alterations & Dates

Change in Use

Site Plan: Indicate all door and window openings, roof shapes, and landscape features. Indicate FULTION ST. North ALLEY

PLANNING	Site No. —
December of the City	
Preservation Strengths of the Site	• • • • •
In Use and Not Threatened.	
———— In Good Structural Condition	•
Owners Protecting Site	
Appreciated by Public	
Valuable to Research	
Preservation Threats	w.
Abandonment	
Deterioration Through Lack of Resources	
Vandalism or Looting	•
———— Inappropriate Alterations	
Inappropriate or Poor Maintenance	Sump.
Fragile or Deteriorating Construction Materials	
Unsound Condition	
<pre>Lack of Support (Specify by Whom)</pre>	
	Y
	u
Environmental Situations Effecting Site (Specify V Flooding, Erosion, Pollution, Acid Rain, Weather,	Isolation, Development, Ect.)
Establish Commencer of the Commencer of	