



Site Map

Railing Scope

The work to be accomplished at the east stair is intended to closely match what was completed at the west stair 5-7 years ago. Due to egress of elementary children, open railings are being in filled to prevent children or so “a 4-inch diameter sphere cannot pass through any opening” to meet current Uniform Building Code.