SOUTH DAKOTA HISTORIC SITES INVENTORY	Site Number
Historic Name ————————————————————————————————————	PN RC RC WB 153 CTY TWP CIT NBH NUM
Address/ 1021 ST. JOSEPH ST.	DBASE —————
Common Name ————————————————————————————————————	U.S.G.S. Quad Map Name
Historic Function	Legal Description
Historic Context(s)	Q1 Q2 SEC TWP RNG
Owner's Name	Urban LOT
Owner's Address	Surveyors
Owner's Phone #	Date ————————————————————————————————————
Date(s) of Construction	Significance
Roll # — Frame #'s — (Attach Photographs Below)	□HIST □ARCH □ARCE □NATL □STAT □LOCL

## SOUTH DAKOTA HISTORIC SITES INVENTORY

Historic Name

Address/
Location 1021 St. Joseph Street

Common Name

Historic Function House

Historic
Context(s) VI. The Great Depression

Owner's Name Lavern L. & Leona M. Anthony
Owner's Address 309 N. Berry Pine Road
Rapid City, SD 57702

Owner's Phone # (605) 343-0263

Date(s) of Construction Circa 1930

Photographer L. Johnson
Roll # 10 Frame #'s 31-32,34-35
(Attach Photographs Below)







Site Number
PN- RC -RC -WB-00153
CTY TWP CIT NBH NUM

DBASE 0000000000

U.S.G.S. Quad Map Name

Legal Description

0
Q1 Q2 SEC TWP RNG
Urban Only BLK 3
LOT 19-20
ADD Boulevard

Surveyors
L. Johnson/RTI

Date 07/13/1991
NR Eligible Y
Future NR Y

Significance HIST, ARCH, LOCL

## Preservation Strengths of the Site

In Use and Not Threatened

- X In Good Structural Condition
  Owners Protecting Site
  Appreciated by Public
- X Valuable to Research

## Preservation Threats of the Site

Abandonment

Deterioration Through Lack of Resources

Vandalism or Looting

Inappropriate Alterations

Inappropriate or Poor Maintenance

Fragile or Deteriorating Construction Materials

Unsound Condition

Lack of Support (Specify by Whom)

Environmental Situations Effecting Site (Specify What: May Include Mining, Flooding, Erosion, Pollution, Acid Rain, Weather, Isolation, Development, Etc.)

Dates:

Founding of Institution or Settlement 1876
Town and Addition Platted 1877 1885 Initial Construction of Structure 1930

Original Owners:

Name (Include Spouse if Known)
Place of Origin
Date Arrived in S.D. 0000 In USA 0000

Occupation(s)

Religious Affiliation Social/Fraternal Affiliation

Other Previous Owners:

Names and Dates of Occupation B2: Earl & Teresa Berman (R.L. Polk: 1928; Earl listed as conductor C & NW Railway)

B2: Albert & Josephine Stahoski (R.L. Polk: 1930-31; Albert listed as President of Black Hills Hy-Vis

Structural History:
Architect's Name and
Date of Commission

Builder's Name Pattern, Book and Number/Name

Historic Uses of the Site House

Changes in Use

Statement of Historical Significance: (Including Relation to Historic Context Topics and Study Units)

This property has the potential to contribute to the West Boulevard Historic District. It is significant for its association with the development of the West Boulevard neighborhood in Rapid City from 1878 to 1942. Constructed circa 1930, the primary house (B1) corresponds with the Great Depression (1930-1942). During this era of economic uncertainty, Rapid City experienced limited economic growth that created a demand for residential construction in the West Boulevard neighborhood, although on a much smaller scale then in previous decades. The property illustrates the varied economic status of the neighborhood's inhabitants during this period and serves as a representative example of residential architecture popular at the time.

Miscellaneous Historical Information:

The alley house (B2) was built about 1920, around the time water permit #941-942 was issued for the property. The main house was presumably constructed about 1930, the year-built date provided in tax records.

Bibliography:

Oral Interview (Name, Date & Relationship to Site)

Atlas (Date & Publisher)

County History (Title & Pages)

Deed Abstract

Tax Records Assessors' Card: 1930

Sanborn-Ferris Maps (Dates)
1923 & 1930: show alley house (B2) only

.Census Records

Historical Photos (Description & Date)

Manuscripts (Name & Date)

Directories (Type & Date) R.L. Polk: 1928, 1930-31

Other Sources

Rapid City Public Works, Water Permit #941-942 [ca. 1920]: indexed but not available

ARCHITECTURAL EVALUATION/PRINCIPAL STRUCTURE

Page 1

General Information:

Building #

Site No. PN-RC -RC-WB-00153 Date of Construction c.1930 Photos 32

Function House

Plan Form Rectangular

Height (Stories) 1.5

Method of

Overall

style Picturesque: Tudor

Construction Wood-frame

Condition E

Additions & Alterations (Types & Dates)

Evaluation of Specific Elements: Foundation: Materials Concrete Walls: Cladding 2" Clapboard

Condition E

Condition E

Condition E

Windows: General/ Type

Glazing

Condition Location

Pattern Unique Double-hung, wood-sash

6/1

 $\mathbf{E}$ 

Doors: Type Glazing Pattern Condition Location

Prairie

3/3

E North

Roof: Form Gable; steep

Materials Asphalt shingles

Condition E

Type Shed (2)

Location(s) East, West

Chimneys/Ventilators: Materials Stucco chimney with 2 clay flues

Condition I

Location(s) Interior: ridge

Materials Porches:

Condition Height Roof Location

(Stories) Configuration

Concrete; wrought iron balustrade

0

North

Bays/Towers: Form

Condition Height (Stories) Location(s)

ARCHITECTURAL EVALUATION/PRINCIPAL STRUCTURE
Site No. PN-RC -RC-WB-00153 Building # 1

Significant Exterior Details:

Porch: brick header course border

Roof: gables have 1' overhang, gable fascia is at the wall plane and extends in lightning bolt pattern

Significant Interior Details:

Interior not accessed

ARCHITECTURAL EVALUATION/ANCILLARY ST	TRUCTURES	Site No. PN-RC -RC-WB	3-00153
Bldg# Date C/NC Function 2 c.1920 C Alley house	=	Construction Method Wood-frame	Height 1
Windows: Type & Glazing Pa	adding- 2' attern- Do attern- 1 erials- Ga	'Clapboard buble-hung wood; 1/1 Square panel; fixed light able; asphalt shingles	Cond. E E E E E E

Significant Exterior Details
House appears tall at gables; pergola over sidewalk

Significant Interior Details Not accessed

Alterations & Dates

Change in Use

Site Plan: Indicate all door and window openings, roof shapes, and landscape features. ST. JOSEPH ST. North S ALLEY