PLANNING Site No.
Preservation Strengths of the Site ( )
——— In Use and Not Threatened
——— In Good Structural Condition
Owners Protecting Site
——— Appreciated by Public
Valuable to Research
Preservation Threats
Abandonment
Deterioration Through Lack of Resources
——— Vandalism or Looting
Inappropriate Alterations
Inappropriate or Poor Maintenance
Fragile or Deteriorating Construction Materials
Unsound Condition
Lack of Support (Specify by Whom)
——— Environmental Situations Effecting Site (Specify What: May Include Mining,
Flooding, Erosion, Pollution, Acid Rain, Weather, Isolation, Development, Ect.)

SOUTH DAKOTA HISTORIC SIT	ES INVENTORY	Site Number
Historic Name ————————		PN RC RC WB 239 CTY TWP CIT NBH NUM
Address/ 1115 Location — 115	COLUMBUS ST.	
Common Name	WATER TO THE TOTAL THE TOTAL TO THE TOTAL TOTAL TO THE TO	U.S.G.S. Quad Map Name
Historic Function		— Legal Description
Historic Context(s)		Q1 Q2 SEC TWP RNG
Owner's		Only ADD
	······	
Ownon's		— Date —
Construction —		
Photographer ————		—
Roll # ———— Frame #'s	))	NATL STAT LOCL

Publication of this form was assisted by a grant fron the National Park Service. It was published by the South Dakota Historical Preservation Center at a cost of \$.23 per form. ECA-OH-572

#### SOUTH DAKOTA HISTORIC SITES INVENTORY

Historic Name

Address/
Location 1115 Columbus

Common Name

Historic
Function House

Rapid City, SD 57701

Owner's Name Harmon & Evelyn Rose
Owner's Address 1115 Columbus Street

Owner's Phone # (605) 342-1853

Date(s) of Construction 1909

Photographer L. Johnson
Roll # 3 Frame #'s 9-10
(Attach Photographs Below)





Site Number
PN- RC -RC -WB-00239
CTY TWP CIT NBH NUM

**DBASE** 000000000

U.S.G.S. Quad Map Name

Legal Description
0
Q1 Q2 SEC TWP RNG
Urban Only BLK 17
LOT 23-24
ADD Boulevard

Surveyors
L. Johnson/RTI

Date 07/16/1991

NR Eligible Y

Future NR Y

Significance HIST, ARCH, LOCL

#### PLANNING

# Preservation Strengths of the Site

In Use and Not Threatened

- X In Good Structural Condition
  Owners Protecting Site
  Appreciated by Public
- X Valuable to Research

### Preservation Threats of the Site

Abandonment

Deterioration Through Lack of Resources

Vandalism or Looting

Inappropriate Alterations

Inappropriate or Poor Maintenance

Fragile or Deteriorating Construction Materials

Unsound Condition

Lack of Support (Specify by Whom)

Environmental Situations Effecting Site (Specify What: May Include Mining, Flooding, Erosion, Pollution, Acid Rain, Weather, Isolation, Development, Etc.)

Site No. PN-RC -RC-WB-00239

Dates:

Founding of Institution or Settlement 1876

Town and Addition Platted 1877 1885 Initial Construction of Structure 1909

Original Owners:

Name (Include Spouse if Known)
Place of Origin
Date Arrived in S.D. 0000 In USA 0000

Occupation(s)

Religious Affiliation Social/Fraternal Affiliation

Other Previous Owners:

Names and Dates of Occupation Stephen A. & Grace Hearn (R.L. Polk: 1928-31; Stephen listed as auditor, Rapid City, Black Hills & Western Railroad)

Structural History:
Architect's Name and
Date of Commission

Builder's Name Pattern, Book and Number/Name

Historic Uses of the Site House

Changes in Use

Statement of Historical Significance: (Including Relation to Historic Context Topics and Study Units)

This property has the potential to contribute to the West Boulevard Historic District. It is significant for its association with the growth of and development of the West Boulevard neighborhood in Rapid City from 1878 to 1942. Built circa 1909, the house corresponds with the rebuilding phase of residential development in Rapid City (1898 to 1929), a period in which the West Boulevard neighborhood rapidly grew in response to tremendous population growth in the city. The property illustrates the varied economic status of the neighborhood's inhabitants during this period and serves as a representative example of residential architecture popular at the time.

# Miscellaneous Historical Information:

Historic research indicates that the house was built in 1909, around the time that Oscar Egemo received a water permit for the property. Egemo worked as a mason, and its seems likely that the house was one of his building projects. (The 1914 city directory shows Egemo living elsewhere in the city). The original owner and/or occupants of this

#### Bibliography:

Oral Interview (Name, Date & Relationship to Site)

Atlas (Date & Publisher)

County History (Title & Pages)

Deed Abstract

Tax Records Assessors' Card: 1909

Sanborn-Ferris Maps (Dates)
1923 (first map of area)

Census Records

Historical Photos (Description & Date)

Manuscripts (Name & Date)

Directories (Type & Date) R.L. Polk: 1928, 1930-31

Other Sources Rapid City Public Works, Water Permit #562: O. Egemo, 1909

General Information:

Building # 1

Site No. PN-RC -RC-WB-00239 Date of Construction 1909

Photos 9,10

Function House

Plan Form Rectangular

Height (Stories) 1.5 Overall

Method of

Style Vernacular

Construction Wood-frame

Condition E

Additions & Alterations (Types & Dates)

Full-length, shed-roofed addition & gabled-roofed house at the rear (south) were added after 1930.

Evaluation of Specific Elements:

Foundation: Materials Sandstone; coursed sandstone Condition E

Walls: Cladding 4" Clapboard Condition E

Windows: General/ Type Glazing Condition Location

Unique Pattern

G Double-hung, wood-sash 1/1 E

U Cottage E East
U Cottage Leaded transom E North

Doors: Type

Glazing Pattern Condition Location

Not visible North

Roof: Form Gable with returns Materials Asphalt shingles Condition E

Dormer: Type Gable; Shed Condition E

Location(s) North; South (attached building)

Chimneys/Ventilators: Materials Concrete masonry unit (2) Condition E

Location(s) Exterior: east; Exterior: west (addition

Porches: Materials Condition Height Roof Location

(Stories) Configuration

Tapered round columns E 1 Hip North

Bays/Towers: Form Condition Height(Stories) Location(s)

ARCHITECTURAL EVALUATION/PRINCIPAL STRUCTURE Page Site No. PN-RC -RC-WB-00239 Building #

### Significant Exterior Details:

Porch: 4" clapboard balustrade, lattice skirt
Cornice boards with cornice molding
Routed side panels flank the door on north side

# Significant Interior Details:

Interior not accessed

ARCHI	TECTURAL	EVA	LUATION/	ANCILLARY	STRUCTURES	Site No	. PN-RC	-RC-WB-0023
===== Bldg# 2			Function Garage;	=========     Apartment	Photo#	Construction Wood-frame	Method	Heigh 1
						Indi	vidual	Element Cond
0	11 Condi	+ion	F Found	dation: Ma	terials- Co	oncrete		E
Overa	II Conar	CIOII	E Poun	Walls: C	ladding- 4	" Clapboard		E
	Win	dows	· Type	& Glazing	Pattern- 1	/1 double-hung	Pallad	lian E
		oors	: Type	& Glazing	Pattern- O	verhead		E
			Roof:	Form & Ma	<b>terials-</b> Ga	able		E
	Chimn	ev/V	ent: Ma	terial & L	ocation-			

Significant Exterior Details Fixed lights on south side

Significant Interior Details Not accessed

Alterations & Dates Owner supplied construction date

Change in Use