#### STAFF REPORT

June 20, 2002

# No. 02SR009 - 11-6-19 SDCL Review to allow public improvements

**ITEM 22** 

### **GENERAL INFORMATION:**

PETITIONER TSP Three, Inc.

REQUEST No. 02SR009 - 11-6-19 SDCL Review to allow public

improvements

**EXISTING** 

LEGAL DESCRIPTION Block 34, 35, 36, 37, 46, 47, 48, and the west 145 feet of

Block 49, Airport Subdivision, Section 25, T2N, R7E, BHM, Rapid City, Pennington County, South Dakota

PARCEL ACREAGE Approximately 3.74 acres

LOCATION At the intersection of Curtis Street and Lindbergh Street

EXISTING ZONING Medium Density Residential District

SURROUNDING ZONING

North: Low Density Residential District

South: Medium Density Residential District/Low Density

Residential District

East: Public District

West: Low Density Residential District

PUBLIC UTILITIES City water and sewer

DATE OF APPLICATION 05/10/2002

REPORT BY Lisa Seaman

#### **RECOMMENDATION:**

Staff recommends that the 11-6-19 SDCL Review be approved with the following stipulations:

#### **Engineering Division Recommendations:**

- 1. Prior to issuance of a Building Permit, an erosion/sediment control plan shall be submitted for review and approval;
- 2. Applicable Haines Avenue Drainage Basin Fees shall be paid upon issuance of a building permit;
- 3. All approach, sidewalk and curb and gutter construction and repair shall be completed in the same construction season as the parking lot improvements are completed;
- 4. Prior to issuance of a Building Permit, a grading plan shall be submitted for review and approval showing the location of a overflow channel between the buildings and that the final floor elevation of the buildings shall be eighteen inches above the bottom of the overflow channel;

June 20, 2002

## No. 02SR009 - 11-6-19 SDCL Review to allow public improvements

**ITEM 22** 

### **Fire Department Recommendations:**

- 5. All Uniform Fire Codes shall be continually met;
- 6. All requirements of the Street Design Criteria Manual shall be continually met;

### **Air Quality Division Recommendations:**

 An Air Quality Construction Permit shall be obtained if more than one acre of surface area is disturbed prior to the issuance of any building permits or grading permits;

## **Building Inspection Division Recommendations:**

8. A Building Permit shall be obtained prior to any construction; and,

### **Urban Planning Division Recommendations:**

- 9. All provisions of Section 17.50.270, the Minimum Off-Street Parking Requirements of the Rapid City Municipal Code shall be continually met;
- GENERAL COMMENTS: This item was continued from the June 6, 2002 Planning Commission meeting. (Updates to the staff report are shown in bold.) The Pennington County Housing Authority is proposing to construct a parking lot in the northeast corner of the subject property. The subject property is located at the intersection of Lindbergh Street and Wood Avenue. Currently, six multi-family units and two off-street parking areas are located on the property. The applicant is proposing to relocate one of the parking areas to the northeast side of three of the multi-family units. The site plan submitted with this request shows that the parking lot will be paved with asphalt and curb and gutter will be installed around the perimeter of the parking lot and the access aisles. The demolition plan shows that the pavement in the existing parking lot located on the southwest side of the multi-family units will be removed and the approaches to this parking lot closed.
- STAFF REVIEW: SDCL 11-6-19 requires that prior to construction of any street, park or other public way, ground, place, space, public building or structure, or public utility the location and extent thereof shall be submitted to and approved by the Planning Commission. Staff has reviewed the proposed parking lot construction for compliance with all applicable requirements of the Zoning Ordinance and Rapid City Comprehensive Plan.

The North Rapid Neighborhood Area Future Land Use Plan identifies the property as appropriate for development as multi-family land uses. The zoning and existing land use appear to be consistent with the adopted land use plan.

Staff has noted a few site plan issues that must be addressed prior to consideration by the Planning Commission:

<u>Drainage</u>: The site grading and drainage plan for the parking lot relocation shows a storm inlet in the southwest corner of the proposed parking lot. The inlet discharges through a pipe that is buried between two of the multi-family units. The Engineering Division has noted that the site grading plan does not provide an overflow channel between the multi-family units to convey storm water in the event the inlet is inundated with storm water. Staff

#### STAFF REPORT

June 20, 2002

## No. 02SR009 - 11-6-19 SDCL Review to allow public improvements

**ITEM 22** 

is requesting that the applicant revise the grading plan to provide channel between the multifamily units of the appropriate depth to insure that storm water is channeled away from the multi-family units.

Off-Street Parking: The site plan submitted with this request included the location of 26 parking stalls on the property. The Off-Street Parking Ordinance requires that when 26 parking stalls are provided, two of the stalls be reserved for exclusive use by persons with disabilities. Staff is recommending that the applicant revise the site plan to show the location of two handicap-accessible parking stalls and that one of those stalls be vanaccessible. On June 10, 2002 that applicant submitted a revised site plan showing the location of 26 off-street parking stalls. Two of the stalls are handicap-accessible with one of them being van-accessible.

<u>Fire Hydrants</u>: Currently, fire hydrants are located at the corner of Lindbergh Street and Wood Avenue and at the south entrance to the parking area that is being relocated. The relocation of the paved parking area and access to the property to the northeast side of the multi-family units increases the distance from the fire hydrant to the location where a emergency vehicle would access the property by more than allowed by the Uniform Fire Code. The Fire Department Staff has requested that the applicant submit a revised site plan identifying the location of one additional on-site fire hydrant. The revised site plan submitted on June 10, 2002 identified the location of the on-site fire hydrant as requested by the Fire Department.