04PL007

operate, maintain, inspect, and repair such improvements and structures as deems necessary to facilitate drainage

from any source.

PLAT OF LOT A OF LOT 2 AND LOT B OF LOT 2


OF BUFFALO CORRAL SUBDIVISION


FORMERLY: LOT 2 OF BUFFALO CORRAL SUBDIVISION

LOCATED IN THE NE1/4 OF THE SE1/4

SECTION 28, T1N, R9E, BHM.

PENNINGTON COUNTY, SOUTH DAKOTA





NOTICE OF HEARING MAY BE SENT TO: STATH MANTZEOROS

915 HALLEY AVENUE

RAPID CITY, SD 57701

LEGEND:

Found survey monument as noted

FEBRUARY 6, 2004

- O Set 5/8 rebar with survey cap marked "Davis Eng 3095"
- Set 5/8 rebar with no cap
- Recorded in previous survey
- Measured this survey

BASIS OF BEARINGS: As shown hereon

CERTIFICATE OF TREASURER:

I, Treasurer of Pennington County, do hereby certify that all taxes which are liens upon the within described lands are fully paid according to the records of my office.