SENERAL INFORMATION:	
PETITIONER	Fisk Land Surveying & Consulting Engineers for Mike Buckingham, Dlorah Inc.
REQUEST	No. 04PD080 - Major Amendment to Fairway Hills Planned Residential Development Plan
EXISTING LEGAL DESCRIPTION	A tract of land located in the N½ SW¼ and in the SW½ NW¼ of Section 15, T1N, R7E, BHM, Rapid City Pennington County, South Dakota, more fully described as follows: beginning at the southeast corner of Lot 29F of Fairway Hills P.R.D., as shown on the plat filed of February 17, 1984 and recorded in Plat Book 19 on Page 124, said corner being marked by a rebar with surve cap number 3095;Thence, South 73 degrees 09 minute 46 seconds East, more or less, a distance of 4.84 fee more or less, to a point along the westerly edge of Fairway Hills Drive right-of-way, as shown on the plat filed on March 10, 1986 and recorded in Plat Book 20 on Page 224, said corner being marked by a rebar wigh surve cap number 6565; Thence, southerly and along the westerly edge of said Fairway Hills Drive right-of-way, S16°50'14'W, more or less, a distance of 160.90 feel more or less to a point of curvature along said right-of way, said point being marked by a rebar with survey cap number 6565; thence, continuing along the westerly edge of said Fairway Hills Drive right-of-way and curving to the right on a curve with a radius of 96.87 feet, a delt of 17°55'27", an arc length of 30.30 feet, a chord bearing of S25°58'25"W, more or less, to a point of tangent on the westerly edge of said right-of-way, S34°46'00" W, more or less, a distance of 496.97 feet, more or less to a point of using along the westerly edge of said Fairway Hills Drive right-of-way, said point being marked by a rebar with survey cap number 6565. Thence, continuing along the westerly edge of said Fairway Hills Drive right-of-way, said point being marked by a rebar with survey cap number 6565. Thence, continuing along the westerly edge of said Fairway Hills Drive right-of-way, said point being marked by a rebar with survey cap number 6565. Thence, continuing along the vesterly edge of said Fairway Hills Drive right-of-way, said point being marked by a rebar with survey cap number 6565; Thence continuing along the northwesterly edge of said Fairway Hills Drive right-of-way and

right-of-way, said point being marked by a rebar with survey cap number 6565; Thence, continuing along the northerly edge of said Fairway Hills Drive right-of-way, N53º37'38", W more or less, a distance of 69.36 feet, more or less, to a point of curvature along said right-ofway, said point being marked by a rebar with survey cap number 6565; Thence, continuing along the northerly edge of said Fairway Hills Drive right-of-way and curving to the left on a curve with a radius of 230.00 feet, a delta of 4º41'57", an arc length of 18.86 feet, a chord bearing of N56º09'17" W, more or less, and a chord distance of 18.86 feet, more or less, to a point on the northerly edge of said Fairway Hills Drive right-of-way, said point being marked by a rebar with survey cap number 6565; Thence, continuing along the northerly edge of said Fairway Hills Drive right-of-way, as shown on the plat filed September 22, 2004 and recorded in Plat Book 32 on page 94, and curving to the left on a curve with a radius of 230.00 feet, a delta of 16°30'34", an arc length of 66.27 feet, a chord bearing of N66º39'30" W, more or less, and a chord distance of 66.04 feet, more or less, to a point on the northerly edge of said Fairway Hills Drive right-of-way, said point also being the southeast corner of Lot 16 of Block 10 of Fairway Hills PRD, as shown on the aforementioned plat, said point being marked by a number 6565; rebar with survey cap Thence. northeasterly along the easterly line of said Lot 16 in Block 10 of Fairway Hills PRD, N14º38'21" E, more or less, a distance of 102.58 feet, more or less, to the northeast corner of said Lot 16, said corner being coincident with the southeast corner of Lot 15 of Block 10 of Fairway Hills PRD, and said corner being marked by a rebar with survey cap number 6565; Thence, northeasterly along the easterly lot line of said Lot 15 in Block 10 of Fairway Hills PRD, N14º38'21" E, more or less, a distance of 83.44 feet, more or less, to a point on the easterly lot line of said Lot 15, said point being marked by a rebar with survey cap number 6565; Thence, northwesterly along the northeasterly lot line of said Lot 15 in Block 10 of Fairway Hills PRD, N25°09'50" W, more or less, a distance of 132.38 feet, more or less, to the northerly corner of said Lot 15, said corner being coincident with the northeast corner of Lot 14 of Block 10 of Fairway Hills PRD, and also coincident with the southeast corner of Lot 3B of Fairway Hills PRD, as shown on the plat filed July 9, 1980 and filed in Plat Book

17, Page 189, and also coincident with the westerly lot line of Lot 3A of Fairway Hills PRD, as shown on the plat filed November 21, 1979 and recorded in Plat Book 17, on Page 132, said corner being marked by a rebar with survey cap number 1019; Thence, northeasterly along the easterly lot line of said Lot 3B of Fairway Hills PRD, and the westerly line of said Lot 3A of Fairway Hills PRD, N17º55'58" E, more or less, a distance of 191.15 feet, more or less, to a point on the easterly lot line of said Lot 3B and the westerly lot line of said Lot 3A, said point being marked by a rebar with survey cap number 6565; Thence, northwesterly along the easterly lot line of said Lot 3B of Fairway Hills PRD, and the westerly line of said Lot 3A of Fairway Hills PRD, N20º01'18" W, more or less, a distance of 326.69 feet, more or less, to a point on the easterly lot line of said Lot 3B and the westerly lot line of said Lot 3A, said point being coincident with the southwest corner of Lot H1 of Lot 3A of Fairway Hills PRD, as shown on the plat filed on August 30, 1991 and recorded in Book 8 of Highway Plats on Page 39, said corner being marked by a rebar with survey cap number 6565; Thence, northeasterly along the southerly line of said Lot H1 of Lot 3A of Fairway Hills PRD, N57º02'43" E, more or less, a distance of 77.75 feet, more or less, to the southeasterly corner of said Lot H1 of Lot 3A, said point also being located on the northeasterly lot line of said Lot 3A of Fairway Hills PRD, and also on the southwesterly line of Lot 2 of Fairway Hills PRD, as shown on the plat filed on November 30, 1977 and recorded in Plat Book 15 of Page 215, said corner being marked by a rebar with survey cap number 6565; Thence, southeasterly along the northeasterly lot line of said Lot 3A of Fairway Hills PRD, and along the southwesterly line of said Lot 2 of Fairway Hills PRD, S22º24'27" E, more or less, a distance of 100.94 feet, more or less, to a point on the northeasterly lot line of said Lot 3A and the southwesterly line of said Lot 2, said point being marked by a rebar with survey cap number 3095; Thence, southeasterly along the northeasterly lot line of said Lot 3A of Fairway Hills PRD, and along the southwesterly line of said Lot 2 of Fairway Hills PRD, S40º29'56" E, more or less, a distance of 133.62 feet, more or less, to a point on the northeasterly lot line of said Lot 3A and the southwesterly line of said Lot 2, said point being marked by a rebar with survey cap number 1019; Thence, southeasterly along the northeasterly lot

line of said Lot 3A of Fairway Hills PRD, and along the southerly line of said Lot 2 of Fairway Hills PRD, S76º54'53" E, more or less, a distance of 221.11 feet, more or less, to a point on the northeasterly lot line of said Lot 3A, said point being coincident with the southeast corner of said Lot 2 of Fairway Hills PRD, and also coincident with the westerly line of Lot 30 of Fairway Hills PRD, as shown on the plat filed February 17, 1984 and recorded in Plat Book 19 on Page 124, said point being marked by a rebar with survey cap number 1019; Thence, southerly along the easterly line of said Lot 3A of Fairway Hills PRD, and along the westerly line of said Lot 30 of Fairway Hills PRD, S08º05'24" E, more or less, a distance of 102.89 feet, more or less, to a point on the easterly line of said Lot 3A, said point being coincident with the southwest corner of said Lot 30, said point being marked by a rebar with survey cap number 3095; Thence, northeasterly along the southerly line of said Lot 30 of Fairway Hills PRD, N76º46'01" E, more or less, a distance of 105.59 feet, more or less, to the southeast corner of said Lot 30, said corner also being coincident with the southwesterly corner of Lot 29R of Fairway Hills PRD, as shown on the plat filed February 17, 1984 and filed in Plat Book 19 and Page 124, said corner being marked by a rebar with survey cap number 3095; Thence, easterly along the southerly lot line of said Lot 29R of Fairway Hills PRD, N76º42'20" E, more or less, a distance of 161.03 feet, more or less, to a point on the southerly lot line of said Lot 29R, said point being marked by a rebar with survey cap 3095; Thence, easterly along the southerly lot line of said Lot 29R of Fairway Hills PRD, N87º22'22" E, more or less, a distance of 66.97 feet, more or less, to the point of beginning. Said tract of land contains 8.00 acres, more or less

PROPOSED LEGAL DESCRIPTION	Lot 3A revised and Block 11 of Fairway Hills Planned Residential Development
PARCEL ACREAGE	Approximately 8.00 acres
LOCATION	Along Fairway Hills Drive and Old Hwy. 40
EXISTING ZONING	Medium Density Residential District with a Planned Residential District

SURROUNDING ZONING

North:	Medium Density Residential District with a Planned
	Residential District
South:	Medium Density Residential District with a Planned
	Residential District
East:	Medium Density Residential District with a Planned
	Residential District
West:	Medium Density Residential District with a Planned
	Residential District
PUBLIC UTILITIES	City water and sewer
DATE OF APPLICATION	12/10/2004
DATE OF APPLICATION	12/10/2004
REVIEWED BY	Vicki L. Fisher / Curt Huus

RECOMMENDATION:

Due to Staff illness, the completed staff report will be forwarded to the Planning Commission as soon as possible.

GENERAL COMMENTS:

The applicant has submitted a Major Amendment to the Fairway Hills P.R.D. to allow an apartment complex to be constructed on the subject property. In particular, the apartment complex will consist of four buildings, each three stories in height with a drive under garage in each building. In addition, each building will consist of 27 units for a total of 108 units. The applicant has also submitted a Preliminary Plat to subdivide the subject property into two lots. (See companion item #04PL192.)

The property is located along Fairway Hills Drive within the Fairway Hills Planned Residential Development. Currently, a clubhouse, swimming pool and playground are located on proposed Lot 3A and proposed Block 11 is void of any structural development.

STAFF REVIEW:

Due to staff illness, the staff report for this project has not been completed as of this writing. Staff will forward the completed report to the Planning Commission as soon as possible.