

STAFF REPORT
January 25, 2007

No. 06PL171 - Preliminary Plat

ITEM 6

GENERAL INFORMATION:

PETITIONER Fisk Land Surveying for Harley Taylor

REQUEST **No. 06PL171 - Preliminary Plat**

EXISTING
LEGAL DESCRIPTION

A parcel of land located in the N½ SW¼ of Section 21, T1N, R7E, BHM, Pennington County, South Dakota, more fully described as follows: Beginning at the northeast corner of the N½ SW¼ of said Section 21, said point being also known as the center of said Section 21 and said point being coincident with the southwest corner of Lot R of Block 3 of Westview Estates (as shown on the plat recorded in Plat Book 21 page 102) and also coincident with the northwest corner of Lot 9 of Block 3 of Wildwood Subdivision (as shown on the plat recorded in Plat Book 18 on Page 75), said point being marked by a rebar with cap "LS 1019"; thence, southerly along the north-south quarter section line and along the west line of said Lot 9 of Block 3 of Wildwood Subdivision, S00°00'48"E, a distance of 170.74 feet more or less, to the southwest corner of said Lot 9 of Block 3, of Wildwood Subdivision, said point being coincident with the northwest corner of Lot 10 of Block 3 of Wildwood Subdivision, and said point being marked by a rebar with cap "FISK LS 1771"; thence, continuing southerly along the center quarter section line and along the west line of said Lot 10 of Block 3 of Wildwood Subdivision, S00°03'36"W, a distance of 655.65 feet more or less, to the southwest corner of said Lot 10 of Block 3 of Wildwood Subdivision, said point being coincident with a point on the northerly line of Lot 11 of Block 3 of Wildwood Subdivision (as shown on the plat recorded in Plat Book 18 on Page 75), and said point being marked by a rebar with cap "FISK LS 1771"; thence, southwesterly along the northwesterly line of said Lot 11 of Block 3 of Wildwood Subdivision, S32°53'42"W, a distance of 67.03 feet more or less, to the westerly corner of said Lot 11 of Block 3 of Wildwood Subdivision, said point being coincident with the north corner of Lot 12 of Block 3 of Wildwood Subdivision (as shown on the plat recorded in Plat Book 17 on Page 187), and said point being marked by a rebar with cap "FISK LS 1771"; thence, southwesterly along the northwesterly line of said Lot 12 of Block 3 of Wildwood Subdivision, S32°58'25"W, a distance of 65.94 feet more or less, to the northwest corner of said Lot 12 in Block 3 of Wildwood Subdivision,

STAFF REPORT
January 25, 2007

No. 06PL171 - Preliminary Plat

ITEM 6

said point being coincident with the north corner of Lot 13R of Block 3 of Wildwood Subdivision (as shown on the plat recorded in Plat Book 30 on Page 34), and said point being marked by a rebar with cap "FISK LS 1771"; thence, S90°00'00"W, a distance of 704.97 feet more or less; thence, North, a distance of 747.30 feet more or less; thence, N69°00'53"W, a distance of 37.22 feet more or less; thence, southwesterly and curving to the right on a curve with a radius of 492.26 feet, a delta of 02°26'04", an arc length of 20.92 feet more or less, and a chord bearing of S25°13'48"W, and a chord distance of 20.91 feet, more or less; thence, N63°33'10"W, a distance of 100.00 feet more or less; thence, northeasterly and curving to the left on a curve with a radius of 392.26 feet, a delta of 09°44'59", an arc length of 66.75 feet more or less, and a chord bearing of N21°34'20"E, and a chord distance of 66.67 feet, more or less; thence, S83°00'00"W, a distance of 363.67 feet more or less; thence, S04°41'43"E, a distance of 202.00 feet more or less; thence, S35°35'41"W, a distance of 163.11 feet more or less, to a point on the 1/16th section line; thence, S89°47'34"W, a distance of 331.70 feet more or less, to a point on the 1/256th section line; thence, northerly along said 1/256th section line, N00°12'26"W, a distance of 463.97 feet more or less, to a point on the east-west one-quarter section line of said Section 21, said point also being located on the south line of Lot 9 of Block 5 of Westview Estates Subdivision (as shown on the plat recorded in Plat Book 27 on Page 177); thence, easterly along said one-quarter section line and along the south line of said Lot 9 of Block 5 of Westview Estates and along the south line of Lot 1 of Block 5 of Westview Estates (as shown on the plat recorded in plat Book 27 on Page 177), N89°47'51"E, a distance of 331.81 feet, more or less, to a point on the north-south 1/16th section line, said point being marked by a rebar; thence, continuing easterly along said one-quarter section line and along the south line of said Lot One (1) of Block Five (5) of Westview Estates, N89°46'54"E, a distance of 272.14 feet more or less, to a point marked by a rebar; thence, continuing easterly along said one-quarter section line and along the south line of said Lot 1 of Block 5 of Westview Estates and along the south line of Carriage Hills Drive right-of-way, N89°51'26"E, a distance of 270.78 feet more or less, to the southeast corner of the terminus of Carriage Hills Drive, said point also being coincident with the southwest corner of Lot 27 of Block 3 of Westview Estates (as shown on the plat

STAFF REPORT
January 25, 2007

No. 06PL171 - Preliminary Plat

ITEM 6

recorded in Plat Book 27 on page 177), said point being marked by a rebar with survey cap "LS 2652"; thence, continuing easterly along said one-quarter section line and along the south line of said Lot 27 of Block 3 of Westview Estates, N89°50'31"E, a distance of 224.99 feet, more or less, said point being marked by a rebar with cap "FISK LS 1771"; thence, continuing easterly along said one-quarter section line and along the south line of said Lot 27 of Block 3 of Westview Estates, N89°48'02"E, a distance of 29.61 feet more or less, to the southeast corner of said Lot 27 of Block 3 of Westview Estates, said point also being coincident with the southwest corner of Lot 26R of Block 3 of Westview Estates (as shown on the plat recorded in plat Book 27 on page 177), said point being marked by a rebar with cap "LS 2652"; thence, continuing easterly along said one-quarter section line and along the south line of said Lot 26R of Block 3 of Westview Estates, N89°52'45"E, a distance of 100.03 feet more or less, to a point marked by a rebar with cap "LS 2652"; thence, continuing easterly along said one-quarter section line and along the south line of said Lot 26R of Block 3 of Westview Estates, N89°46'22"E, a distance of 165.37 feet more or less, said point being marked by a rebar with cap "FISK LS 1771"; thence, continuing easterly along said one-quarter section line and along the south line of said Lot 26R of Block 3 of Westview Estates, N89°48'13"E, a distance of 134.59 feet more or less, to the southeast corner of said Lot 26R of Block 3 of Westview Estates, said point being coincident with the southwest corner of Lot R of Block 3 of Westview Estates, and said point being marked by a rebar with cap "LS 2652"; thence, continuing easterly along said one-quarter section line and along the south line of said Lot R of Block 3 of Westview Estates, N89°48'06"E, a distance of 130.02 feet more or less, to the point of beginning.

PARCEL ACREAGE	Approximately 22.32
LOCATION	At the southern terminus of Carriage Hills Drive
EXISTING ZONING	Suburban Residential District (Pennington County)
SURROUNDING ZONING	
North:	Low Density Residential District
South:	Suburban Residential District (Pennington County)
East:	Low Density Residential District
West:	Suburban Residential District (Pennington County)

STAFF REPORT
January 25, 2007

No. 06PL171 - Preliminary Plat

ITEM 6

PUBLIC UTILITIES	City sewer and water
DATE OF APPLICATION	10/13/2006
REVIEWED BY	Vicki L. Fisher / Mary Bosworth

RECOMMENDATION:

Staff recommends that the Preliminary Plat be approved with the following stipulations:

1. Prior to Preliminary Plat approval by the City Council, a cost estimate of the subdivision improvements shall be submitted for review and approval;
2. Upon submittal of a Final Plat application, surety for any required subdivision improvements that have not been completed shall be posted and the subdivision inspection fees shall be paid; and,
3. Prior to the City's acceptance of the public improvements, a warranty surety shall be submitted for review and approval as required.

GENERAL COMMENTS:

The applicant has submitted a Preliminary Plat to subdivide the subject property into eight residential lots. On November 9, 2006, the Planning Commission recommended approval of the Preliminary Plat with stipulations. However, on December 15, 2006 the applicant submitted a revised plat document reconfiguring three of the lots. Subsequently, on December 18, 2006, the City Council sent the Preliminary Plat back to the Planning Commission for review at the applicant's request.

On October 2, 2006, the City Council approved a Layout Plat to subdivide the subject property into eight lots. In addition, the City Council approved a Variance to the Subdivision Regulations to waive the requirement to install sidewalk along Carriage Hills Drive and Elysian Court; to reduce the pavement width from 40 feet to 27 feet along Carriage Hills Drive; and, to allow a lot twice as long as wide. The City Council also approved an Exception to the Street Design Criteria Manual to allow 63 dwelling units with one point of access in lieu of 40 dwelling units. (See companion items 06PL141, 06SV054 and 06EX045.)

The subject property is located at the southern terminus of Carriage Hills Drive. Currently, a riding arena and a barn are located on the property.

STAFF REVIEW:

Staff has reviewed the Preliminary Plat and has noted the following considerations:

Construction Plans: The construction plans have been reviewed and approved as a part of the previous review of the Preliminary Plat. In particular, all red line comments have been addressed and no additional revisions are needed due to the reconfiguration of the three lots.

Warranty Surety: On June 19, 2006, the City Council adopted a resolution establishing a formal warranty process for subdivision improvements. In particular, the resolution requires that

STAFF REPORT
January 25, 2007

No. 06PL171 - Preliminary Plat

ITEM 6

the developer provide an acceptable Warranty Surety for the required public improvements. In particular, the Warranty Surety must be in force for a period of two years after the required final inspection and the City has accepted the improvements. As such, staff is recommending that prior to the City's acceptance of the public improvements, a warranty surety be submitted for review and approval as required.

Staff believes that this proposed plat generally complies with all applicable Zoning and Subdivision Regulations assuming compliance with the stated stipulations.