



CITY OF RAPID CITY

RAPID CITY, SOUTH DAKOTA 57701-5035

Growth Management Department

300 Sixth Street

Brad Solon, Building Official
Development Service Center
City web: www.rcgov.org

Phone: 605-394-4157
Fax: 605-394-6636
e-mail: brad.solon@rcgov.org

MEMORANDUM

From: Brad Solon, Building Official
To: Rapid City Planning Commission
Date: September 18, 2008
Subject: Road Name Change - Service Road to Bridge View Drive

Business owners along the old South Highway 79 service road (in the 2201-2999 address range) currently use South Highway 79 as their address. Highway 79 is no longer located in the vicinity. The adjoining property owners agree that the service road should be renamed from where the service road intersects E Saint Joseph Street to where the service road intersects the old portion of South Highway 79. See the attached map.

Staff received many comments of possible names from adjoining property owners. The most suggested name was Bridge View Drive. Emergency Services noted that the name is suitable. The Fire Department commented that there are two other roads named "Bridge" but this road name change would not present a huge problem. Several of the suggested names were inappropriate since they were exact duplicates of names elsewhere in the 911 call area.

RECOMMENDATION: Staff recommends that from where the service road intersects E Saint Joseph Street to the location where the service road intersects the old portion of Highway 79 be renamed Bridge View Drive.



EQUAL HOUSING
OPPORTUNITY

EQUAL OPPORTUNITY EMPLOYER