April 25, 2002

No. 02PL029 - Preliminary and Final Plat

ITEM 12

GENERAL INFORMATION:

PETITIONER Davis Engineering

REQUEST No. 02PL029 - Preliminary and Final Plat

EXISTING

LEGAL DESCRIPTION A portion of Tract F of the NW1/4 of Section 14, T1N,

R8E, BHM, Pennington County, South Dakota

PROPOSED

LEGAL DESCRIPTION Tract A of Murphy Ranch Estates Subdivision of the

NW1/4 of Section 14, T1N, R8E, BHM, Pennington

County, South Dakota

PARCEL ACREAGE Approximately 12.36 acres

LOCATION Southeast of the intersection of Reservoir Road and

Longview Drive

EXISTING ZONING Limited Agriculture District

SURROUNDING ZONING

North: Suburban Residential District
South: Limited Agriculture District
East: General Agriculture District
West: Suburban Residential District

PUBLIC UTILITIES none

DATE OF APPLICATION 03/28/2002

REPORT BY Lisa Seaman

RECOMMENDATION:

Staff recommends that the Preliminary and Final Plat be continued to the May 23, 2002 Planning Commission meeting to allow the applicant time to provide additional required information.

GENERAL COMMENTS: The petitioner has submitted this Preliminary and Final Plat to subdivide one lot out of a larger tract of land in order to transfer title of the property. The subject property is located south of Long View Road, east of Reservoir Road and north of East Highway 44 in Rapid Valley. The subject property is located within Rapid City's three mile platting jurisdiction. The applicant has also submitted an associated Subdivision Regulations Variance request (File # 02SV016) to waive the required improvements along the Long View Road frontage of the subject property.

STAFF REVIEW: Staff has reviewed the Preliminary and Final Plat and has identified several

No. 02PL029 - Preliminary and Final Plat

ITEM 12

issues that must be addressed by the petitioner before the Preliminary and Final Plat can proceed.

Master plan: The Engineering Division has requested that the applicant submit a master plan of the future street network, sanitary sewer lines and drainage improvements. Staff is concerned that platting the property as indicated on the proposed plat may limit the options for internal roadway connections when platting adjacent parcels in the balance of Tract F or when further subdividing the proposed Tract A. The required master plan will identify the number of approaches needed on Long View Drive as well as ensure that adequate approach spacing is provided between the approaches. The subject property is located within the Rapid Valley Sanitary District service area; however, the closest sewer main is located along Reservoir Road. A master plan identifying the applicant's future subdivision of the property and the proposed sanitary sewer system will enable the developer to identify future easements required for the sanitary sewer system. In addition to the master plan, the Engineering Division is requesting that topographic mapping be submitted to identify how storm water runoff from the property will be routed and enable the evaluation of the proposed drainage improvements and easements.

<u>Plat revisions</u>: The plat that was submitted with this request did not include all of the pertinent boundary data required to clearly identify the lot lines of the proposed lot. In particular, the plat clearly shows a curve in the west lot line; however, no curve data defining the exact location of the curve has been provided on the plat. In addition, the scale identified on the plat is incorrect. Staff is recommending that the applicant provide a revised plat providing all the pertinent boundary data.