

STAFF REPORT

September 5, 2002

No. 02PL029 - Preliminary and Final Plat

ITEM 6

GENERAL INFORMATION:

PETITIONER	Davis Engineering
REQUEST	No. 02PL029 - Preliminary and Final Plat
EXISTING LEGAL DESCRIPTION	A portion of Tract F of the NW1/4 of Section 14, T1N, R8E, BHM, Pennington County, South Dakota
PROPOSED LEGAL DESCRIPTION	Tract A of Murphy Ranch Estates Subdivision of the NW1/4 of Section 14, T1N, R8E, BHM, Pennington County, South Dakota
PARCEL ACREAGE	Approximately 12.36 acres
LOCATION	Southeast of the intersection of Reservoir Road and Longview Drive
EXISTING ZONING	Limited Agriculture District
SURROUNDING ZONING	
North:	Suburban Residential District
South:	Limited Agriculture District
East:	General Agriculture District
West:	Suburban Residential District
PUBLIC UTILITIES	None
DATE OF APPLICATION	03/28/2002
REPORT BY	Lisa Seaman

RECOMMENDATION:

Staff recommends that the Preliminary and Final Plat be continued to the September 26, 2002 Planning Commission meeting to be heard in conjunction with the associated Layout Plat.

GENERAL COMMENTS: (Updates to the staff report are shown in bold.) This item was continued from the August 8, 2002 Planning Commission meeting. The applicant met with staff on August 27, 2002 and submitted a revised Preliminary and Final Plat. The applicant has also indicated that a revised Layout Plat will be submitted on August 30, 2002. The petitioner has submitted this Preliminary and Final Plat to subdivide one lot out of a larger tract of land in order to transfer title of the property. The subject property is located south of Long View Road, east of Reservoir Road and north of South Dakota East Highway 44 in Rapid Valley. The subject property is located within Rapid City's three mile platting jurisdiction. The applicant has also submitted an associated Subdivision

STAFF REPORT

September 5, 2002

No. 02PL029 - Preliminary and Final Plat

ITEM 6

Regulations Variance request (File # 02SV016) to waive the required improvements along the Long View Road frontage of the subject property.

STAFF REVIEW: Staff has reviewed the Preliminary and Final Plat and has identified several issues that must be addressed by the petitioner before the Preliminary and Final Plat can proceed.

Master plan: The Engineering Division has requested that the applicant submit a master plan of the future street network, sanitary sewer lines and drainage improvements. Staff is concerned that platting the property as indicated on the proposed plat may limit the options for internal roadway connections when platting adjacent parcels in the balance of Tract F or when further subdividing the proposed Tract A. The required master plan will identify the number of approaches needed on Long View Drive as well as ensure that adequate approach spacing is provided between the approaches. The subject property is located within the Rapid Valley Sanitary District service area; however, the closest sewer main is located along Reservoir Road. A master plan identifying the applicant's future subdivision of the property and the proposed sanitary sewer system will enable the developer to identify future easements required for the sanitary sewer system. In addition to the master plan, the Engineering Division is requesting that topographic mapping be submitted to identify how storm water runoff from the property will be routed and enable the evaluation of the proposed drainage improvements and easements. **The requested master plan was submitted on May 10, 2002 in the form of a Layout Plat (File #02PL049). Staff has reviewed the Layout Plat and noted several major issues. The applicant has indicated that the additional requested information and revised Layout Plat will be submitted on August 30, 2002. Staff is recommending that this Preliminary and Final Plat request be continued to the September 26, 2002 Planning Commission meeting to allow the applicant time to submit the additional required information for further review of the associated Layout Plat.**

Plat revisions: The plat that was submitted with this request did not include all of the pertinent boundary data required to clearly identify the lot lines of the proposed lot. In particular, the plat clearly shows a curve in the west lot line; however, no curve data defining the exact location of the curve has been provided on the plat. In addition, the scale identified on the plat is incorrect. Staff is recommending that the applicant provide a revised plat providing all the pertinent boundary data. **The applicant submitted a revised Preliminary and Final Plat on August 27, 2002.**