

KENNEY DESIGN GROUP, INC. 4955 ENCHANTED PINES DRIVE 605.394.0189 keni@henrikseninc.com

Revisions
No Date Description By


File Name current dwg Na. Date
Drawn By RKK
Onecked By 829.11

OWNER: CORTEZ LLC 502 WEST BLVD RAPID CITY, SD 57701

FORMATION
IMPROVEMENT IN PADDY O'NEILS LOUNGE
LEX JOHNSON, RAPID CITY, SD

DATE: 9.29.11

A1 Drawing Number




OWNER: CORTEZ LLC 502 WEST BLVD RAPID CITY, SD 57701

TENANT IMPROVEMENT IN PADDY O'NEILS LOUNGE HOTEL ALEX JOHNSON, RAPID CITY, SD

DATE: 9.29.11

A2
Drawing Number



KENNEDY DESIGN GROUP, INC. 4955 ENCHANTED PINES DRIVE RAPID CITY, SD 57701 605,394 0199 kenl@henrikseninc.com




Floyer Number 1122
Floyer Number 1122
Floyer British Charles British Checked By HKK
Checked By HKK
Checked By HKK
Checked By HKK

OWNER: CORTEZ LLC 502 WEST BLVD RAPID CITY, SD 57701

> TENANT IMPROVEMENT IN PADDY O'NEILS LOUNGE HOTEL ALEX JOHNSON, RAPID CITY, SD

DATE: 9.29.11

A3
Drawing Number



KENNEDY DESIGN GROUP, INC.
4955 ENCHANTED PINES DRIVE
RAPID GITY, SD 57701
FOR SAGE OF STATE OF STATE

Revisions
No Date Description By


Project Number 1122
File Name Current dwg Drawn By RKK
Checked By RKK
Date

OWNER: CORTEZ LLC 502 WEST BLVD RAPID CITY, SD 57701

> TENANT IMPROVEMENT IN PADDY O'NEILS LOUNGE HOTEL ALEX JOHNSON, RAPID CITY, SD

DATE: 9.29.11

A4 Drawing Number




57701 OWNER: CORTEZ LLC 502 WEST BLVD RAPID CITY, SD 5

TENANT IMPROVEMENT IN PADDY O'NEILS LOUNGE HOTEL ALEX JOHNSON, RAPID CITY, SD

DATE: 9.29.11

REFLECTED CEILING PLAN

Drawing Number



KENNEDY DESIGN GROUP, INC.
4955 ENCHANTED PINES DRIVE
RAPID CITY. SD 57701
605.394.0189

Revisions
No. Date Description By

File Name current dwg No. Precked By RKK Checked By RKK Date


OWNER: CORTEZ LLC 502 WEST BLVD RAPID CITY, SD 57701

> TENANT IMPROVEMENT IN PADDY O'NEILS LOUNGE HOTEL ALEX JOHNSON, RAPID CITY, SD

DATE: 9.29.11

FLOOR COVERING PLAN

A6 Drawing Number



## **KEY NOTE LEGEND**

- 5/8" 'X' GYPSUM BOARD OF FURRING OR EXISTING FRAMING
- 5/8" 'X' GYPSUM BOARD ON EACH SIDE OF 3 5/8" METAL STUD WALL
- CERAMIC TILES ON GYPSUM BOARD BEIGE COLORS - SELECTION BY OWNER
- WOOD PANELING ON GYPSUM BOARD MATCH EXISTING WOOD PANELING TO INCLUDE CAP AND BASE
- FAUX WOOD FLOORING MATCH EXISTING WOOD FLOORING
- CERAMIC OR STONE TILE FLOORING BEIGE COLORS - SELECTION BY OWNER
- SEALED EXISTING CONCRETE FLOOR
- 2'-0" X 2'-0" SUSPENDED CEILING SYSTEM PAINT - COLOR SELECTED BY OWNER
- RECESSED LIGHT FIXTURE
- 10 WALL MOUNTED LIGHT FIXTURE
- 11 LIGHT BAR OVER TOILET VANITY
- 12 TRACK LIGHT SYSTEM
- 13 EXHAUST FAN SYSTEM
- 14 INTERIOR DOOR, MATCH EXISTING TRIMS
- SERVICE BAR CONSTRUCTED SAME AS EXISTING BAR
- 16 EXISTING SOFFIT, REPAIR AS NECESSARY
- 17 FLOOR DRAIN

#### WALL LEGEND

NEW FULL HEIGHT METAL STUD WALL

EXISTING WALL

EXISTING WALL OR CONDITION TO BE DEMO'ED COMPLETELY AND/OR TO BOTTOM OF SOFFIT INCLUDING WALLS AND CONDITIONS THAT SEPARATE THE EXISTING LOUNGE TO THE **EXPANSION** 

### **GENERAL NOTES**

-FIELD VERIFY ALL DIMENSIONS AND CONDITIONS BEFORE BEGINNING CONSTRUCTION OR PROCURING MATERIALS

-MATERIALS AND COLORS TO MATCH THE EXISTING MATERIALS AND COLORS


57701 OWNER: CORTEZ LLC 502 WEST BLVD RAPID CITY, SD 5


TENANT IMPROVEMENT IN PADDY O'NEILS LOUNGE HOTEL ALEX JOHNSON, RAPID CITY, SD


TOILET ROOMS WALL ELEVATIONS

DATE: 9.29.11

Drawing Number







### **KEY NOTE LEGEND**

- 5/8" 'X' GYPSUM BOARD OF FURRING OR EXISTING FRAMING
- 5/8" 'X' GYPSUM BOARD ON EACH SIDE OF 3 5/8" METAL STUD WALL
- CERAMIC TILES ON GYPSUM BOARD BEIGE COLORS SELECTION BY OWNER
- WOOD PANELING ON GYPSUM BOARD MATCH EXISTING WOOD PANELING TO INCLUDE CAP AND BASE
- FAUX WOOD FLOORING MATCH EXISTING WOOD FLOORING
- CERAMIC OR STONE TILE FLOORING BEIGE COLORS - SELECTION BY OWNER
- SEALED EXISTING CONCRETE FLOOR
- 2'-0" X 2'-0" SUSPENDED CEILING SYSTEM PAINT COLOR SELECTED BY OWNER
- 9 RECESSED LIGHT FIXTURE
- 10 WALL MOUNTED LIGHT FIXTURE
- 11 LIGHT BAR OVER TOILET VANITY
- 12 TRACK LIGHT SYSTEM
- 13 EXHAUST FAN SYSTEM
- 14 INTERIOR DOOR, MATCH EXISTING TRIMS
- 15 SERVICE BAR CONSTRUCTED SAME AS EXISTING BAR
- 16 EXISTING SOFFIT, REPAIR AS NECESSARY
- 17 FLOOR DRAIN

### WALL LEGEND

NEW FULL HEIGHT METAL STUD WALL

EXISTING WALL

EXISTING WALL OR CONDITION TO BE DEMO'ED COMPLETELY AND/OR TO BOTTOM OF SOFFIT INCLUDING WALLS AND CONDITIONS THAT SEPARATE THE EXISTING LOUNGE TO THE **EXPANSION** 

# **GENERAL NOTES**

-FIELD VERIFY ALL DIMENSIONS AND CONDITIONS BEFORE BEGINNING CONSTRUCTION OR PROCURING MATERIALS

-MATERIALS AND COLORS TO MATCH THE EXISTING MATERIALS AND COLORS





57701 OWNER: CORTEZ LLC 502 WEST BLVD RAPID CITY, SD 5

TENANT IMPROVEMENT IN PADDY O'NEILS LOUNGE HOTEL ALEX JOHNSON, RAPID CITY, SD

DATE: 9.29.11

GAMING ROOM WALL ELEVATIONS

**A8** Drawing Number