



IMPROVEMENT LOCATION EXHIBIT and BOUNDARY SURVEY

See Misc. Book 106 Page 3125 for easement.



Easement good as long as garage stands No longer valid if garage is taken down

Garage From Adjoining Lot 7 Is Located 1.8' To 1.9' Onto Subject Property.




*Treated Framing
Cedar Decking & Hard Rail & Powder coat spindels*

- Found Survey Monument As Noted
- ⊙ Set Survey Monument Marked "RW FISK 6565"
- (m)- Measured This Survey
- (R)- Recorded On Previous Plat

LEGAL: Lots 8,9 and the N1/2 of Lot 10, Block 31, Boulevard Addition
Rapid City, South Dakota

CLIENT: Laura Lynne Rulz -1215 12th Street
Prudential

I, the Registered Land Surveyor in the State of South Dakota as signed hereon, do hereby certify that this drawing was prepared by me or under my direct supervision. The boundary lines of the parcel of land shown and described hereon are the deed lines of the property as described on the record plat of said property. The location of the major improvements are geometrically calculated from the nearest reliable property corners. This is not a boundary survey and the precise property lines were not determined at the time of this survey. The dimensions to the deed lines are shown to the degree of accuracy required to satisfy the needs of a lending institution or title company and should not be used to establish the true boundary. Easements or restrictions of miscellaneous record or private agreements that are not known to me are not shown hereon.
Copy of Title Commitment _____ Provided: Not Provided



P.O. Box 8154
Rapid City, SD 57709
Phone (605) 348-1538
Fax (605) 341-1112

**FISK LAND SURVEYING
& CONSULTING ENGINEERS, INC.**

SURVEYED: WF 8/9/03
DRAWN: BL 8/20/03
PROJECT NO. 03-242