

ORDINANCE #3637**AN ORDINANCE AMENDING TITLE 15, CHAPTER 15.24 OF THE RAPID CITY MUNICIPAL CODE BY ADOPTING THE 1996 NATIONAL STANDARD PLUMBING CODE AND ADDING A NEW AMENDMENT THERETO.**

BE IT ORDAINED by the City of Rapid City that Section 15.24.010 of Chapter 15.24 of the Rapid City Municipal Code is hereby amended to read as follows:

15.24.010 Adoption.

There is adopted by the City of Rapid City the ~~1993~~ 1996 National Standard Plumbing Code, as adopted by the South Dakota State Plumbing Commission. A copy of the same is on file in the office of the city finance officer.

BE IT FURTHER ORDAINED by the City of Rapid City that Section 15.24.235 of Chapter 15.24 is hereby added amending Chapter 6, Section 6.1 of the National Standard Plumbing Code.

15.24.235 NSPC Chapter 6, Section 6.1, Interceptors – General Amended.

NSPC, Chapter 6, Section 6.1, Subsection 6.1.1 is hereby amended by adding paragraph a, to read as follows:

6.1 INTERCEPTORS GENERAL**6.1.1 When Required**

Interceptors (including grease, oil, and sand interceptors, etc.) shall be provided when, in the opinion of the Administrative Authority, they are necessary for the proper handling of liquid wastes containing grease, flammable wastes, sand, solids, and other ingredients harmful to the building drainage system, the public sewer or sewage-treatment plant or process.

- a. Grease Interceptors. The Director of Public Works, or his designee, (Industrial Pretreatment Personnel) is responsible to determine if a grease interceptor is necessary in Rapid City. The City Plumbing Inspector will approve design, sizing, and installation. All kitchen drainage receiving grease shall pass through the interceptor. The interceptor shall be easily accessible for cleaning and inspection. The responsibility of cleaning and maintaining the interceptor in an efficient operating condition shall be the owner and/or lessee's responsibility. Single family dwelling units are exempt from the grease interceptor requirements. Existing interior replacements may be allowed when proper sizing and installation procedures can be accomplished. When, in the judgement of the Administrative Authority, it would be

impractical or unnecessary to install a full-size grease interceptor outside the building, due to the nature or relative size of a food establishment, the installation of an inline grease trap may be approved. Expense shall not be considered sufficient reason to waive the requirements for full-size grease interceptors.

CITY OF RAPID CITY

Mayor

ATTEST:

Finance Officer

(SEAL)

First Reading:
Second Reading:
Published:
Effective:

Prepared By: CITY ATTORNEY'S OFFICE