



NOTES:

Coordinate with Golf Course Superintendent prior to starting work along golf course.

Remove and reset existing steel post and cable fence along new right of way from 0+00 to 1+ 60 Rt.

Transition from existing to proposed street section 0-40 to 0+00. Replace existing golf cart path approach.

Provide temporary access to golf course from existing W. Chicago Street.



CITY OF RAPID CITY
GROWTH MANAGEMENT DEPT.
DEVELOPMENT SERVICES

There are no warranties or representations made by the City of Rapid City for the use of the information contained herein for any purpose other than that for which it was prepared. The City of Rapid City does not warrant the accuracy, completeness or timeliness of the information contained herein. The City of Rapid City does not warrant the accuracy, completeness or timeliness of the information contained herein. The City of Rapid City does not warrant the accuracy, completeness or timeliness of the information contained herein.

Engineering: _____ Date: _____

Comments: _____