
Plat of Lots 12A and 12B of Lot 12, Block 3 of Gemstone Subdivision.


(formerly all of Lots 12 of Block 3 of Gemstone Subdivision)


08PD023 Located in Section 19, T1N, R8E, BHM,

Rapid City, Pennington County, South Dakota

- = Found Survey Monument, LS6251 or as noted Set Rebar with cap marked "RW Fisk 6565"







N89°51'28"W

214 58'

Sandra Lane 52' Right-of-Way

N89'49'27"W

) ROX 8154 RAPID CITY SD 57709 (605) 348-1538 February 10, 2008

PECEIVED

MAY 0 S 2008

Rapid City Growth Management Department

EPARED BY: K LAND SURVEYING & CONSULTING ENGINEERS, INC.


Bosis of Bearings


Plat of Lots 13A and 13B of Lot 13, Block 3 of Gemstone Subdivision,


(formerly all of Lots 13 of Block 3 of Gemstone Subdivision) 08PD023 Located in Section 19, T1N, R8E, BHM,

Rapid City, Pennington County, South Dakota

- = Found Survey Monument, LS6251 or as noted = Set Rebar with cap marked "RW Fisk 6565"







Sandra Lane Basis of Bearings

N89*52'44"W

26,

S89°52'06"E 52' Right-of-Way

PECEIVED

S89*51'28"E

MAY € € 2008

Rapid City Growth Management Department

REPARED BY:

TSK LAND SURVEYING & CONSULTING ENGINEERS, INC. O ROX 8154 RAPID CITY SD 57709 (605) 348-1538 October 18 2007

N89°52'44"W