



- LEGEND**
- - - - - EXISTING MINOR CONTOUR (1')
 - - - - - EXISTING MAJOR CONTOUR (5')
 - ⊕ BORE LOCATION AND ELEVATION
SEE REPORT OF GEOTECHNICAL
EXPLORATION AND REVIEW
DATED AUGUST 18, 2009
 - ⊕ SIGN (TYPE AS NOTED)
 - ▨ SPILL CURB & GUTTER
 - ▭ STANDARD CURB & GUTTER
 - - - - - CONTROL JOINT
 - - - - - EXPANSION/CONTRACTION JOINT

JOINTS:
ALL CONCRETE JOINTS SHALL BE SEALED
PER SPECIFICATIONS

Prepared By:
RENNER & ASSOCIATES, LLC.
616 5th St. • Rapid City, SD 57701
Phone: 605/721-7310 Fax: 605/721-7313
City Hall 1003

West Parking Lot and Signage Layout

2.10

PROJECT	UNIVERSITY CENTER - BLACK HILLS
NUMBER	0620.2146.09, Error - #2442
DATE	September 21, 2009
DRAWN	ADP
CHECKED	
REVISION	

Architecture Incorporated
415 S. Main Avenue
P.O. Box 2140
Sioux Falls, South Dakota
57101-2140
Phone: (605) 339-1711
Fax: (605) 339-2331