

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
1	Barnett Arena	Interior	Owned	Hallway	Mezzanine Level West by Men's Restroom	1-Public Unsupervised	Drinking Fountain		Height		41 inches	No	Drinking fountain spout height is too high.	2-Service	Replace the existing fountain with a highflow fountain. The low fountain spout height must be 36 inches minimum and the high fountain spout height must be 38 inches to 43 inches.		602	2-Moderate	<a href="#">006</a>	#REF!	#REF!		
2	Barnett Arena	Exterior	Owned	Parking Facility	West lot, NW Parking	1-Public Unsupervised	Access Aisle	2nd from left	Slope, running		7.30%	No	Slope is too steep.	1-Entry	Regrade access aisle or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1:48, 2.08%)	2.08% Maximum	502.3, 502.4, 502.5	1-High	<a href="#">225</a>	#REF!	#REF!		
4	Barnett Arena	Exterior	Owned	Parking Facility	West lot, NW Parking	1-Public Unsupervised	Parking Space	2nd from left	Slope, running		8.10%	No	Slope is too steep.	1-Entry	Regrade parking space or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1:48, 2.08%)	2.08%	502.2	1-High	<a href="#">223</a>	#REF!	#REF!		
5	Barnett Arena	Exterior	Owned	Parking Facility	West lot, NW Parking	1-Public Unsupervised	Parking Space	2nd from left	Van sign?		No	No	No van sign is provided	1-Entry	Provide a Van-Accessible sign at this parking space that is located 60 inches minimum above finished surface.		502.2	3-Low	<a href="#">224</a>	#REF!	#REF!		
7	Barnett Arena	Exterior	Owned	Parking Facility	West lot, NW Parking	1-Public Unsupervised	Signage	2nd from left	Height, bottom		41 inches	No	Signage is too low	1-Entry	Install parking signs at correct height.	60 inches minimum	703	3-Low	<a href="#">224</a>	#REF!	#REF!		
9	Barnett Arena	Exterior	Owned	Parking Facility	West lot, NW Parking	1-Public Unsupervised	Parking Space	1st from left	Slope, running		9%	No	Slope is too steep.	1-Entry	Regrade parking space or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1:48, 2.08%)	2.08%	502.2	1-High	<a href="#">227</a>	#REF!	#REF!		
11	Barnett Arena	Exterior	Owned	Parking Facility	West lot, NW Parking	1-Public Unsupervised	Signage	1st from left	Height, bottom		16 inches	No	Signage is too low	1-Entry	Install parking signs at correct height.	60 inches minimum	703	3-Low	<a href="#">228</a>	#REF!	#REF!		
12	Barnett Arena	Exterior	Owned	Parking Facility	West lot, Nw facing Interstate Bank entrance	1-Public Unsupervised	Access Aisle		Slope, cross		12.60%	No	Slope is too steep.	1-Entry	Regrade access aisle or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1:48, 2.08%)	2.08% Maximum	502.3, 502.4, 502.5	1-High	<a href="#">230</a>	#REF!	#REF!		
15	Barnett Arena	Exterior	Owned	Parking Facility	West lot, Nw facing Interstate Bank entrance	1-Public Unsupervised	Signage		Height, bottom		16 inches	No	Signage is too low	1-Entry	Install parking signs at correct height.	60 inches minimum	703	3-Low	<a href="#">229</a>	#REF!	#REF!		
18	Barnett Arena	Exterior	Owned	Concessions	Mezzanine Level West	1-Public Unsupervised	Counter		Height		42 inches	No	Height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	2-Service	Provide at least a 36" wide portion at the compliant height.	36 inches maximum	904	2-Moderate	<a href="#">235</a>	May 2014	17		
20	Barnett Arena	Exterior	Owned	Walkway	Nw facing Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	1st from parking on path to entrance	Height, level change		1 inch	No	There is a change in level on the in the walkway.	1-Entry	Rebuild curb ramp so that the bottom of the ramp has vertical change in level not > 1/4 inch vertical or 1/2 inch beveled.	5 inch maximum	406	2-Moderate	<a href="#">230</a>	Mar 2014	15		
21	Barnett Arena	Exterior	Owned	Walkway	Nw facing Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	1st from parking on path to entrance	Slope, cross		3.70%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	2.08 maximum	406	1-High	<a href="#">232</a>	Sep 2014	21		
22	Barnett Arena	Exterior	Owned	Walkway	Nw facing Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	1st from parking on path to entrance	Slope, flare	Right	16%	No	Slope is too steep.	1-Entry	Rebuild curb ramp with compliant side flares.	10% maximum	406	1-High	<a href="#">232</a>	Sep 2014	21		
24	Barnett Arena	Exterior	Owned	Walkway	Mezzanine Level Walkway to Accessible Seating	1-Public Unsupervised	Ramp		Slope, running		9.40%	No	Slope is too steep.	4-Other	Rebuild ramp with compliant running slope, cross slope, and landings.	8.33%	405	1-High	<a href="#">232</a>	Mar 2015	27		
26	Barnett Arena	Exterior	Owned	Walkway	Mezzanine Level Walkway around entire seating area	1-Public Unsupervised	Handrail		Cross section dimension, maximum		2.5 inches	No	Diameter of the handrails are too wide	4-Other	Replace handrails with new ones that have the correct diameter.	1.25 inches minimum and 2 inches maximum	505	2-Moderate	<a href="#">239</a>	Sep 2014	21		
28	Barnett Arena	Exterior	Owned	Walkway	Mezzanine Level Walkway around entire seating area	1-Public Unsupervised	Handrail		Height, top		42 inches	No	Handrails are too high	4-Other	Replace handrails and install new ones at the correct height.	34-38 inches	505	2-Moderate	<a href="#">238</a>	Sep 2014	21		
29	Barnett Arena	Exterior	Owned	Walkway	Nw facing Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	2nd from parking on path to entrance	Height, level change		1 inch	No	There is a change in level on the in the walkway.	1-Entry	Rebuild curb ramp so that the bottom of the ramp has vertical change in level not > 1/4 inch vertical or 1/2 inch beveled.	5 inch maximum	406	2-Moderate	<a href="#">341</a>	#REF!	#REF!		
30	Barnett Arena	Exterior	Owned	Walkway	Nw facing Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	2nd from parking on path to entrance	Slope, cross		3.70%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	2.08 maximum	406	1-High	<a href="#">341</a>	#REF!	#REF!		
31	Barnett Arena	Exterior	Owned	Walkway	Nw facing Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	2nd from parking on path to entrance	Slope, flare	Right	16%	No	Slope is too steep.	1-Entry	Rebuild curb ramp with compliant side flares.	10% maximum	406	1-High	<a href="#">341</a>	#REF!	#REF!		
33	Barnett Arena	Interior	Owned	Sport Area		1-Public Unsupervised	Wheelchair Space		Companion seat?		Yes, Folding chairs provided, but placed behind seats	No	Companion seats are provided but are sometimes placed behind wheelchair seats.	2-Service	See Executive Summary		802.1, 221	2-Moderate	<a href="#">241</a>	#REF!	#REF!		
34	Barnett Arena	Interior	Owned	Sport Area		1-Public Unsupervised	Wheelchair Space		Depth		36 inches marked	No	Wheelchair spaces are not deep enough.	2-Service	Wheelchair spaces should be 48 inches deep when entered from the front or rear and 60 inches deep when entered only from the side.		802.1, 221	2-Moderate	<a href="#">243</a>	#REF!	#REF!		
35	Barnett Arena	Interior	Owned	Sport Area		1-Public Unsupervised	Wheelchair Space		Width		32 inches	No	Wheelchair spaces are not wide enough.	2-Service	Wheelchair spaces should be 36 inches wide minimum or where adjacent wheelchair spaces are provided the spaces are allowed to be 33 inches wide minimum. Companion seats must still be provided for each wheelchair seat.		802.1, 221	2-Moderate	<a href="#">243</a>	#REF!	#REF!		
36	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Door Gate		Clear opening	At Turn	34.75 inches	No	The clear width at the turn is not wide enough.	3-Restrooms	Reconfigure the vestibule to provide an opening of 48 inches minimum at the turn.	48 inches	403.5.2	1-High	<a href="#">082</a>	Jan 2015	25		
37	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Door Gate		Clear opening	At Turn	34.75 inches	No	The clear width at the turn is not wide enough.	3-Restrooms	Reconfigure the vestibule to provide an opening of 48 inches minimum at the turn.	48 inches	403.5.2	1-High	<a href="#">084</a>	Jan 2015	25		
38	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Door Gate		Clear opening	At Turn	34.75 inches	No	The clear width at the turn is not wide enough.	3-Restrooms	Reconfigure the vestibule to provide an opening of 48 inches minimum at the turn.	48 inches	403.5.2	1-High	<a href="#">086</a>	Jan 2015	25		
39	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Door Gate		Clear opening	At Turn	34.75 inches	No	The clear width at the turn is not wide enough.	3-Restrooms	Reconfigure the vestibule to provide an opening of 48 inches minimum at the turn.	48 inches	403.5.2	1-High	<a href="#">083</a>	Jan 2015	25		
40	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Urinal		Depth		12.5 inches	No	Urinal is not deep enough.	3-Restrooms	Install a urinal with the correct depth.	13.5 inches minimum	603, 605	2-Moderate	<a href="#">96</a>	Jul 2014	19		
41	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Urinal		Height, rim		20 inches	No	Urinal rim is too high.	3-Restrooms	Replace or remount the urinal to the correct height.	17 inches maximum	603, 605	2-Moderate	<a href="#">96</a>	Jul 2014	19		
44	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Fixture Count		Number, ambulatory compartments		0	No	No ambulatory toilet compartment is provided	3-Restrooms	When six or more toilet compartments are provided including urinals, an ambulatory toilet compartment is required.		603, 213	1-High	No Photo	Jan 2015	25		
46	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Water Closet		Height, seat		19.5 inches	No	Toilet seat is too high	3-Restrooms	Adjust or modify the toilet so the seat height is at the required accessible height.	17-19 inches	603, 213.2, 604.2, 604.3, 604.4, 604.6	2-Moderate	<a href="#">093</a>	Jul 2014	19		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
47	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Grab Bar	Side Wall	Clearance, to wall		3 inches	No	Space between the wall and grab bar is too much	3-Restrooms	Replace grab bars with new ones that have the correct spacing.	1.5 inches maximum	603.609	3-Low	<a href="#">092</a>	Jan 2014	13		
48	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Grab Bar	Side Wall	Dimension, end to wall		13 inches	No	Side wall grab bar is located to far away from the back wall.	3-Restrooms	Move the grab bar.	12 inches maximum	603.609	3-Low	<a href="#">092</a>	Jan 2014	13		
49	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Grab Bar	Side Wall	Dimension, between	Toilet Paper Dispenser and Grab Bar	5 inches	No	Dispenser is located above the grab bar.	3-Restrooms	Relocate the dispenser so that it does not interfere with the grab bar.	12 inches minimum between the dispenser and grab bar	603.609	3-Low	<a href="#">090</a>	Jan 2014	13		
50	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		0 inches	No	Toilet paper dispenser is not mounted at the correct location.	3-Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603.604.7, 604.9.6, 606.1	3-Low	<a href="#">090</a>	Jan 2014	13		
51	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Toilet Compartment		Door location		In Front of Toilet	No	Door is located in front of water closet.	3-Restrooms	Relocate door in the front partition farthest from the front of the water closet.		603.604.8.1	2-Moderate	<a href="#">095</a>	Jul 2014	19		
52	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Toilet Compartment		Self-closing?		No	No	Toilet compartment door does not have self-closing hinges.	3-Restrooms	Install self-closing hinges on the toilet compartment door.		603.604.8.1	3-Low	<a href="#">097</a>	Jan 2014	13		
53	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Toilet Compartment		Door swing direction		In	No	Compartment door swings into the clear floor of the toilet compartment.	3-Restrooms	Change the door swing of the door.		603.604.8.1	3-Low	<a href="#">097</a>	Jan 2014	13		
54	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Toilet Compartment		Hardware both sides?		One Side	No	Door pull is not provided on both sides of the toilet compartment door.	3-Restrooms	Install a door pull on both sides of the door.		603.604.8.1	3-Low	<a href="#">094</a>	Jan 2014	13		
56	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Grab Bar	Rear Wall	Dimension, between	Water Closet Centerline and End of Grab Bar	22 inches	No	Grab bar is not mounted in the correct location.	3-Restrooms	Rear grab bar should provide 12 inches minimum from the center line of the water closet on one side and 24 inches minimum from the center line of the water closet on the other side.	24 inches	603.609	3-Low	<a href="#">091</a>	Jan 2014	13		
57	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Protrusion		Dimension, protruding	Lavatory	28 inches	No	Lavatory protrudes into the path of travel.	3-Restrooms	Remove sink or install a new sink that isn't a protruding object	4 inches maximum protrusion in path of travel at 27 inches high minimum	603.307.2, 307.3	2-Moderate	<a href="#">097</a>	Jul 2014	19		
58	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		No	No	Supply lines/drain are not wrapped.	3-Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		603.606	3-Low	<a href="#">097</a>	Jan 2014	13		
59	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Lavatory Sink		Clearance, perpendicular		19 inches	No	Clear floor space perpendicular to the lavatory is not long enough.	3-Restrooms	Reconfigure the restroom to provided the required clear floor space for the lavatory.	48 inches minimum	603.606	1-High	<a href="#">100</a>	Jan 2015	25		
60	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Dispenser	Soap	Height		48.5 inches	No	Dispenser is mounted too high.	3-Restrooms	Relocate the dispenser to the correct height.	48 inches maximum	603.604.7, 604.9.6, 606.1	3-Low	<a href="#">099</a>	Jan 2014	13		
61	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Mirror		Height, bottom		46 inches	No	The bottom of the mirror is mounted too high	3-Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603.603.3	3-Low	<a href="#">098</a>	Jan 2014	13		
62	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Alarm System		Visible alarm		None Provided	No	There are no visual alarms provided.	2-Services	Install audible and visual alarms in all common spaces.		603.215.702	2-Moderate	<a href="#">No Photo</a>	May 2014	17		
63	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's East	1-Public Unsupervised	Alarm System		Visible alarm		None Provided	No	There are no visual alarms provided.	2-Services	Install audible and visual alarms in all common spaces.		603.215.702	2-Moderate	<a href="#">No Photo</a>	May 2014	17		
64	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Alarm System		Visible alarm		None Provided	No	There are no visual alarms provided.	2-Services	Install audible and visual alarms in all common spaces.		603.215.702	2-Moderate	<a href="#">No Photo</a>	May 2014	17		
65	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Alarm System		Visible alarm		None Provided	No	There are no visual alarms provided.	2-Services	Install audible and visual alarms in all common spaces.		603.215.702	2-Moderate	<a href="#">No Photo</a>	May 2014	17		
68	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Fixture Count		Number, ambulatory compartments		0	No	No ambulatory toilet compartment is provided	3-Restrooms	When six or more toilet compartments are provided an ambulatory toilet compartment is required.		603.213	1-High	<a href="#">No Photo</a>	Jan 2015	25		
69	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Water Closet		Dimension, sidewall		18.5 inches	No	Toilet is located too far away from the side wall on the narrow side.	3-Restrooms	Relocate the toilet so that it is within the required distance from the side wall.	16-18 inches	603.213.3.2, 604.2, 604.3, 604.4, 604.6	1-High	<a href="#">059</a>	Jan 2015	25		
70	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Water Closet		Height, seat		19.5 inches	No	Toilet seat is too high	3-Restrooms	Adjust or modify the toilet so the seat height is at the required accessible height.	17-19 inches	603.213.3.2, 604.2, 604.3, 604.4, 604.6	2-Moderate	<a href="#">063</a>	Jul 2014	19		
71	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Water Closet		Clearance, parallel		40 inches	No	Toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	3-Restrooms	Relocate the toilet in a space which provides the required clearances.	42 inches minimum	603.213.3.2, 604.2, 604.3, 604.4, 604.6	1-High	<a href="#">063</a>	Jan 2015	25		
72	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Grab Bar	Side Wall	Clearance, to wall		3 inches	No	Space between the wall and grab bar is too much	3-Restrooms	Replace grab bars with new ones that have the correct spacing.	1.5 inches maximum	603.609	3-Low	<a href="#">060</a>	Jan 2014	13		
73	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Toilet Compartment		Door swing direction		In	No	Compartment door swings into the clear floor of the toilet compartment.	3-Restrooms	Change the door swing of the door.		603.604.8.1	3-Low	<a href="#">066</a>	Jan 2014	13		
74	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Toilet Compartment		Hardware both sides?		One Side	No	Door pull is not provided on both sides of the toilet compartment door.	3-Restrooms	Install a door pull on both sides of the door.		603.604.8.1	3-Low	<a href="#">066</a>	Jan 2014	13		
75	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Toilet Compartment		Self-closing?		No	No	Toilet compartment door does not have self-closing hinges.	3-Restrooms	Install self-closing hinges on the toilet compartment door.		603.604.8.1	3-Low	<a href="#">066</a>	Jan 2014	13		
76	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Grab Bar	Side Wall	Dimension, end to wall	To Front of Grab Bar	46 inches	No	Grab bar is not mounted in the correct location.	3-Restrooms	Move the grab bar.	54 inches from the rear wall	603.609	3-Low	<a href="#">065</a>	Jan 2014	13		
78	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Grab Bar	Rear Wall	Dimension, between	Water Closet Centerline and End of Grab Bar	20 inches	No	Grab bar is not mounted in the correct location.	3-Restrooms	Rear grab bar should provide 12 inches minimum from the center line of the water closet on one side and 24 inches minimum from the center line of the water closet on the other side.	24 inches	603.609	3-Low	<a href="#">062</a>	Jan 2014	13		
79	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Toilet Compartment		Door location		In Front of Toilet	No	Door is located in front of water closet.	3-Restrooms	Relocate door in the front partition farthest from the front of the water closet.		603.604.8.1	2-Moderate	<a href="#">066</a>	Jul 2014	19		
80	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Grab Bar	Side Wall	Dimension, between	Toilet Paper Dispenser and Grab Bar	4 inches	No	Dispenser is located above the grab bar.	3-Restrooms	Relocate the dispenser so that it does not interfere with the grab bar.	12 inches minimum between the dispenser and grab bar	603.609	3-Low	<a href="#">060</a>	Jan 2014	13		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
81	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		75 inches	No	Toilet paper dispenser is not mounted at the correct location.	3-Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603.604.7, 604.9.6, 606.1	3-Low	<a href="#">061</a>	Jan 2014	13		
82	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		No	No	Supply lines/drain are not wrapped.	3-Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		603.606	3-Low	<a href="#">067</a>	Jan 2014	13		
83	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Protrusion		Dimension, protruding	Lavatory	28 inches	No	Lavatory protrudes into the path of travel.	3-Restrooms	Remove sink or install a new sink that isn't a protruding object	4 inches maximum protrusion in path of travel at 27 inches high minimum	603.307.2, 307.3	2-Moderate	<a href="#">071</a>	Jul 2014	19		
84	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Mirror		Height, bottom		46 inches	No	The bottom of the mirror is mounted too high	3-Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603.603.3	3-Low	<a href="#">068</a>	Jan 2014	13		
85	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Other Element	Baby Change Station	Height, operable part		57.75 inches	No	Baby change table is out of reach range.	3-Restrooms	Lower the baby change table.	48 inches maximum to handle	#N/A	3-Low	<a href="#">069</a>	Jan 2014	13		
86	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's East	1-Public Unsupervised	Other Element	Baby Change Station	Height, top		38.5 inches	No	Baby change table is mounted too high when lowered.	3-Restrooms	The top of the work surface should be 28 inches minimum and 34 inches maximum.	28-34 inches	#N/A	3-Low	<a href="#">070</a>	Jan 2014	13		
88	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3-Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603.213	1-High	<a href="#">No Photo</a>	Jan 2015	25		
90	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Water Closet		Height, seat		21 inches	No	Toilet seat is too high	3-Restrooms	Adjust or modify the toilet so the seat height is at the required accessible height.	17-19 inches	603.213.3.2, 604.2, 604.3, 604.4, 604.6	2-Moderate	<a href="#">039</a>	Jul 2014	19		
91	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Grab Bar	Both Side Wall	Dimension, between	From Front of Grab Bar to Back Wall	48 inches	No	The side grab bar is not located in the correct location	3-Restrooms	The side wall grab bar shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603.609	3-Low	<a href="#">040</a>	Jan 2014	13		
92	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Grab Bar		Dimension, between	Toilet Paper Dispenser and Grab Bar	4.5 inches	No	Dispenser is located above the grab bar.	3-Restrooms	Relocate the dispenser so that it does not interfere with the grab bar.	12 inches minimum between the dispenser and grab bar	603.609	3-Low	<a href="#">041</a>	Jan 2014	13		
93	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Toilet Compartment		Self-closing?		No	No	Toilet compartment door does not have self-closing hinges.	3-Restrooms	Install self-closing hinges on the toilet compartment door.		603.604.8.1	3-Low	<a href="#">043</a>	Jan 2014	13		
94	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Coat Hook		Height		66 inches	No	Coat hook is mounted too high.	3-Restrooms	Lower the coat hook.	48 inches maximum	603.603.4, 604.8.3, 803.5	3-Low	<a href="#">044</a>	Jan 2014	13		
95	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Mirror		Height, bottom		45.5 inches	No	The bottom of the mirror is mounted too high	3-Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603.603.3	3-Low	<a href="#">047</a>	Jan 2014	13		
96	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		Half Way?	No	Supply lines/drain are not wrapped.	3-Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		603.606	3-Low	<a href="#">046</a>	Jan 2014	13		
97	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		25 inches at 8 inches in	No	Insufficient knee clearance is provided.	3-Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603.606	2-Moderate	<a href="#">046</a>	Jul 2014	19		
98	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Other Element	Baby Change Station	Height, operable part		60.75 inches	No	Baby change table is out of reach range.	3-Restrooms	Lower the baby change table.	48 inches maximum to handle	#N/A	3-Low	<a href="#">051</a>	Jan 2014	13		
99	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Other Element	Baby Change Station	Height, top		41.5 inches	No	Baby change table is mounted too high when lowered.	3-Restrooms	The top of the work surface should be 28 inches minimum and 34 inches maximum.	28-34 inches	#N/A	3-Low	<a href="#">050</a>	Jan 2014	13		
100	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Door Gate		Clearance, parallel	Pull Side	2 inches	No	Clearance on the pull side of the door is insufficient.	2-Services	Install doors so that they have the correct pull side clearance.	18 inches minimum	#N/A	1-High	<a href="#">No Photo</a>	Nov 2014	23		
102	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3-Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603.213	1-High	<a href="#">No Photo</a>	Jan 2015	25		
104	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Coat Hook		Height		67 inches	No	Coat hook is mounted too high.	3-Restrooms	Lower the coat hook.	48 inches maximum	603.603.4, 604.8.3, 803.5	3-Low	<a href="#">158</a>	Jan 2014	13		
105	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Ambulatory Compartment		Clear opening		42 inches	No	Ambulatory stall is too wide.	3-Restrooms	Reconfigure stall so that it is at the correct width.	35-37 inches	603.604.8.2	1-High	<a href="#">156</a>	Jan 2015	25		
106	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Grab Bar	Left	Clearance, to wall		3 inches	No	Space between the wall and grab bar is too much	3-Restrooms	Replace grab bars with new ones that have the correct spacing.	1.5 inches maximum	603.609	3-Low	<a href="#">157</a>	Jan 2014	13		
109	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		0 inches	No	Toilet paper dispenser is not mounted at the correct location.	3-Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603.604.7, 604.9.6, 606.1	3-Low	<a href="#">157</a>	Jan 2014	13		
110	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Grab Bar		Dimension, between	Toilet Paper Dispenser and Grab Bar	5.5 inches	No	Dispenser is located above the grab bar.	3-Restrooms	Relocate the dispenser so that it does not interfere with the grab bar.	12 inches minimum between the dispenser and grab bar	603.609	3-Low	<a href="#">157</a>	Jan 2014	13		
111	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Water Closet		Height, seat		20.5 inches	No	Toilet seat is too high	3-Restrooms	Adjust or modify the toilet so the seat height is at the required accessible height.	17-19 inches	603.213.3.2, 604.2, 604.3, 604.4, 604.6	2-Moderate	<a href="#">156</a>	Jul 2014	19		
112	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Protrusion		Dimension, protruding	Lavatory	27 inches	No	Lavatory protrudes into the path of travel.	3-Restrooms	Remove sink or install a new sink that isn't a protruding object	4 inches maximum protrusion in path of travel at 27 inches high minimum	603.307.2, 307.3	2-Moderate	<a href="#">161</a>	Jul 2014	19		
113	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Mirror		Height, bottom		48 inches	No	The bottom of the mirror is mounted too high	3-Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603.603.3	3-Low	<a href="#">152</a>	Jan 2014	13		
114	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Dispenser	Soap	Height		49 inches	No	Dispenser is mounted too high.	3-Restrooms	Relocate the dispenser to the correct height.	48 inches maximum	603.604.7, 604.9.6, 606.1	3-Low	<a href="#">152</a>	Jan 2014	13		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
115	Barnett Arena	Interior	Owned	Restroom	Ground Level Women's West	1-Public Unsupervised	Other Element	Baby Change Station	Height, top		35 inches	No	Baby change table is mounted too high when lowered.	3-Restrooms	The top of the work surface should be 28 inches minimum and 34 inches maximum.	28-34 inches	#N/A	3-Low	<a href="#">155</a>	Jan 2014	13		
116	Barnett Arena	Interior	Owned	Concessions	#1 Down West Concession Stand	1-Public Unsupervised	Counter		Height		42 inches	No	Height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	2-Services	Provide at least a 36" wide portion at the compliant height.	36 inches maximum	904	2-Moderate	<a href="#">167</a>	May 2014	17		
117	Barnett Arena	Interior	Owned	Hallway	Between Dressing Rooms A & B	1-Public Unsupervised	Protrusion	Drinking Fountain	Dimension, protruding		7.5 inches	No	Fountain is a Protruding Object.	2-Services	Make sure that the fountain is not a Protruding Object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">169</a>	May 2014	17		
118	Barnett Arena	Interior	Owned	Hallway	Between Dressing Rooms A & B	1-Public Unsupervised	Drinking Fountain		Hardware type		Twist	No	Door knob requires twisting of the wrist.	4-Other	Install lever type door hardware.		602	3-Low	<a href="#">170</a>	Mar 2014	15		
120	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room A	1-Public Unsupervised	Signage		Braille?		No	No	Signage does not provide braille.	4-Other	Install signage with raised letters and braille.		222, 703	3-Low	<a href="#">171</a>	Mar 2014	15		
121	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room A	1-Public Unsupervised	Signage		Tactile letters?		No	No	Tactile signage is not provided.	2-Services	Install room identification signage that includes raised characters and Braille on latch side of door.		222, 703	3-Low	<a href="#">171</a>	Nov 2013	11		
122	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room A	1-Public Unsupervised	Door Gate		Clear opening		27 inches	No	Door opening is not wide enough.	2-Services	Reframe doorway to provide widest possible clear opening width, up to 32 inches. Offset hinges may be used to facilitate process.	32 inches minimum	222, 404	1-High	<a href="#">180</a>	Nov 2014	23		
123	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room A	1-Public Unsupervised	Door Gate		Clearance, parallel	Pull Side	2 inches	No	Clearance on the pull side of the door is insufficient.	2-Services	Install doors so that they have the correct pull side clearance.	18 inches minimum	222, 404	1-High	<a href="#">180</a>	Nov 2014	23		
124	Barnett Arena	Interior	Owned	Locker Room	Dressing Room A	1-Public Unsupervised	Shower Compartment		Height, threshold		5 inches	No	Threshold is too high.	2-Services	Thresholds in roll-in type shower compartments shall be .5 inch high maximum.	5 inch maximum	222, 803, 608	1-High	<a href="#">173</a>	Nov 2014	23		
125	Barnett Arena	Interior	Owned	Locker Room	Dressing Room A	1-Public Unsupervised	Shower Compartment		Hand spray unit?		No	No	Showers do not provide a handheld spray unit.	4-Other	Install an accessible shower with a handheld unit that is mounted 48 inches maximum above the finished floor with a 59 inch long minimum hose.		222, 803, 608	3-Low	<a href="#">175</a>	Mar 2014	15		
126	Barnett Arena	Interior	Owned	Locker Room	Dressing Room A	1-Public Unsupervised	Shower Compartment		Shower type	Gang Shower, with no grab bars	No	No	No accessible shower provided.	3-Restrooms	Provide an accessible roll-in or transfer type shower compartment.		222, 803, 608	1-High	<a href="#">184</a>	Jan 2015	25		
128	Barnett Arena	Interior	Owned	Restroom	Dressing Room A Typical for all Dressing Rooms	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3-Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603, 213	1-High	<a href="#">186</a>	Jan 2015	25		
130	Barnett Arena	Interior	Owned	Restroom	Dressing Room A Typical for all Dressing Rooms	1-Public Unsupervised	Door Gate		Clear opening		27 inches	No	Door opening is not wide enough.	2-Services	Reframe doorway to provide widest possible clear opening width, up to 32 inches. Offset hinges may be used to facilitate process.	32 inches minimum	#N/A	1-High	<a href="#">192</a>	Nov 2014	23		
131	Barnett Arena	Interior	Owned	Restroom	Dressing Room A Typical for all Dressing Rooms	1-Public Unsupervised	Water Closet		Dimension, sidewall		15.5 inches	No	Toilet is located too far away from the side wall on the narrow side.	3-Restrooms	Relocate the toilet so that it is within the required distance from the side wall.	16-18 inches	603, 213.2, 604.2, 604.3, 604.4, 604.6	1-High	<a href="#">201</a>	Jan 2015	25		
132	Barnett Arena	Interior	Owned	Restroom	Dressing Room A Typical for all Dressing Rooms	1-Public Unsupervised	Water Closet		Height, seat		15.5 inches	No	Toilet seat is too low	3-Restrooms	Adjust or modify the toilet so the seat height is at the required accessible height.	17-19 inches	603, 213.2, 604.2, 604.3, 604.4, 604.6	2-Moderate	<a href="#">201</a>	Jul 2014	19		
133	Barnett Arena	Interior	Owned	Restroom	Dressing Room A Typical for all Dressing Rooms	1-Public Unsupervised	Lavatory Sink		Control access		Twist	No	Sink hardware is not accessible.	3-Restrooms	Install lever type hardware.		603, 606	3-Low	<a href="#">199</a>	Jan 2014	13		
134	Barnett Arena	Interior	Owned	Restroom	Dressing Room A Typical for all Dressing Rooms	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		No	No	Supply lines/drain are not wrapped.	3-Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		603, 606	3-Low	<a href="#">199</a>	Jan 2014	13		
135	Barnett Arena	Interior	Owned	Restroom	Dressing Room A Typical for all Dressing Rooms	1-Public Unsupervised	Mirror		Height, bottom		46.5 inches	No	The bottom of the mirror is mounted too high	3-Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603, 603.3	3-Low	<a href="#">200</a>	Jan 2014	13		
136	Barnett Arena	Interior	Owned	Restroom	Dressing Room A Typical for all Dressing Rooms	1-Public Unsupervised	Toilet Compartment		Door swing direction		In	No	Compartment door swings into the clear floor of the toilet compartment.	3-Restrooms	Change the door swing of the door.		603, 604.8.1	3-Low	<a href="#">203</a>	Jan 2014	13		
137	Barnett Arena	Interior	Owned	Restroom	Dressing Room A Typical for all Dressing Rooms	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		25 inches at 8 inches in	No	Insufficient knee clearance is provided.	3-Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603, 606	2-Moderate	<a href="#">199</a>	Jul 2014	19		
138	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room B	1-Public Unsupervised	Signage		Braille?		No	No	Signage does not provide braille.	4-Other	Install signage with raised letters and braille.		222, 703	3-Low	<a href="#">179</a>	Mar 2014	15		
139	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room B	1-Public Unsupervised	Signage		Tactile letters?		No	No	Tactile signage is not provided.	2-Services	Install room identification signage that includes raised characters and Braille on latch side of door.		222, 703	3-Low	<a href="#">179</a>	Nov 2013	11		
140	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room B	1-Public Unsupervised	Door Gate		Clear opening		27 inches	No	Door opening is not wide enough.	2-Services	Reframe doorway to provide widest possible clear opening width, up to 32 inches. Offset hinges may be used to facilitate process.	32 inches minimum	222, 404	1-High	<a href="#">No Photo</a>	Nov 2014	23		
141	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room B	1-Public Unsupervised	Door Gate		Clearance, parallel	Pull Side	2 inches	No	Clearance on the pull side of the door is insufficient.	2-Services	Install doors so that they have the correct pull side clearance.	18 inches minimum	222, 404	1-High	<a href="#">No Photo</a>	Nov 2014	23		
142	Barnett Arena	Interior	Owned	Locker Room	Dressing Room B	1-Public Unsupervised	Shower Compartment		Height, threshold		5 inches	No	Threshold is too high.	2-Services	Thresholds in roll-in type shower compartments shall be .5 inch high maximum.	5 inch maximum	222, 803, 608	1-High	<a href="#">109</a>	Nov 2014	23		
143	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room B	1-Public Unsupervised	Shower Compartment		Hand spray unit?		No	No	Showers do not provide a handheld spray unit.	4-Other	Install an accessible shower with a handheld unit that is mounted 48 inches maximum above the finished floor with a 59 inch long minimum hose.		222, 608	3-Low	<a href="#">106</a>	Mar 2014	15		
144	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room B	1-Public Unsupervised	Shower Compartment		Shower type	Gang Shower, with no grab bars	No	No	No accessible shower provided.	3-Restrooms	Provide an accessible roll-in or transfer type shower compartment.		222, 608	1-High	<a href="#">106</a>	Jan 2015	25		
145	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room C	1-Public Unsupervised	Signage		Braille?		No	No	Signage does not provide braille.	4-Other	Install signage with raised letters and braille.		222, 703	3-Low	<a href="#">191</a>	Mar 2014	15		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
146	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room C	1-Public Unsupervised	Signage		Tactile letters?		No	No	Tactile signage is not provided.	2-Service	Install room identification signage that includes raised characters and Braille on latch side of door.		222, 703	3-Low	<a href="#">191</a>	Nov 2013	11		
147	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room C	1-Public Unsupervised	Door Gate		Clear opening		27 inches	No	Door opening is not wide enough.	2-Service	Reframe doorway to provide widest possible clear opening width, up to 32 inches. Offset hinges may be used to facilitate process.	32 inches minimum	222, 404	1-High	<a href="#">192</a>	Nov 2014	23		
148	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room C	1-Public Unsupervised	Door Gate		Clearance, parallel	Pull Side	2 inches	No	Clearance on the pull side of the door is insufficient.	2-Service	Install doors so that they have the correct pull side clearance.	18 inches minimum	222, 404	1-High	<a href="#">192</a>	Nov 2014	23		
149	Barnett Arena	Interior	Owned	Locker Room	Dressing Room C	1-Public Unsupervised	Shower Compartment		Height, threshold		5 inches	No	Threshold is too high.	2-Service	Thresholds in roll-in type shower compartments shall be .5 inch high maximum.	5 inch maximum	222, 803, 608	1-High	<a href="#">195</a>	Nov 2014	23		
150	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room C	1-Public Unsupervised	Shower Compartment		Hand spray unit?		No	No	Showers do not provide a handheld spray unit.	4-Other	Install an accessible shower with a handheld unit that is mounted 48 inches maximum above the finished floor with a 59 inch long minimum hose.		222, 608	3-Low	<a href="#">196</a>	Mar 2014	15		
151	Barnett Arena	Interior	Owned	Dressing Room	Dressing Room C	1-Public Unsupervised	Shower Compartment		Shower type			No	No accessible shower provided.	3-Restrooms	Provide an accessible roll-in or transfer type shower compartment.		222, 608	1-High	<a href="#">196</a>	Jan 2015	25		
152	Barnett Arena	Interior	Owned	Hallway	Ground Level West Side South of Restrooms	1-Public Unsupervised	Protrusion	Drinking Fountain	Dimension, protruding		21 inches at 29 inches high	No	Fountain is a Protruding Object.	2-Service	Make sure that the fountain is not a Protruding Object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">204</a>	May 2014	17		
153	Barnett Arena	Interior	Owned	Hallway	Ground Level West Side South of Restrooms	1-Public Unsupervised	Drinking Fountain		Height		38.5 inches	No	Drinking fountain spout height is too high.	2-Service	Replace the existing fountain with a highflow fountain. The low fountain spout height must be 36 inches minimum and the high fountain spout height must be 38 inches to 43 inches.		602	2-Moderate	<a href="#">204</a>	May 2014	17		
155	Barnett Arena	Interior	Owned	Elevator		1-Public Unsupervised	Hoistway Sign		Both jambs?		Neither Side	No	Signage is not provided on either hoistway.	2-Service	Install signage with raised letters and braille on both hoistways of the elevator indicating the current location.		407, 407.2, 3	3-Low	<a href="#">211</a>	Nov 2013	11		
156	Barnett Arena	Interior	Owned	Elevator		1-Public Unsupervised	Hall Signal		Audible signal?		No	No	No audible or visual signal is provided for the elevator.	2-Service	Contact an licensed elevator repair company to provide necessary repairs.		407, 407.2, 2	2-Moderate	<a href="#">211</a>	May 2014	17		
157	Barnett Arena	Interior	Owned	Elevator		1-Public Unsupervised	Emergency Communications		Provided?		No	No	No emergency communications provided in the elevator.	2-Service	Contact an licensed elevator repair company to provide necessary repairs.		407, 407.9, 2	2-Moderate	<a href="#">209</a>	May 2014	17		
158	Barnett Arena	Interior	Owned	Elevator		1-Public Unsupervised	Elevator Door		Closing speed		5 second reopening time	No	Door reopening device does not stay open for a minimum of 20 seconds.	2-Service	Contact an licensed elevator repair company to provide necessary repairs.		407, 407.3, 2	2-Moderate	<a href="#">205</a>	May 2014	17		
159	Barnett Arena	Interior	Owned	Elevator		1-Public Unsupervised	Car Controls		Braille?		No	No	Signage does not provide braille.	4-Other	Install signage with raised letters and braille.		407, 407.6, 3	3-Low	<a href="#">210</a>	Mar 2014	15		
160	Barnett Arena	Interior	Owned	Elevator		1-Public Unsupervised	Car Controls		Star?		No	No	There is no star provided on the car controls indicating the main floor.	2-Service	Provide a tactile star to the left of the 1st floor button.		407, 407.6, 3	3-Low	<a href="#">210</a>	Nov 2013	11		
161	Barnett Arena	Interior	Owned	Elevator		1-Public Unsupervised	Car Controls		Tactile?		No	No	There are no tactile characters provided beside the car controls.	2-Service	Provide tactile characters to the left of the car controls.		407, 407.6, 3	3-Low	<a href="#">210</a>	Nov 2013	11		
162	Barnett Arena	Interior	Owned	Stairway	Typical Stairway	1-Public Unsupervised	Handrail		Cross section dimension, maximum		2.5 inches	No	Diameter of the handrails are too wide	4-Other	Replace handrails with new ones that have the correct diameter.	1.25 inches minimum and 2 inches maximum	210, 216.4, 504, 505	2-Moderate	<a href="#">211</a>	Sep 2014	21		
163	Barnett Arena	Interior	Owned	Stairway	Typical Stairway	1-Public Unsupervised	Handrail		Height, top		32 inches	No	Handrails are too low	4-Other	Replace handrails and install new ones at the correct height.	34-38 inches	210, 216.4, 504, 505	2-Moderate	<a href="#">211</a>	Sep 2014	21		
164	Barnett Arena	Interior	Owned	Stairway	Typical Stairway	1-Public Unsupervised	Tread		Depth		10.5 inches	No	Stair treads are not deep enough.	2-Service	Stair treads shall be 11 inches deep minimum.	11 inches minimum	210, 216.4, 504, 504.2, 502.4, 502.5, 502.7	1-High	<a href="#">211</a>	Nov 2014	23		
165	Barnett Arena	Interior	Owned	Stairway	Typical Stairway at Mezzanine Level Seating	1-Public Unsupervised	Handrail		Both sides?		Only one side	No	Handrails are not provided on both sides	4-Other	Provide handrails on both side and ensure they are installed at the correct height.	Both sides	210, 216.4, 504, 505	2-Moderate	<a href="#">224</a>	Sep 2014	21		
166	Barnett Arena	Interior	Owned	Stairway	Typical Stairway at Mezzanine Level Seating	1-Public Unsupervised	Riser		Uniform risers?		No	No	Risers are not uniform.	2-Service	Stair risers must be uniform heights, 4 inches minimum and 7 inches maximum.		210, 216.4, 504, 504.2, 504.3	1-High	<a href="#">224</a>	Nov 2014	23		
167	Barnett Arena	Interior	Owned	Walkway	From Elevator to Accessible Seating on Mezzanine Level	1-Public Unsupervised	Ramp		Slope, running		9.40%	No	Slope is too steep.	4-Other	Rebuild ramp with compliant running slope, cross slope, and landings.	8.33%	405	1-High	<a href="#">238</a>	Mar 2015	27		
168	Barnett Arena	Interior	Owned	Walkway	To Crows Nest	1-Public Unsupervised	Walking Surface		Surface material			No	No accessible means of entry provided to the crow's nest.	4-Other	Provide an accessible means of entry such as a LULA or platform lift		403	1-High	<a href="#">234</a>	Mar 2015	27		
169	Barnett Arena	Interior	Owned	Stairway	To Crows Nest	1-Public Unsupervised	Riser		Open?		Yes	No	Risers are open.	2-Service	Provide stairs that do not have open risers.		210, 216.4, 504, 504.2, 504.3	1-High	<a href="#">234</a>	Nov 2014	23		
170	Barnett Arena	Interior	Owned	Walkway	Egress Doors by Lower Level East Restrooms	1-Public Unsupervised	Door Gate		Closing force		>7 lbs	No	Force to open the door is greater than the maximum force allowed.	2-Service	Adjust the door closer to the required amount of force allowed.	5 lbs maximum	404	3-Low	<a href="#">No Photo</a>	Nov 2013	11		
171	Barnett Arena	Interior	Owned	Concessions	#4 Down East Concessions	1-Public Unsupervised	Counter		Height		42 inches	No	Height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	2-Service	Provide at least a 36" wide portion at the compliant height.	36 inches maximum	904	2-Moderate	<a href="#">237</a>	May 2014	17		
172	Barnett Arena	Interior	Owned	Dressing Room	Dressing Rooms E & F	1-Public Unsupervised	Signage		Location		On Door	No	Signage located on the door.	2-Service	Relocate the sign to the latch side of the door at the correct height.		222, 703	3-Low	<a href="#">No Photo</a>	Nov 2013	11		
173	Barnett Arena	Interior	Owned	Dressing Room	Dressing Rooms E & F	1-Public Unsupervised	Signage		Braille?		No	No	Signage does not provide braille.	4-Other	Install signage with raised letters and braille.		222, 703	3-Low	<a href="#">No Photo</a>	Mar 2014	15		
174	Barnett Arena	Interior	Owned	Dressing Room	Dressing Rooms E & F	1-Public Unsupervised	Signage		Tactile letters?		No	No	Tactile signage is not provided.	2-Service	Install room identification signage that includes raised characters and Braille on latch side of door.		222, 703	3-Low	<a href="#">No Photo</a>	Nov 2013	11		
175	Barnett Arena	Interior	Owned	Locker Room	Dressing Rooms E & F	1-Public Unsupervised	Shower Compartment		Height, threshold		5 inches	No	Threshold is too high.	2-Service	Thresholds in roll-in type shower compartments shall be .5 inch high maximum.	5 inch maximum	222, 803, 608	1-High	<a href="#">110</a>	Nov 2014	23		
176	Barnett Arena	Interior	Owned	Locker Room	Dressing Rooms E & F	1-Public Unsupervised	Shower Compartment		Hand spray unit?		No	No	Showers do not provide a handheld spray unit.	4-Other	Install an accessible shower with a handheld unit that is mounted 48 inches maximum above the finished floor with a 59 inch long minimum hose.		222, 803, 608	3-Low	<a href="#">124</a>	Mar 2014	15		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
177	Barnett Arena	Interior	Owned	Locker Room	Dressing Rooms E & F	1-Public Unsupervised	Shower Compartment		Shower type		Gang Shower, with no grab bars	No	No accessible shower provided.	3-Restrooms	Provide an accessible roll-in or transfer type shower compartment.		222, 803, 608	1-High	<a href="#">124</a>	Jan 2015	25		
178	Barnett Arena	Interior	Owned	Locker Room	Dressing Rooms E & F	1-Public Unsupervised	Coat Hook		Height		68 inches	No	Coat hook is mounted too high.	3-Restrooms	Lower the coat hook.	48 inches maximum	222, 803, 603.4, 604.8.3, 803.5	3-Low	<a href="#">119</a>	Jan 2014	13		
179	Barnett Arena	Interior	Owned	Locker Room	Dressing Rooms E & F	1-Public Unsupervised	Dispenser	Soap in Shower	Height		56 inches	No	Dispenser is mounted too high.	3-Restrooms	Relocate the dispenser to the correct height.	48 inches maximum	222, 803, 604.7, 604.9.6, 606.1	3-Low	<a href="#">107</a>	Jan 2014	13		
180	Barnett Arena	Interior	Owned	Dressing Room	Dressing Rooms E & F	1-Public Unsupervised	Door Gate		Clearance, parallel	Pull Side	2 inches	No	Clearance on the pull side of the door is insufficient.	2-Services	Install doors so that they have the correct pull side clearance.	18 inches minimum	222, 404	1-High	<a href="#">125</a>	Nov 2014	23		
181	Barnett Arena	Interior	Owned	Hallway	Between Dressing Rooms E & F	1-Public Unsupervised	Protrusion	Drinking Fountain	Dimension, protruding		7 inches	No	Fountain is a Protruding Object.	2-Services	Make sure that the fountain is not a Protruding Object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">128</a>	May 2014	17		
182	Barnett Arena	Interior	Owned	Hallway	Between Dressing Rooms E & F	1-Public Unsupervised	Drinking Fountain		Hardware type		Twist	No	Door knob requires twisting of the wrist.	4-Other	Install level type door hardware.		602	3-Low	<a href="#">128</a>	Mar 2014	15		
184	Barnett Arena	Interior	Owned	Hallway	South of #1 East Concessions	1-Public Unsupervised	Protrusion	Drinking Fountain	Dimension, protruding		21 inches	No	Fountain is a Protruding Object.	2-Services	Make sure that the fountain is not a Protruding Object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">129</a>	May 2014	17		
186	Barnett Arena	Interior	Owned	Hallway	South of #1 East Concessions	1-Public Unsupervised	Drinking Fountain		Height		39 inches	No	Drinking fountain spout height is too high.	2-Services	Replace the existing fountain with a high/low fountain. The low fountain spout height must be 36 inches minimum and the high fountain spout height must be 38 inches to 43 inches.		602	2-Moderate	<a href="#">129</a>	May 2014	17		
187	Barnett Arena	Interior	Owned	Hallway	South of #1 East Concessions	1-Public Unsupervised	Protrusion	AED Box	Dimension, protruding		6 inches	No	AED box is a Protruding Object.	2-Services	Make sure that the AED box is not a Protruding Object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	3-Low	<a href="#">130</a>	Nov 2013	11		
189	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3-Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603, 213	1-High	<a href="#">No Photo</a>	Jan 2015	25		
192	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Coat Hook		Height		67 inches	No	Coat hook is mounted too high.	3-Restrooms	Lower the coat hook.	48 inches maximum	603, 603.4, 604.8.3, 803.5	3-Low	<a href="#">143</a>	Jan 2014	13		
193	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Ambulatory Compartment		Clear opening		42 inches	No	Ambulatory stall is too wide.	3-Restrooms	Reconfigure stall so that it is at the correct width.	35-37 inches	603, 604.8.2	1-High	<a href="#">140</a>	Jan 2015	25		
194	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Grab Bar		Clearance, to wall		3 inches	No	Space between the wall and grab bar is too much.	3-Restrooms	Replace grab bars with new ones that have the correct spacing.	1.5 inches maximum	603, 609	3-Low	<a href="#">140</a>	Jan 2014	13		
195	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Grab Bar		Dimension, between	Toilet Paper Dispenser and Grab Bar	3.5 inches	No	Dispenser is located above the grab bar.	3-Restrooms	Relocate the dispenser so that it does not interfere with the grab bar.	12 inches minimum between the dispenser and grab bar	603, 609	3-Low	<a href="#">141</a>	Jan 2014	13		
196	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Grab Bar	Right	Dimension, end to wall		13 inches	No	Side wall grab bar is located to far away from the back wall.	3-Restrooms	Move the grab bar.	12 inches maximum	603, 609	3-Low	<a href="#">142</a>	Jan 2014	13		
197	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Grab Bar	Left	Dimension, between	From Front of Grab Bar to Back Wall	52 inches	No	The side grab bar is not located in the correct location.	3-Restrooms	The side wall grab shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603, 609	3-Low	<a href="#">141</a>	Jan 2014	13		
198	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		1 inches	No	Toilet paper dispenser is not mounted at the correct location.	3-Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603, 604.7, 604.9.6, 606.1	3-Low	<a href="#">140</a>	Jan 2014	13		
199	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Urinal		Depth		13 inches	No	Urinal is not deep enough.	3-Restrooms	Install a urinal with the correct depth.	13.5 inches minimum	603, 605	2-Moderate	<a href="#">134</a>	Jul 2014	19		
200	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Urinal		Height, rim		20.5 inches	No	Urinal rim is too high.	3-Restrooms	Replace or remount the urinal to the correct height.	17 inches maximum	603, 605	2-Moderate	<a href="#">134</a>	Jul 2014	19		
201	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Urinal		Height, flush control	Automatic with manual flush provided	52 inches	No	Flush control is not within reach range.	3-Restrooms	Relocate flush control to 48 inches maximum.	15 inches minimum - 48 inches maximum	603, 605	2-Moderate	<a href="#">134</a>	Jul 2014	19		
202	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		No	No	Supply lines/drain are not wrapped.	3-Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		603, 606	3-Low	<a href="#">137</a>	Jan 2014	13		
203	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Mirror		Height, bottom		41 inches	No	The bottom of the mirror is mounted too high.	3-Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603, 603.3	3-Low	<a href="#">137</a>	Jan 2014	13		
204	Barnett Arena	Interior	Owned	Restroom	Ground Level Men's West	1-Public Unsupervised	Dispenser	Soap	Height		52 inches	No	Dispenser is mounted too high.	3-Restrooms	Relocate the dispenser to the correct height.	48 inches maximum	603, 604.7, 604.9.6, 606.1	3-Low	<a href="#">137</a>	Jan 2014	13		
205	Barnett Arena	Interior	Owned	Concessions	Mezzanine Level East	1-Public Unsupervised	Counter		Height		42 inches	No	Height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	2-Services	Provide at least a 36" wide portion at the compliant height.	36 inches maximum	904	2-Moderate	<a href="#">167</a>	May 2014	17		
206	Barnett Arena	Interior	Owned	Hallway	Mezzanine Level East	1-Public Unsupervised	Protrusion	Tables	Dimension, protruding		21 inches	No	Tables at concession area protrudes into the path of travel.	2-Services	Remove table and install a table that is not a protruding object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">236</a>	May 2014	17		
207	Barnett Arena	Interior	Owned	Concessions	Mezzanine Level East	1-Public Unsupervised	Counter	Tables	Height		41 inches	No	Height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	2-Services	Provide at least a 36" wide portion at the compliant height.	36 inches maximum	904	2-Moderate	<a href="#">235</a>	May 2014	17		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
208	Barnett Arena	Interior	Owned	Hallway	Mezzanine Level East	1-Public Unsupervised	Drinking Fountain		Height		41 inches	No	Drinking fountain spout height is too high.	2- Services	Replace the existing fountain with a highflow fountain. The low fountain spout height must be 36 inches minimum and the high fountain spout height must be 38 inches to 43 inches.		602	2-Moderate	<a href="#">255</a>	May 2014	17		
209	Barnett Arena	Interior	Owned	Hallway	Mezzanine Level West	1-Public Unsupervised	Protrusion	Drinking Fountain	Dimension, protruding		12.5 inches	No	Fountain is a Protruding Object.	2- Services	Make sure that the fountain is not a Protruding Object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">No Photo</a>	May 2014	17		
210	Barnett Arena	Interior	Owned	Hallway	Mezzanine Level East	1-Public Unsupervised	Protrusion	Drinking Fountain	Dimension, protruding		12.5 inches	No	Fountain is a Protruding Object.	2- Services	Make sure that the fountain is not a Protruding Object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">No Photo</a>	May 2014	17		
211	Barnett Arena	Interior	Owned	Walkway	Typical Back of House Room	1-Public Unsupervised	Walking Surface	Shag Rug	Firm, stable, slip resistant		No	No	Rug is not attached and has a non-compliant pile height.	2- Services	Rugs must be securely attached and have a pile height of .5 inches maximum.		403	3-Low	<a href="#">250</a>	Nov 2013	11		
212	Barnett Arena	Interior	Owned	Break Room	Typical Back of House Room	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		24 inches	No	Insufficient knee clearance is provided.	3- Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	606	2-Moderate	<a href="#">250</a>	Jul 2014	19		
213	Barnett Arena	Interior	Owned	Break Room	Typical Back of House Room	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		No	No	Supply lines/drain are not wrapped.	3- Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		606	3-Low	<a href="#">250</a>	Jan 2014	13		
214	Barnett Arena	Interior	Owned	Restroom	Typical Back of House Room	1-Public Unsupervised	Water Closet		Dimension, sidewall		15 inches	No	Toilet is located too far away from the side wall on the narrow side.	3- Restrooms	Relocate the toilet so that it is within the required distance from the side wall.	16-18 inches	603, 213.3.2, 604.2, 604.3, 604.4, 604.6	1-High	<a href="#">249</a>	Jan 2015	25		
215	Barnett Arena	Interior	Owned	Restroom	Typical Back of House Room	1-Public Unsupervised	Water Closet		Clearance, parallel		Sink Beside	No	Toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	3- Restrooms	Relocate the toilet in a space which provides the required clearances.	42 inches minimum	603, 213.3.2, 604.2, 604.3, 604.4, 604.6	1-High	<a href="#">249</a>	Jan 2015	25		
216	Barnett Arena	Interior	Owned	Restroom	Typical Back of House Room	1-Public Unsupervised	Lavatory Sink		Other attribute		In Cabinet	No	Lavatory is located in a cabinet.	3- Restrooms	Provide a lavatory with the required knee clearance.		603, 606	2-Moderate	<a href="#">249</a>	Jul 2014	19		
217	Barnett Arena	Interior	Owned	Restroom	Typical Back of House Room	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3- Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603, 213	1-High	<a href="#">249</a>	Jan 2015	25		
218	Barnett Arena	Interior	Owned	Restroom	Typical Back of House Room	1-Public Unsupervised	Shower Compartment		Seat?		No	No	No seat provided for shower.	3- Restrooms	Shower does not contain the necessary clearance to be made into an accessible shower, if a transfer shower is installed include a folding seat.		603, 608	2-Moderate	<a href="#">255</a>	Jul 2014	19		
219	Barnett Arena	Interior	Owned	Restroom	Typical Back of House Room	1-Public Unsupervised	Shower Compartment		Shower type		Regular Shower not accessible	No	No accessible shower provided.	3- Restrooms	Provide an accessible roll-in or transfer type shower compartment.		603, 608	1-High	<a href="#">255</a>	Jan 2015	25		
220	Barnett Arena	Interior	Owned	Restroom	West Back of House Room	1-Public Unsupervised	Turning Space		Diameter		56 inches	No	Insufficient turning space inside the restroom.	3- Restrooms	Remodel the restroom or include signs that indicate where the accessible restroom is located.	60 inches minimum	603, 304	1-High	<a href="#">257</a>	Jan 2015	25		
221	Barnett Arena	Interior	Owned	Restroom	Typical Back of House Room	1-Public Unsupervised	Shower Compartment		Hand spray unit?		No	No	Showers do not provide a handheld spray unit.	4- Other	Install an accessible shower with a handheld unit that is mounted 48 inches maximum above the finished floor with a 59 inch long minimum hose.		603, 608	3-Low	<a href="#">256</a>	Mar 2014	15		
222	Barnett Arena	Interior	Owned	Restroom	Typical Back of House Room	1-Public Unsupervised	Shower Compartment		Dimension, side to side		34 inches	No	Shower is not wide enough to install a transfer shower.	3- Restrooms	Transfer shower must be 36 inches wide and 36 inches deep.		603, 608	1-High	<a href="#">255</a>	Jan 2015	25		
223	Barnett Arena	Interior	Owned	Restroom	Typical Back of House Room	1-Public Unsupervised	Door Gate		Hardware type		Knob	No	Door knob requires twisting of the wrist.	3- Restrooms	Install lever type door hardware.		#N/A	3-Low	<a href="#">No Photo</a>	Jan 2014	13		
224	Barnett Arena	Interior	Owned	Restroom	East Back of House Room	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		11 inches	No	Toilet paper dispenser is not mounted at the correct location.	3- Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603, 604.7, 604.9.6, 606.1	3-Low	<a href="#">257</a>	Jan 2014	13		
225	Barnett Arena	Interior	Owned	Restroom	Back of House Public Women's Restrooms	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3- Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603, 213	1-High	<a href="#">261</a>	Jan 2015	25		
226	Barnett Arena	Interior	Owned	Restroom	Back of House Public Women's Restrooms	1-Public Unsupervised	Mirror		Height, bottom		50 inches	No	The bottom of the mirror is mounted too high	3- Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603, 603.3	3-Low	<a href="#">263</a>	Jan 2014	13		
227	Barnett Arena	Interior	Owned	Restroom	Back of House Public Women's Restrooms	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		25 inches at 8 inches in	No	Insufficient knee clearance is provided.	3- Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603, 606	2-Moderate	<a href="#">262</a>	Jul 2014	19		
228	Barnett Arena	Interior	Owned	Restroom	Back of House Public Women's Restrooms	1-Public Unsupervised	Dispenser	Soap	Height		53 inches	No	Dispenser is mounted too high.	3- Restrooms	Relocate the dispenser to the correct height.	48 inches maximum	603, 604.7, 604.9.6, 606.1	3-Low	<a href="#">263</a>	Jan 2014	13		
229	Barnett Arena	Interior	Owned	Restroom	Back of House Public Women's Restrooms	1-Public Unsupervised	Dispenser	Feminine Products	Height		54 inches	No	Dispenser is mounted too high.	3- Restrooms	Relocate the dispenser to the correct height.	48 inches maximum	603, 604.7, 604.9.6, 606.1	3-Low	<a href="#">264</a>	Jan 2014	13		
230	Barnett Arena	Interior	Owned	Restroom	Back of House Public Women's Restrooms	1-Public Unsupervised	Door Gate		Clearance, perpendicular	Pull Side	41 inches	No	Clear space perpendicular to the door is not compliant.	3- Restrooms	Modify the doorway to provide a clearance of 60 inches minimum on the pull side of the door.	42 inches minimum	#N/A	1-High	<a href="#">265</a>	Jan 2015	25		
231	Barnett Arena	Interior	Owned	Restroom	Back of House Public Women's Restrooms	1-Public Unsupervised	Signage		Location		Accessible Signage not Provided by Door	No	Signage is not provided in the correct location.	3- Restrooms	Signage must be provided on the latch side of the door.		603, 703	3-Low	<a href="#">260</a>	Jan 2014	13		
232	Barnett Arena	Interior	Owned	Restroom	Back of House Public Women's Restrooms	1-Public Unsupervised	Door Gate		Hardware type		Knob	No	Door knob requires twisting of the wrist.	3- Restrooms	Install lever type door hardware.		#N/A	3-Low	<a href="#">265</a>	Jan 2014	13		



Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
233	Barnett Arena	Interior	Owned	Hallway	Back of House between Public Restrooms	1-Public Unsupervised	Protrusion	Drinking Fountain	Dimension, protruding		12 inches	No	Fountain is a Protruding Object.	2-Services	Make sure that the fountain is not a Protruding Object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">266</a>	May 2014	17		
234	Barnett Arena	Interior	Owned	Hallway	Back of House between Public Restrooms	1-Public Unsupervised	Drinking Fountain		Height		41 inches	No	Drinking fountain spout height is too high.	2-Services	Replace the existing fountain with a highflow fountain. The low fountain spout height must be 36 inches minimum and the high fountain spout height must be 38 inches to 43 inches.		602	2-Moderate	<a href="#">266</a>	May 2014	17		
235	Barnett Arena	Interior	Owned	Restroom	Back of House Public Men's Restrooms	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3-Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603, 213	1-High	<a href="#">272</a>	Jan 2015	25		
236	Barnett Arena	Interior	Owned	Restroom	Back of House Public Men's Restrooms	1-Public Unsupervised	Mirror		Height, bottom		50 inches	No	The bottom of the mirror is mounted too high	3-Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603, 603.3	3-Low	<a href="#">271</a>	Jan 2014	13		
237	Barnett Arena	Interior	Owned	Restroom	Back of House Public Men's Restrooms	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		25 inches at 8 inches in	No	Insufficient knee clearance is provided.	3-Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603, 606	2-Moderate	<a href="#">270</a>	Jul 2014	19		
238	Barnett Arena	Interior	Owned	Restroom	Back of House Public Men's Restrooms	1-Public Unsupervised	Dispenser	Soap	Height		53 inches	No	Dispenser is mounted too high.	3-Restrooms	Relocate the dispenser to the correct height.	48 inches maximum	603, 604.7, 604.9.6, 606.1	3-Low	<a href="#">271</a>	Jan 2014	13		
239	Barnett Arena	Interior	Owned	Restroom	Back of House Public Men's Restrooms	1-Public Unsupervised	Door Gate		Clearance, perpendicular	Pull Side	41 inches	No	Clear space perpendicular to the door is not compliant.	3-Restrooms	Modify the doorway to provide a clearance of 60 inches minimum on the pull side of the door.	42 inches minimum	#N/A	1-High	<a href="#">268</a>	Jan 2015	25		
240	Barnett Arena	Interior	Owned	Restroom	Back of House Public Men's Restrooms	1-Public Unsupervised	Signage		Location		Accessible Signage not Provided by Door	No	Signage is not provided in the correct location.	3-Restrooms	Signage must be provided on the latch side of the door.		603, 703	3-Low	<a href="#">267</a>	Jan 2014	13		
241	Barnett Arena	Interior	Owned	Restroom	Back of House Public Men's Restrooms	1-Public Unsupervised	Door Gate		Hardware type		Knob	No	Door knob requires twisting of the wrist.	3-Restrooms	Install lever type door hardware.		#N/A	3-Low	<a href="#">268</a>	Jan 2014	13		
244	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3-Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603, 213	1-High	<a href="#">No Photo</a>	Jan 2015	25		
246	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Ambulatory Compartment		Door swing direction		In	No	Compartment door swings into the clear floor of the toilet compartment.	3-Restrooms	Change the door swing of the door.		603, 604.8.2	3-Low	<a href="#">281</a>	Jan 2014	13		
247	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Ambulatory Compartment		Self-closing?		No	No	Toilet compartment door does not have self-closing hinges.	3-Restrooms	Install self-closing hinges on the toilet compartment door.		603, 604.8.2	3-Low	<a href="#">281</a>	Jan 2014	13		
248	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Ambulatory Compartment		Clear opening		37.5 inches	No	Ambulatory stall is too wide.	3-Restrooms	Reconfigure stall so that it is at the correct width.	35-37 inches	603, 604.8.2	1-High	<a href="#">282</a>	Jan 2015	25		
249	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Grab Bar	Both	Dimension, between	From Front of Grab Bar to Back Wall	48 inches	No	The side grab bar is not located in the correct location	3-Restrooms	The side wall grab shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603, 609	3-Low	<a href="#">282</a>	Jan 2014	13		
250	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Grab Bar		Dimension, between	Toilet Paper Dispenser and Grab Bar	5 inches	No	Dispenser is located above the grab bar.	3-Restrooms	Relocate the dispenser so that it does not interfere with the grab bar.	12 inches minimum between the dispenser and grab bar	603, 609	3-Low	<a href="#">282</a>	Jan 2014	13		
251	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		1 inches	No	Toilet paper dispenser is not mounted at the correct location.	3-Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603, 604.7, 604.9.6, 606.1	3-Low	<a href="#">282</a>	Jan 2014	13		
252	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Water Closet		Height, seat		16 inches	No	Toilet seat is too low	3-Restrooms	Adjust or modify the toilet so the seat height is at the required accessible height.	17-19 inches	603, 213.3.2, 604.2, 604.3, 604.4, 604.6	2-Moderate	<a href="#">281</a>	Jul 2014	19		
253	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Coat Hook		Height		66.5 inches	No	Coat hook is mounted too high.	3-Restrooms	Lower the coat hook.	48 inches maximum	603, 603.4, 604.8.3, 803.5	3-Low	<a href="#">No Photo</a>	Jan 2014	13		
254	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Mirror		Height, bottom		46 inches	No	The bottom of the mirror is mounted too high	3-Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603, 603.3	3-Low	<a href="#">280</a>	Jan 2014	13		
255	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		26 inches	No	Insufficient knee clearance is provided.	3-Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603, 606	2-Moderate	<a href="#">284</a>	Jul 2014	19		
256	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Dispenser	Soap	Height		50 inches	No	Dispenser is mounted too high.	3-Restrooms	Relocate the dispenser to the correct height.	48 inches maximum	603, 604.7, 604.9.6, 606.1	3-Low	<a href="#">280</a>	Jan 2014	13		
257	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Other Element	Baby Change Station	Height, top		38.5 inches	No	Baby change table is mounted too high when lowered.	3-Restrooms	The top of the work surface should be 28 inches minimum and 34 inches maximum.	28-34 inches	#N/A	3-Low	<a href="#">277</a>	Jan 2014	13		
258	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Typical Restroom	1-Public Unsupervised	Signage	In/Out	Braille?		No	No	Signage does not provide braille.	4-Other	Install signage with raised letters and braille.		603, 703	3-Low	<a href="#">274</a>	Mar 2014	15		
259	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Typical Restroom	1-Public Unsupervised	Signage	In/Out	Tactile letters?		No	No	Tactile signage is not provided.	3-Restrooms	Install room identification signage that includes raised characters and Braille on latch side of door.		603, 703	3-Low	<a href="#">274</a>	Jan 2014	13		
261	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3-Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603, 213	1-High	<a href="#">No Photo</a>	Jan 2015	25		
263	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Grab Bar	Both	Dimension, between	From Front of Grab Bar to Back Wall	48 inches	No	The side grab bar is not located in the correct location	3-Restrooms	The side wall grab shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603, 609	3-Low		Jan 2014	13		
264	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Ambulatory Compartment		Self-closing?		No	No	Toilet compartment door does not have self-closing hinges.	3-Restrooms	Install self-closing hinges on the toilet compartment door.		603, 604.8.2	3-Low		Jan 2014	13		



Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
265	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Coat Hook		Height		66.5 inches	No	Coat hook is mounted too high.	3- Restrooms	Lower the coat hook.	48 inches maximum	603, 604.3, 604.8.3, 603.5	3-Low	No Photo	Jan 2014	13		
266	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Grab Bar		Dimension, between	Toilet Paper Dispenser and Grab Bar	5 inches	No	Dispenser is located above the grab bar.	3- Restrooms	Relocate the dispenser so that it does not interfere with the grab bar.	12 inches minimum between the dispenser and grab bar	603, 609	3-Low	No Photo	Jan 2014	13		
267	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		3 inches	No	Toilet paper dispenser is not mounted at the correct location.	3- Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603, 604.7, 604.9.6, 606.1	3-Low		Jan 2014	13		
268	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Water Closet		Height, seat		16 inches	No	Toilet seat is too low	3- Restrooms	Adjust or modify the toilet so the seat height is at the required accessible height.	17-19 inches	603, 213.3.2, 604.2, 604.3, 604.4, 604.6	2-Moderate		Jul 2014	19		
269	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		25 inches at 8 inches in	No	Insufficient knee clearance is provided.	3- Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603, 606	2-Moderate		Jul 2014	19		
270	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Other Element	Baby Change Station	Height, operable part		58 inches	No	Baby change table is out of reach range.	3- Restrooms	Lower the baby change table.	48 inches maximum to handle	#N/A	3-Low		Jan 2014	13		
271	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Other Element	Baby Change Station	Height, top		35 inches	No	Baby change table is mounted too high when lowered.	3- Restrooms	The top of the work surface should be 28 inches minimum and 34 inches maximum.	28-34 inches	#N/A	3-Low		Jan 2014	13		
272	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible Restroom East and West Typical	1-Public Unsupervised	Water Closet		Clearance, parallel	Wide Side	27 inches	No	Toilet is not located in a space which provides the minimum required distance from a fixture or the minimum required clear space from a wall at the wide side.	3- Restrooms	Relocate the toilet in a space which provides the required clearances.	42 inches minimum	603, 213.3.2, 604.2, 604.3, 604.4, 604.6	1-High	294	Jan 2015	25		
273	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible Restroom East and West Typical	1-Public Unsupervised	Protrusion	Hand Dryer	Dimension, protruding		5 inches	No	Hand dryer protrudes into the path of travel.	3- Restrooms	Relocate or remove hand dryer so that it is not in the path of travel.	4 inches maximum protrusion in path of travel at 27 inches high minimum	603, 307.2, 307.3	2-Moderate	294	Jul 2014	19		
274	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible Restroom East and West Typical	1-Public Unsupervised	Lavatory Sink		Clearance, perpendicular	Toilet Interrupts Clear Floor Space Perpendicular to Lavatory		No	Clear floor space perpendicular to the lavatory is not long enough.	3- Restrooms	Reconfigure the restroom to provided the required clear floor space for the lavatory.	48 inches minimum	603, 606	1-High	296	Jan 2015	25		
275	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 1st Right	1-Public Unsupervised	Turning Space		Diameter		59.5 inches	No	Insufficient turning space inside the restroom.	3- Restrooms	Remodel the restroom or include signs that indicate where the accessible restroom is located.	60 inches minimum	603, 304	1-High	294	Jan 2015	25		
276	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 1st Right	1-Public Unsupervised	Water Closet		Dimension, sidewall		18.5 inches	No	Toilet is located too far away from the side wall on the narrow side.	3- Restrooms	Relocate the toilet so that it is within the required distance from the side wall.	16-18 inches	603, 213.3.2, 604.2, 604.3, 604.4, 604.6	1-High	296	Jan 2015	25		
277	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 1st Right	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		10 inches	No	Toilet paper dispenser is not mounted at the correct location.	3- Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603, 604.7, 604.9.6, 606.1	3-Low	296	Jan 2014	13		
278	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 1st Right	1-Public Unsupervised	Grab Bar	Side Wall	Dimension, between	From Front of Grab Bar to Back Wall	48 inches	No	The side grab bar is not located in the correct location	3- Restrooms	The side wall grab shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603, 609	3-Low	293	Jan 2014	13		
279	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East and West Typical	1-Public Unsupervised	Grab Bar	Rear Wall	Dimension, between	Water Closet Centerline and End of Grab Bar	20 inches	No	Grab bar is not mounted in the correct location.	3- Restrooms	Rear grab bar should provide 12 inches minimum from the center line of the water closet on one side and 24 inches minimum from the center line of the water closet on the other side.	24 inches	603, 609	3-Low	293	Jan 2014	13		
280	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 2nd Right	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		12 inches	No	Toilet paper dispenser is not mounted at the correct location.	3- Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603, 604.7, 604.9.6, 606.1	3-Low	297	Jan 2014	13		
281	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 2nd Right	1-Public Unsupervised	Grab Bar	Side Wall	Dimension, between	From Front of Grab Bar to Back Wall	49 inches	No	The side grab bar is not located in the correct location	3- Restrooms	The side wall grab shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603, 609	3-Low	298	Jan 2014	13		
282	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 2nd Right	1-Public Unsupervised	Grab Bar		Clearance, to wall		2 inches	No	Space between the wall and grab bar is too much	3- Restrooms	Replace grab bars with new ones that have the correct spacing.	1.5 inches maximum	603, 609	3-Low	298	Jan 2014	13		
283	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 2nd Right	1-Public Unsupervised	Protrusion	Sprinkler	Height		78 inches	No	Sprinkler is located too low.	3- Restrooms	Contact fire marshal.	80 inches minimum	603, 307.2, 307.3	1-High	306	Jan 2015	25		
284	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 2nd Left	1-Public Unsupervised	Protrusion	Sprinkler	Height		78 inches	No	Sprinkler is located too low.	3- Restrooms	Contact fire marshal.	80 inches minimum	603, 307.2, 307.3	1-High	305	Jan 2015	25		
285	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 2nd Left	1-Public Unsupervised	Water Closet		Dimension, sidewall		18.5 inches	No	Toilet is located too far away from the side wall on the narrow side.	3- Restrooms	Relocate the toilet so that it is within the required distance from the side wall.	16-18 inches	603, 213.3.2, 604.2, 604.3, 604.4, 604.6	1-High	301	Jan 2015	25		
286	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 2nd Left	1-Public Unsupervised	Grab Bar	Side Wall	Dimension, between	From Front of Grab Bar to Back Wall	48 inches	No	The side grab bar is not located in the correct location	3- Restrooms	The side wall grab shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603, 609	3-Low	302	Jan 2014	13		
287	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 2nd Left	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		10 inches	No	Toilet paper dispenser is not mounted at the correct location.	3- Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603, 604.7, 604.9.6, 606.1	3-Low	302	Jan 2014	13		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
288	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 1st Left	1-Public Unsupervised	Grab Bar	Side Wall	Dimension, between	From Front of Grab Bar to Back Wall	48 inches	No	The side grab bar is not located in the correct location.	3- Restrooms	The side wall grab shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603.609	3-Low	<a href="#">297</a>	Jan 2014	13		
289	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible East 1st Left	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		12 inches	No	Toilet paper dispenser is not mounted at the correct location.	3- Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603.604.7, 604.9.6, 606.1	3-Low	<a href="#">298</a>	Jan 2014	13		
290	Barnett Arena	Interior	Owned	Lobby Reception	By South Entrance	1-Public Unsupervised	Counter	Ticket Counter	Dimension, knee clearance		4 inches in depth	No	Height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	2-Services	Provide at least a 36" wide portion at the compliant height.	36 inches maximum	904	2-Moderate	<a href="#">No Photo</a>	May 2014	17		
293	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Fixture Count		Number, accessible compartments		0	No	No wheelchair accessible toilet compartments in the restroom.	3- Restrooms	Rebuild or reconfigure the restroom, with a wheelchair accessible toilet compartment.	At least 1 wheelchair toilet compartment	603.213	1-High	<a href="#">No Photo</a>	Jan 2015	25		
295	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Grab Bar	Both	Dimension, between	From Front of Grab Bar to Back Wall	48 inches	No	The side grab bar is not located in the correct location.	3- Restrooms	The side wall grab shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603.609	3-Low	<a href="#">247</a>	Jan 2014	13		
296	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Water Closet		Height, seat		16 inches	No	Toilet seat is too low	3- Restrooms	Adjust or modify the toilet so the seat height is at the required accessible height.	17-19 inches	603.213.3.2, 604.2, 604.3, 604.4, 604.6	2-Moderate	<a href="#">247</a>	Jul 2014	19		
297	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Ambulatory Compartment		Self-closing?		No	No	Toilet compartment door does not have self-closing hinges.	3- Restrooms	Install self-closing hinges on the toilet compartment door.		603.604.8.2	3-Low	<a href="#">250</a>	Jan 2014	13		
298	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Coat Hook		Height		66 inches	No	Coat hook is mounted too high.	3- Restrooms	Lower the coat hook.	48 inches maximum	603.603.4, 604.8.3, 803.5	3-Low	<a href="#">249</a>	Jan 2014	13		
299	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		1.5 inches	No	Toilet paper dispenser is not mounted at the correct location.	3- Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603.604.7, 604.9.6, 606.1	3-Low	<a href="#">246</a>	Jan 2014	13		
300	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Grab Bar		Dimension, between	Toilet Paper Dispenser and Grab Bar	5.5 inches	No	Dispenser is located above the grab bar.	3- Restrooms	Relocate the dispenser so that it does not interfere with the grab bar.	12 inches minimum between the dispenser and grab bar	603.609	3-Low	<a href="#">246</a>	Jan 2014	13		
301	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Urinal		Height, flush control	Automatic with manual flush provided	52 inches	No	Flush control is not within reach range.	3- Restrooms	Relocate flush control to 48 inches maximum.		603.605	2-Moderate	<a href="#">251</a>	Jul 2014	19		
302	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		25 inches at 8 inches in	No	Insufficient knee clearance is provided.	3- Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603.606	2-Moderate	<a href="#">253</a>	Jul 2014	19		
303	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		One covered but not fully covered	No	Supply lines/drain are not wrapped.	3- Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		603.606	3-Low	<a href="#">253</a>	Jan 2014	13		
304	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		One covered but not fully covered	No	Supply lines/drain are not wrapped.	3- Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		603.606	3-Low	<a href="#">No Photo</a>	Jan 2014	13		
305	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		One covered but not fully covered	No	Supply lines/drain are not wrapped.	3- Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		603.606	3-Low	<a href="#">No Photo</a>	Jan 2014	13		
306	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Lavatory Sink		Drain Wrapped?		One covered but not fully covered	No	Supply lines/drain are not wrapped.	3- Restrooms	Wrap or insulate the drain and supply lines to protect against contact.		603.606	3-Low	<a href="#">No Photo</a>	Jan 2014	13		
307	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Mirror		Height, bottom		45.5 inches	No	The bottom of the mirror is mounted too high	3- Restrooms	Install mirror so that the bottom edge of the reflecting surface is 40 inches maximum above the finished floor.	40 inches maximum	603.603.3	3-Low	<a href="#">254</a>	Jan 2014	13		
308	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Signage	In/Out	Braille?		No Braille or raised letters	No	Signage does not provide braille or raised letters	4-Other	Install signage with raised letters and braille.		603.703	3-Low	<a href="#">274</a>	Mar 2014	15		
309	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Signage	In/Out	Braille?		No Braille or raised letters	No	Signage does not provide braille or raised letters	4-Other	Install signage with raised letters and braille.		603.703	3-Low	<a href="#">55</a>	Mar 2014	15		
310	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Signage	In/Out	Braille?		No Braille or raised letters	No	Signage does not provide braille or raised letters	4-Other	Install signage with raised letters and braille.		603.703	3-Low	<a href="#">No Photo</a>	Mar 2014	15		
311	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Signage	In/Out	Braille?		No Braille or raised letters	No	Signage does not provide braille or raised letters	4-Other	Install signage with raised letters and braille.		603.703	3-Low	<a href="#">No Photo</a>	Mar 2014	15		
312	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's West	1-Public Unsupervised	Signage	In/Out	Height, top		63 inches	No	The signage is mounted too high.	3- Restrooms	Tactile characters on signs shall be located 48 inches minimum above the finish floor or ground surface, measured from the baseline of the lowest tactile character and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile character.	48-60 inches	603.703	3-Low	<a href="#">274</a>	Jan 2014	13		
314	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's West	1-Public Unsupervised	Signage	In/Out	Height, top		63 inches	No	The signage is mounted too high.	3- Restrooms	Tactile characters on signs shall be located 48 inches minimum above the finish floor or ground surface, measured from the baseline of the lowest tactile character and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile character.	48-60 inches	603.703	3-Low	<a href="#">55</a>	Jan 2014	13		
315	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Women's East	1-Public Unsupervised	Signage	In/Out	Height, top		63 inches	No	The signage is mounted too high.	3- Restrooms	Tactile characters on signs shall be located 48 inches minimum above the finish floor or ground surface, measured from the baseline of the lowest tactile character and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile character.	48-60 inches	603.703	3-Low	<a href="#">No Photo</a>	Jan 2014	13		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
316	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Men's East	1-Public Unsupervised	Signage	In/Out	Height, top		63 inches	No	The signage is mounted too high.	3-Restrooms	Tactile characters on signs shall be located 48 inches minimum above the finish floor or ground surface, measured from the baseline of the lowest tactile character and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile character.	48-60 inches	603. 703	3-Low	<a href="#">No Photo</a>	Jan 2014	13		
317	Barnett Arena	Interior	Owned	Hallway	By Men's Restroom Mezzanine Level West	1-Public Unsupervised	Protrusion	Drinking Fountain	Dimension, protruding		12.5 inches at 32 inches up	No	Fountain is a Protruding Object.	2-Services	Make sure that the fountain is not a Protruding Object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">234</a>	May 2014	17		
318	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 1st Right	1-Public Unsupervised	Water Closet		Dimension, sidewall		18.5 inches	No	Toilet is located too far away from the side wall on the narrow side.	3-Restrooms	Relocate the toilet so that it is within the required distance from the side wall.	16-18 inches	603. 213.3.2, 604.2, 604.3, 604.4, 604.6	1-High	<a href="#">006</a>	Jan 2015	25		
319	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 1st Right	1-Public Unsupervised	Water Closet		Height, seat		19.5 inches	No	Toilet seat is too high	3-Restrooms	Adjust or modify the toilet so the seat height is at the required accessible height.	17-19 inches	603. 213.3.2, 604.2, 604.3, 604.4, 604.6	2-Moderate	<a href="#">006</a>	Jul 2014	19		
320	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 1st Right	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		11 inches	No	Toilet paper dispenser is not mounted at the correct location.	3-Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603. 604.7, 604.9.6, 606.1	3-Low	<a href="#">010</a>	Jan 2014	13		
321	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 1st Right	1-Public Unsupervised	Grab Bar		Clearance, to wall		1.75 inches	No	Space between the wall and grab bar is too much	3-Restrooms	Replace grab bars with new ones that have the correct spacing.	1.5 inches maximum	603. 609	3-Low	<a href="#">009</a>	Jan 2014	13		
322	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 1st Right	1-Public Unsupervised	Grab Bar	Side Wall	Dimension, between	From Front of Grab Bar to Back Wall	48 inches	No	The side grab bar is not located in the correct location	3-Restrooms	The side wall grab shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall.	54 inches from the rear wall	603. 609	3-Low	<a href="#">008</a>	Jan 2014	13		
323	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 1st Right	1-Public Unsupervised	Turning Space		Diameter		59.5 inches	No	Insufficient turning space inside the restroom.	3-Restrooms	Remodel the restroom or include signs that indicate where the accessible restroom is located.	60 inches minimum	603. 304	1-High	<a href="#">008</a>	Jan 2015	25		
324	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 2nd Right	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		27 inches at 7.25 inches depth	No	Insufficient knee clearance is provided.	3-Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603. 606	2-Moderate	<a href="#">009</a>	Jul 2014	19		
325	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 2nd Right	1-Public Unsupervised	Protrusion	Sprinkler	Height		78 inches	No	Sprinkler is located too low.	3-Restrooms	Contact fire marshal.	80 inches minimum	603. 307.2, 307.3	1-High	<a href="#">No Photo</a>	Jan 2015	25		
326	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 2nd Left	1-Public Unsupervised	Protrusion	Sprinkler	Height		78 inches	No	Sprinkler is located too low.	3-Restrooms	Contact fire marshal.	80 inches minimum	603. 307.2, 307.3	1-High	<a href="#">No Photo</a>	Jan 2015	25		
327	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West Exterior	1-Public Unsupervised	Lavatory Sink		Clearance, perpendicular		36.5 inches	No	Clear floor space perpendicular to the lavatory is not long enough.	3-Restrooms	Reconfigure the restroom to provided the required clear floor space for the lavatory.	48 inches minimum	603. 606	1-High	<a href="#">022</a>	Jan 2015	25		
328	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West Exterior	1-Public Unsupervised	Other Element	Baby Change Station	Height, top		36.5 inches	No	Baby change table is mounted too high when lowered.	3-Restrooms	The top of the work surface should be 28 inches minimum and 34 inches maximum.	28-34 inches	#N/A	3-Low	<a href="#">024</a>	Jan 2014	13		
329	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West Exterior	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		27 inches 7 inches depth	No	Insufficient knee clearance is provided.	3-Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603. 606	2-Moderate	<a href="#">022</a>	Jul 2014	19		
330	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West Exterior	1-Public Unsupervised	Other Element	Baby Change Station	Height, knee clearance		26.5 inches at 4.5 inches depth	No	Not enough knee clearance at the baby change table	3-Restrooms	Remount the baby changing table higher and this should give it plenty of knee clearance	27 inches minimum for knee clearance and must extend 8 inches deep	#N/A	2-Moderate	<a href="#">024</a>	Jul 2014	19		
331	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West Exterior	1-Public Unsupervised	Other Element	Baby Change Station	Clearance, perpendicular		36 inches	No	Not enough clear floor space at baby changing table	3-Restrooms	Reconfigure the baby changing table to ensure it has enough clear floor space	48 inches minimum	#N/A	1-High	<a href="#">025</a>	Jan 2015	25		
332	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 2nd Left	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		27 inches at 7.25 inches depth	No	Insufficient knee clearance is provided.	3-Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603. 606	2-Moderate	<a href="#">016</a>	Jul 2014	19		
333	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 1st Left	1-Public Unsupervised	Lavatory Sink		Dimension, knee clearance		26.75 inches	No	Insufficient knee clearance is provided.	3-Restrooms	Provide 27 inches of knee clearance, 8 inches deep from front edge.	27 inches high minimum and 8 inches deep minimum	603. 606	2-Moderate	<a href="#">017</a>	Jul 2014	19		
334	Barnett Arena	Interior	Owned	Restroom	Mezzanine Level Family/Accessible West 1st Left	1-Public Unsupervised	Dispenser	Toilet Paper	Dimension from water closet seat		10.5 inches	No	Toilet paper dispenser is not mounted at the correct location.	3-Restrooms	Move the toilet paper dispenser to the correct distance from the front of the toilet seat.	7-9 inches from the front of the toilet seat.	603. 604.7, 604.9.6, 606.1	3-Low	<a href="#">018</a>	Jan 2014	13		
335	Barnett Arena	Interior	Owned	Hallway	Mezzanine Level West by Concessions	1-Public Unsupervised	Protrusion	Tables	Dimension, protruding		21 inches	No	Tables at concession area protrudes into the path of travel.	2-Services	Remove table and install a table that is not a protruding object or install cane detection.	4 inches maximum protrusion in path of travel at 27 inches high minimum	307.2, 307.3	2-Moderate	<a href="#">No Photo</a>	May 2014	17		
336	Barnett Arena	Interior	Owned	Lobby Reception	Mezzanine Level West by Concessions	1-Public Unsupervised	Counter	Tables	Height		40 inches	No	Height of the counter or desk does not comply with height requirements. No equivalent facilitation is provided in the area.	2-Services	Provide at least a 36" wide portion at the compliant height.	36 inches maximum	904	2-Moderate	<a href="#">No Photo</a>	May 2014	17		
337	Barnett Arena	Exterior	Owned	Walkway	Knology Entrance	1-Public Unsupervised	Door Gate		Slope, running	Pull Side	3.40%	No	Slope is too steep.	2-Services	Rebuild the surface of the pull side of the door.	2.08%	404	1-High	<a href="#">416</a>	Nov 2014	23		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
338	Barnett Arena	Exterior	Owned	Walkway	Knology Entrance	1-Public Unsupervised	Door Gate		Height, threshold		.75 inches	No	Threshold is too high.	2-Service	Provide a threshold that is not higher than 1/2 inch, beveled.	5 inch maximum	404	2-Moderate	<a href="#">417</a>	May 2014	17		
339	Barnett Arena	Exterior	Owned	Walkway	First Interstate Bank Entrance	1-Public Unsupervised	Door Gate		Slope, running		3.20%	No	Slope is too steep.	2-Service	Rebuild the surface of the pull side of the door.	2.08%	404	1-High	<a href="#">424</a>	Nov 2014	23		
340	Barnett Arena	Exterior	Owned	Walkway	First Interstate Bank Entrance	1-Public Unsupervised	Door Gate		Height, threshold		.75 inches	No	Threshold is too high.	2-Service	Provide a threshold that is not higher than 1/2 inch, beveled.	5 inch maximum	404	2-Moderate	<a href="#">425</a>	May 2014	17		
341	Barnett Arena	Interior	Owned	Walkway	Ramp From East Parking Lot, Interior	1-Public Unsupervised	Handrail		Cross section dimension, maximum		2.5 inches	No	Diameter of the handrails are too wide	4-Other	Replace handrails with new ones that have the correct diameter.	1.25 inches minimum and 2 inches maximum	505	2-Moderate	<a href="#">No Photo</a>	Sep 2014	21		
342	Barnett Arena	Exterior	Owned	Parking Facility	East Lot	1-Public Unsupervised	Parking Space	Temporary Spaces	Access aisle?		No	No	No access aisle provided at the accessible parking spaces	1-Entry	Provide an accessible access aisle 60 inches minimum at each of the accessible parking spaces.	60 inches minimum	502.2	2-Moderate	<a href="#">429</a>	Mar 2014	15		
343	Barnett Arena	Exterior	Owned	Parking Facility	East Lot	1-Public Unsupervised	Signage	Temporary Spaces	Height, bottom		35 inches	No	Signage is too low	1-Entry	Install parking signs at correct height.	60 inches minimum	703	3-Low	<a href="#">432</a>	Sep 2013	9		
344	Barnett Arena	Exterior	Owned	Parking Facility	East Lot Overflow Parking	1-Public Unsupervised	Parking Space		Van sign?		No	No	No van sign is provided	1-Entry	Provide a Van-Accessible sign at this parking space that is located 60 inches minimum above finished surface.		502.2	3-Low	<a href="#">434</a>	Sep 2013	9		
345	Barnett Arena	Exterior	Owned	Parking Facility	East Lot Overflow Parking	1-Public Unsupervised	Signage		Height, bottom		47 inches	No	Signage is too low	1-Entry	Install parking signs at correct height.	60 inches minimum	703	3-Low	<a href="#">505</a>	Sep 2013	9		
346	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 1st Row Facing North Closest to Entrance	1-Public Unsupervised	Access Aisle	1st from Left	Width	Van Space	91 inches	No	Access aisle is not wide enough.	1-Entry	Van parking spaces shall be 132 inches wide minimum and shall have an adjacent access aisle that is 60 inches minimum. However, van parking spaces shall be permitted to be 96 inches wide minimum where the access aisle is 96 inches wide minimum. Repaint the access aisle so that is the correct width.	96 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">439</a>	Mar 2014	15		
347	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 1st Row Facing North Closest to Entrance	1-Public Unsupervised	Access Aisle	3rd from Left	Width	Van Space	92 inches	No	Access aisle is not wide enough.	1-Entry	Van parking spaces shall be 132 inches wide minimum and shall have an adjacent access aisle that is 60 inches minimum. However, van parking spaces shall be permitted to be 96 inches wide minimum where the access aisle is 96 inches wide minimum. Repaint the access aisle so that is the correct width.	96 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">440</a>	Mar 2014	15		
348	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 2nd Row Facing South	1-Public Unsupervised	Access Aisle	4th from Left	Width		53 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">449</a>	Mar 2014	15		
349	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 2nd Row Facing South	1-Public Unsupervised	Access Aisle	2nd from Left	Width		54 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">447</a>	Mar 2014	15		
350	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 2nd Row Facing North	1-Public Unsupervised	Access Aisle	1st from Left	Width		53 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">446</a>	Mar 2014	15		
351	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 2nd Row Facing North	1-Public Unsupervised	Access Aisle	3rd from Left	Width		54 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">453</a>	Mar 2014	15		
352	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 3rd Row Facing South	1-Public Unsupervised	Access Aisle	4th from Left	Width		54 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">459</a>	Mar 2014	15		
353	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 3rd Row Facing South	1-Public Unsupervised	Access Aisle	2nd from Left	Width		57 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">456</a>	Mar 2014	15		
354	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 3rd Row Facing North	1-Public Unsupervised	Access Aisle	1st from Left	Width		54 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">460</a>	Mar 2014	15		
355	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 3rd Row Facing North	1-Public Unsupervised	Access Aisle	3rd from Left	Width		57 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">462</a>	Mar 2014	15		
356	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 4th Row Facing South	1-Public Unsupervised	Access Aisle	4th from Left	Width		55 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">468</a>	Mar 2014	15		
357	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 4th Row Facing South	1-Public Unsupervised	Access Aisle	2nd from Left	Width		56 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">467</a>	Mar 2014	15		
358	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 4th Row Facing North	1-Public Unsupervised	Access Aisle	1st from Left	Width		55 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">473</a>	Mar 2014	15		
359	Barnett Arena	Exterior	Owned	Parking Facility	East Lot, 4th Row Facing North	1-Public Unsupervised	Access Aisle	3rd from Left	Width		56 inches	No	Access aisle is not wide enough.	1-Entry	Repaint the access aisle so that it is the correct width.	60 inches minimum	502.3, 502.4, 502.5	2-Moderate	<a href="#">471</a>	Mar 2014	15		
360	Barnett Arena	Exterior	Owned	Walkway	Path from East Parking to Entrance	1-Public Unsupervised	Curb Ramp	Furthest Curb Ramp from Entrance	Slope, flare	Right	11.90%	No	Slope is too steep.	1-Entry	Rebuild curb ramp with compliant side flares.	10% maximum	406	1-High	<a href="#">474</a>	Sep 2014	21		
361	Barnett Arena	Exterior	Owned	Walkway	Path from East Parking to Entrance	1-Public Unsupervised	Curb Ramp	Furthest Curb Ramp from Entrance	Slope, running		9.50%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	8.3% maximum	406	1-High	<a href="#">474</a>	Sep 2014	21		
362	Barnett Arena	Exterior	Owned	Walkway	Path from East Parking to Entrance	1-Public Unsupervised	Curb Ramp	2nd from Furthest Curb Ramp	Slope, flare	Right	11.70%	No	Slope is too steep.	1-Entry	Rebuild curb ramp with compliant side flares.	10% maximum	406	1-High	<a href="#">479</a>	Sep 2014	21		
363	Barnett Arena	Exterior	Owned	Walkway	Path from East Parking to Entrance	1-Public Unsupervised	Curb Ramp	3rd from Furthest Curb Ramp	Slope, flare	Right	12%	No	Slope is too steep.	1-Entry	Rebuild curb ramp with compliant side flares.	10% maximum	406	1-High	<a href="#">488</a>	Sep 2014	21		
364	Barnett Arena	Exterior	Owned	Walkway	Path from East Parking to Entrance	1-Public Unsupervised	Curb Ramp	3rd from Furthest Curb Ramp	Slope, running		9.90%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	8.3% maximum	406	1-High	<a href="#">486</a>	Sep 2014	21		
365	Barnett Arena	Exterior	Owned	Walkway	Path from East Parking to Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp in Front of Entrance	Slope, flare	Right	14.20%	No	Slope is too steep.	1-Entry	Rebuild curb ramp with compliant side flares.	10% maximum	406	1-High	<a href="#">492</a>	Sep 2014	21		
366	Barnett Arena	Exterior	Owned	Walkway	Path from East Parking to Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp in Front of Entrance	Slope, running		10.10%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	8.3% maximum	406	1-High	<a href="#">490</a>	Sep 2014	21		
367	Barnett Arena	Exterior	Owned	Walkway	Path from East Parking to Entrance	1-Public Unsupervised	Walking Surface	From All Curb Ramps	Slope, cross		5.40%	No	Cross slope on the walking surface is too steep.	1-Entry	Repave surface or provide an accessible route to the entrance with cross slopes that do not exceed 2.08% maximum.	2.08% maximum	403	1-High	<a href="#">493</a>	Sep 2014	21		
368	Barnett Arena	Exterior	Owned	Walkway	Path from East Parking to Entrance	1-Public Unsupervised	Walking Surface	From All Curb Ramps	Slope, running		6%	No	Running slope on the walking surface is too steep.	1-Entry	Repave surface or provide an accessible route to the entrance with running slopes that do not exceed 5% maximum.	5% maximum	403	1-High	<a href="#">492</a>	Sep 2014	21		
369	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Parking Space	Typical Parallel Accessible Parking Spaces	Access aisle?		No	No	Accessible parking spaces do not have access aisles.	1-Entry	Provide a 60 inch wide minimum access aisle adjacent to parking spaces or relocate parking space to another area that meets all accessible parking space requirements.	60 inch minimum access aisle at every accessible parking space.	502.2	2-Moderate	<a href="#">367</a>	Mar 2014	15		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
370	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Parking Space	Typical Parallel Accessible Parking Spaces	Slope, cross		6.9% to 12.9%	No	Slope is too steep.	1-Entry	Regrade parking space or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1.48, 2.08%)	2.08%	502.2	1-High	<a href="#">367</a>	Sep 2014	21		
371	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Parking Space	Typical Parallel Accessible Parking Spaces	Width		89 inches to 94.5 inches	No	Accessible parking space are not wide enough	1-Entry	Repaint the parking spaces to ensure they are 96 inches minimum wide or relocate the parking spaces to another area that meets all accessible parking space requirements.	96 inches minimum	502.2	2-Moderate	<a href="#">367</a>	Mar 2014	15		
372	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Signage	Typical Parallel Accessible Parking Spaces	Height, bottom		15 inches to 25 inches	No	Signage is too low	1-Entry	Install parking signs at correct height.	60 inches minimum	703	3-Low	<a href="#">370</a>	Sep 2013	9		
373	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Parking Space	Typical Parallel Accessible Parking Spaces	Width	Van Spaces	93 inches	No	Van accessible parking space is not wide enough	1-Entry	Van parking spaces shall be 132 inches wide minimum and shall have an adjacent access aisle that is 60 inches minimum. However, van parking spaces shall be permitted to be 96 inches wide minimum where the access aisle is 96 inches wide minimum. Repaint the space or move van accessible parking space to where this can be achieved.		502.2	2-Moderate	<a href="#">368</a>	Mar 2014	15		
374	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Parking Space	Typical Parallel Accessible Parking Spaces	Access aisle?	Van Spaces	No	No	No access aisle provided at the van accessible parking space	1-Entry	Van parking spaces shall be 132 inches wide minimum and shall have an adjacent access aisle that is 60 inches minimum. However, van parking spaces shall be permitted to be 96 inches wide minimum where the access aisle is 96 inches wide minimum. Repaint the space or move van accessible parking space to where this can be achieved.		502.2	2-Moderate	<a href="#">368</a>	Mar 2014	15		
375	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Signage	Typical Parallel Accessible Parking Spaces	Height, bottom	Van Spaces	15 inches	No	Signage is too low	1-Entry	Install parking signs at correct height.	60 inches minimum	703	3-Low	<a href="#">368</a>	Sep 2013	9		
376	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Parking Space	Typical Parallel Accessible Parking Spaces	Slope, cross	Van Spaces	7% to 10%	No	Slope is too steep.	1-Entry	Regrade parking space or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1.48, 2.08%)	2.08%	502.2	1-High	<a href="#">370</a>	Sep 2014	21		
377	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Parking Space	South Accessible Parking Spaces, 1st from Left	Slope, running	At head of space	10%	No	Slope is too steep.	1-Entry	Regrade parking space or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1.48, 2.08%)	2.08%	502.2	1-High	<a href="#">314</a>	Sep 2014	21		
378	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Signage	South Accessible Parking Spaces, 1st from Left	Height, bottom		17 inches	No	Signage is too low	1-Entry	Install parking signs at correct height.	60 inches minimum	703	3-Low	<a href="#">314</a>	Sep 2013	9		
379	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Access Aisle	South Accessible Parking Spaces, 1st from Left	Slope, running	At head of aisle	11.80%	No	Slope is too steep.	1-Entry	Regrade access aisle or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1.48, 2.08%)	2.08% Maximum	502.3, 502.4, 502.5	1-High	<a href="#">315</a>	Sep 2014	21		
380	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Parking Space	South Accessible Parking Spaces, 2nd from Left	Slope, running	At head of space	7.30%	No	Slope is too steep.	1-Entry	Regrade parking space or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1.48, 2.08%)	2.08%	502.2	1-High	<a href="#">315</a>	Sep 2014	21		
381	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Signage	South Accessible Parking Spaces, 2nd from Left	Height, bottom		17 inches	No	Signage is too low	1-Entry	Install parking signs at correct height.	60 inches minimum	703	3-Low	<a href="#">316</a>	Sep 2013	9		
382	Barnett Arena	Exterior	Owned	Parking Facility	West Parking	1-Public Unsupervised	Access Aisle	South Accessible Parking Spaces, 2nd from Left	Slope, running		6.20%	No	Slope is too steep.	1-Entry	Regrade access aisle or move accessible parking spaces and aisles to an area of parking lot that is level (slopes not > 1.48, 2.08%)	2.08% Maximum	502.3, 502.4, 502.5	1-High	<a href="#">317</a>	Sep 2014	21		
383	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp in Front of South Accessible Parking Access Aisle	Slope, counter		10.90%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	5% maximum	406	1-High	<a href="#">318</a>	Sep 2014	21		
384	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp in Front of South Accessible Parking Access Aisle	Slope, running		15%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	8.3% maximum	406	1-High	<a href="#">322</a>	Sep 2014	21		
385	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp in Front of South Accessible Parking Access Aisle on Street Side	Slope, running		12.40%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	8.3% maximum	406	1-High	<a href="#">329</a>	Sep 2014	21		
386	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp in Front of South Accessible Parking Access Aisle on Street Side	Slope, counter		7.80%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	5% maximum	406	1-High	<a href="#">326</a>	Sep 2014	21		
387	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Grating	Curb Ramp in Front of South Accessible Parking Access Aisle on Street Side	Width, opening		1 inch	No	Opening in the path of travel is too wide.	1-Entry	Repave or fill in the gap to provide a compliant surface.	5 inch maximum	302.3	2-Moderate	<a href="#">327</a>	Mar 2014	15		
388	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From South Accessible Parking 3rd from Entrance	Slope, counter		7.60%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	5% maximum	406	1-High	<a href="#">330</a>	Sep 2014	21		
389	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From South Accessible Parking 3rd from Entrance	Slope, running		21.10%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	8.3% maximum	406	1-High	<a href="#">329</a>	Sep 2014	21		
390	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From South Accessible Parking 2nd from Entrance	Height, level change		1 inch	No	There is a change in level on the in the walkway	1-Entry	Rebuild curb ramp so that the bottom of the ramp has vertical change in level not > 1/4 inch vertical or 1/2 inch beveled.	5 inch maximum	406	2-Moderate	<a href="#">335</a>	Mar 2014	15		

Record Number	Facility	Area	Owned/Leased	Room/Space	Room/Space Description	Room/Space Type	Element	Element Description	Attribute	Attribute Description/Comment	On-Site Value	Compliant	Finding	Priority	Recommendation	Recomm Value	Citation	Mitigation Difficulty	Photo Link	Milestone Date	Milestone Months	Resolution Status	Resolution Comment
391	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From South Accessible Parking 2nd from Entrance	Slope, counter		10%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	5% maximum	406	1-High	<a href="#">335</a>	Sep 2014	21		
392	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From South Accessible Parking 2nd from Entrance	Slope, running		11.60%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	8.3% maximum	406	1-High	<a href="#">334</a>	Sep 2014	21		
393	Barnett Arena	Exterior	Owned	Walkway	From West Parking To Knology Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From South Accessible Parking 1st from Entrance	Slope, counter		7.30%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	5% maximum	406	1-High	<a href="#">336</a>	Sep 2014	21		
394	Barnett Arena	Exterior	Owned	Walkway	From West Parking to 1st Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From North Accessible Parking 4th from Entrance	Height, level change		1 inch	No	There is a change in level on the in the walkway	1-Entry	Rebuild curb ramp so that the bottom of the ramp has vertical change in level not > 1/4 inch vertical or 1/2 inch beveled.	5 inch maximum	406	2-Moderate	<a href="#">342</a>	Mar 2014	15		
395	Barnett Arena	Exterior	Owned	Walkway	From West Parking to 1st Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From North Accessible Parking 4th from Entrance	Slope, counter		9.60%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	5% maximum	406	1-High	<a href="#">345</a>	Sep 2014	21		
396	Barnett Arena	Exterior	Owned	Walkway	From West Parking to 1st Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From North Accessible Parking 3rd from Entrance	Slope, counter		7.60%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	5% maximum	406	1-High	<a href="#">347</a>	Sep 2014	21		
397	Barnett Arena	Exterior	Owned	Walkway	From West Parking to 1st Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From North Accessible Parking 2nd from Entrance	Slope, running		11%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	8.3% maximum	406	1-High	<a href="#">351</a>	Sep 2014	21		
398	Barnett Arena	Exterior	Owned	Walkway	From West Parking to 1st Interstate Bank Entrance	1-Public Unsupervised	Grating	Curb Ramp From North Accessible Parking 2nd from Entrance	Width, opening		1 inch	No	Opening in the path of travel is too wide.	1-Entry	Repave or fill in the gap to provide a compliant surface.	5 inch maximum	302.3	2-Moderate	<a href="#">355</a>	Mar 2014	15		
399	Barnett Arena	Exterior	Owned	Walkway	From West Parking to 1st Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From North Accessible Parking 2nd from Entrance	Slope, counter		8.30%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	5% maximum	406	1-High	<a href="#">357</a>	Sep 2014	21		
400	Barnett Arena	Exterior	Owned	Walkway	From West Parking to 1st Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From North Accessible Parking 1st from Entrance	Slope, counter		21.50%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	5% maximum	406	1-High	<a href="#">360</a>	Sep 2014	21		
401	Barnett Arena	Exterior	Owned	Walkway	From West Parking to 1st Interstate Bank Entrance	1-Public Unsupervised	Curb Ramp	Curb Ramp From North Accessible Parking 1st from Entrance	Slope, running		10.50%	No	Slope is too steep.	1-Entry	Rebuild curb ramp, curb, and gutter to provide compliant running, cross, and counter slopes.	8.3% maximum	406	1-High	<a href="#">362</a>	Sep 2014	21		
402	Barnett Arena	Interior	Owned	Sport Area		1-Public Unsupervised	Seating Area		Seating dispersed?		No	No	Wheelchair spaces are not dispersed among the different seating types and viewing angles.	2-Services	See Executive Summary		221.2.1.4	1-High	No Photo	Nov 2014	23		