

# SOUTH DAKOTA HISTORIC INVENTORY

Historic Name Unknown

Location 911 Quincy St.

Historic \_\_\_\_\_

Function residence

Historic Context(s)

Topic iv. Permanent Rural & Urban Pioneer Settlement

Study Unit 1 2. Urban Development

Study Unit 2 2. Residential Living

Owner's Name Robert & Barbara Van Norman

Owner's Address Rt 8 Box 3020  
Rc 57702

Owner's Phone # 3480473

Dates of Construction and Founding  
1878

Roll # 21 Frame # 7-9

Attach Photos Here ↓



Site Number  

PN		RC		29
----	--	----	--	----

County Township City (Urban) Neighborhood (Urban) Number

U.S.G.S. Quad Map Name

Lots 5-6, Block 111, Original Townsite

Legal Description  

Q1	Q2	Sec	T	R

Surveyors Michael Koop

Date August 1990

NR Eligible   
 Historic Significance  Local   
 Architect. Sign  State   
 Archaeological Sign  Nat'l   
 Urban only      
 A B C D

CONTEXT

Site Number/Code PN-RC-29

Statement of Significance As It Relates to the Context Topics & Study Units.

In the context of Permanent Rural & Urban Pioneer Settlement, this house contributes to the significance of the district because it represents the historical growth and development of Rapid City.

Sources of Information

Oral Interview  
(name & dates)

Atlas  
(date & publisher)

County History  
(name & pages)

Deed Abstract

Tax Records Equalization Office records

Sanborn-Ferris  
Maps (dates) 1903, 1909, 1915, 1923, 1930

Census Records

Historic Photos  
(description & date)

Manuscripts  
(name & date)

Site Number/Code	Date of Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Photo Info.
<i>PW-RC-29</i>	<i>1878</i>	<i>residence</i>							
Materials	<i>stone</i>								
Method of Construction	<i>coursed</i>								
Design Details									
Condition	deteriorated _____ altered _____	poor maint. _____		deteriorated _____ altered _____	poor maint. _____		deteriorated _____ altered _____	poor maint. _____	
Materials	<i>clapboards</i>								
Method of Construction	<i>wood frame</i>								
Design Details									
Condition	deteriorated _____ altered _____	poor maint. _____		deteriorated _____ altered _____	poor maint. _____		deteriorated _____ altered _____	poor maint. _____	
Materials	<i>wood shingle</i>								
Method of Construction									
Design Details									
Shape									
Condition	deteriorated _____ altered _____	poor maint. _____		deteriorated _____ altered _____	poor maint. _____		deteriorated _____ altered _____	poor maint. _____	
Interior Features - Moldings, Fireplaces, Org. cabinets, Wall decoration									
Condition	deteriorated _____ altered _____	poor maint. _____		deteriorated _____ altered _____	poor maint. _____		deteriorated _____ altered _____	poor maint. _____	

Preservation Strengths of Site

- In use and not threatened
- In good structural condition
- Owners protecting site
- Appreciated by public
- Valuable to research

Preservation Threats

- Abandonment
- Deterioration through lack of resources
- Vandalism or looting
- Inappropriate alterations
- Inappropriate or poor maintenance
- Fragile or deteriorating construction materials
- Unsound fragile condition
- Lack of support (specify by whom)

---

---

---

Environmental situation(s) effecting site (specify what; may include mining, flooding erosion, pollution, acid rain, weather, isolation, settlement, etc.)

---

---

---

---

HISTORY

Date of founding of institution or of settlement \_\_\_\_\_

Previous owners of the site \_\_\_\_\_

First owners \_\_\_\_\_  
and dates \_\_\_\_\_  
of ownership \_\_\_\_\_

Place of origin of owners \_\_\_\_\_

Date owners came to SD (& USA) \_\_\_\_\_

Occupation of owners \_\_\_\_\_  
\_\_\_\_\_

Historic owners: religious affiliation \_\_\_\_\_

Historic owners: social (fraternal) affiliations \_\_\_\_\_

Historic uses of the site (& buildings) residence \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Builder's name unknown \_\_\_\_\_

Architect's name unknown \_\_\_\_\_

Date of commission \_\_\_\_\_ Date of construction 1878 \_\_\_\_\_

History (attach research materials to file)  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_