

Big Dawg Construction

2891 Leola Lane
Rapid City, SD 57703

Estimate

Number: E106

Date: March 30, 2012

Bill To:

Mike Robeck
811 St Andrew
Rapid City, SD 57701

Ship To:

PO Number	Terms	Project
		Inspection garage

Date	Description	Hours	Rate	Amount
3/26/12	Inspection of exsisting garage (1) concrete stem wall and slab cracked and show signs of settlement and displacement. (2) Bottom sill plate around bottom of garage decayed also support for garage door deayed and needs replaced. Replace structure is recommened			
<p>If you have anyquestions Please call Dave 877 6269</p>				
			Total	\$0.00