SOUTH DAKOTA HISTORIC INVENTORY	Site Nu	mber			
Historic Name Mc Gilly cuddy House	PN		RC		49
Location727 Soith St.	County	Tov	City (Url	Neig (Urb	Z
Historic	ınty	vnsh ne	City (Urban)	Neighborl (Urban)	Number
Function		Đ.		orhod	
			Map Name		Y.
Historic Context(s)			Pt of L		-57)
Topic N. Permanent Rural & Ulban Pioneer Settlement			kvere ha	dition	
Study Unit 1 D. Uchan Development	Legal De	escription	,		
Study Unit 2 2. Residential Living					
Owner's Name Harvey + Colette Davis	Q1	Q2	Sec	Τ	R
Owner's Address 727 South St.	Surveyo	ors	lichael K	-00p	3
RC 57701					
	Date	Au	gust 19	90	
Owner's Phone #341 1552		(/		
	NR Eligi	ble			
Dates of Construction and Founding	Historic	Significa	ınce 🔲		Local
	Archite	ct. Sian			State
- 9.// 12					
Roll # $\frac{12321}{2}$ Frame # $\frac{831627}{2}$	Archaed	ological S	ign		Nat'l
Attach Photos Here 4	Urban o	nly			
Altered 1/2-stony dwelling with si	tura and	·4.:	Α	В	C D
			0.2		
east and stucce perch on front and eve	esi. Diaci	KATUK CAV	٤٥.		
053 8K					

Statement of Significance As It Relates to the Context Topics & Study Units.				
This building do.	es nt waterbute to the significance of the district because of modern atterations.			
Sources of Informati	ion			
Oral Interview (name & dates)	Black Hill's Weekly Sournel & May 1877 p. 3 " The Roctor is making arrangements to build a house of white sandstone trimmed with red sandstone."			
Atlas (date & publisher)				
County History (name & pages)				
Deed Abstract				
Tax Records	Equalization Office records			
Sanborn-Ferris Maps (dates)	1923, 1535			
Census Records				
Historic Photos (description & date)	at Minnihus- Romess Museum			
Manuscripts (name & date)				

Site Number/Code	Da of	te Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Photo Info.	Date of Bldg.	Function/Bldg.	Phc Int
PN-RC-49	188	88 McGillycurally House								
Materials		ston	e							
Method of Construction	FOUNDATION	rock-faced coursed								
Design Details	DATIO									
Condition	Z	deteriorated poor altered maint		deteriorated poor altered maint		deter altere	iorated poor ed maint	poor maint		
Materials		ston	e, stucio							e =
Method of Construction	WALLS	stor	ic							
Design Details	STT									
Condition			eriorated poor red/_ maint.			orated poor d maint			iorated poor d maint.	
Materials		aszl	bult shingle							
Method of Construction		,	·							
Design Details	ROOF									
Shape		irreq	gular							
Condition			eriorated poor red/ maint.			orated poor d maint			orated poor d maint.	
Interior Features - Moldings, Fireplaces, Org. cabinets, Wall decoration	INTERIOR									
Condition			eriorated poor red maint.		deteri altere	orated poor d maint		deteri altere	oratedpoor d maint.	

Preservation Strengths of Site
In use and not threatened
In good structural condition
Owners protecting site
Appreciated by public
Preservation Threats
Abandonment
Deterioration through lack of resources
Vandalism or looting
Inappropriate alterations
Inappropriate or poor maintenance
Fragile or deteriorating construction materials
Unsound fragile condition
Lack of support (specify by whom)
Environmental situation(s) effecting site (specify what; may include mining, flooding erosion, pollution, acid rain, weather, isolation, settlement, etc.)

HISTORY

Date of founding of institution or of settlement	
Description of the city	
Previous owners of the site	
and dates of ownership	
Place of origin of owners	
Date owners came to SD (& USA)	
Occupation of owners <u>pliusician</u>	
Historic owners: religious affiliation	
Historic owners: social (fraternal) affiliations	
Historic uses of the site (& buildings)	
Builder's name	
Architect's name <u>Unkippo</u>	
Date of commission	Date of construction 1888
History (attach research materials to file)	