

Figure 1. Front of residence from Columbus street.



Figure 2. Garage from alley.



Figure3. Roof line – 3:12 or 4:12 pitch.



Figure 4. Condition of masonite siding.



Figure 5. Construction on concrete pad.



Figure 6. Recent construct of modern materials. $3\frac{1}{2}$ by $1\frac{1}{2}$ studs and trusses. Windows protrude $\frac{1}{2}$ inch to inside, fuzboard sheeting on exterior.



