



**West
Elevation**

12/05/2013



**East
Elevation**

01/14/2014



**North
Addition
wall**

12/05/2013



**Typical Ceiling Joist Damage
Above Kitchen**

01/08/2014



**Interior Structure Damage to Center
Support Beam**

01/08/2014