

SOUTH DAKOTA HISTORIC SITES INVENTORY

Historic Name _____

Address/Location 1423 9TH

Common Name _____

Historic Function _____

Historic Context(s) _____

Owner's Name _____

Owner's Address _____

Owner's Phone # _____

Date(s) of Construction _____

Photographer _____

Roll # _____ Frame #'s _____
(Attach Photographs Below)

Site Number

PN	RC	RC	WB	447
CTY	TWP	CIT	NBH	NUM

DBASE _____

U.S.G.S. Quad Map Name _____

Legal Description

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Q1	Q2	SEC	TWP	RNG

Urban LOT _____ BLK 3
Only ADD _____

Surveyors _____

Date _____

NR Eligible Yes _____ No _____
Future NR Yes _____ No _____

Significance

HIST ARCH ARCE
 NATL STAT LOCL

SOUTH DAKOTA HISTORIC SITES INVENTORY

Historic

Name Fred & Orene Meyer

Address/
Location

1423 9th Street

Common

Name

Historic

Function House

Historic

Context(s) V. Depression & Rebuilding: A.
Changing Urban Patterns: 3.
Residential Changes

Owner's Name Phyllis Lang

Owner's Address 101 S. Galena
Lead, SD 57754

Owner's Phone # (605) 584-2363

Date(s) of Construction circa 1924

Photographer M. McCormick

Roll # 8 Frame #'s 21-23
(Attach Photographs Below)

Site Number

PN -RC -RC -WB -00447
CTY TWP CIT NBH NUM

DBASE 0000000000

U.S.G.S. Quad Map Name

Legal Description

0
Q1 Q2 SEC TWP RNG
Urban Only BLK 3
LOT 30-32
ADD West Boulevard

Surveyors

M. McCormick/RTI

Date 07/03/1992

NR Eligible Y

Future NR Y

Significance HIST, ARCH
LOCL



Preservation Strengths of the Site

- In Use and Not Threatened
- In Good Structural Condition
- Owners Protecting Site
- Appreciated by Public
- Valuable to Research

Preservation Threats

- Abandonment
- Deterioration Through Lack of Resources
- Vandalism or Looting
- Inappropriate Alterations
- Inappropriate or Poor Maintenance
- Fragile or Deteriorating Construction Materials
- Unsound Condition
- Lack of Support (Specify by Whom)

Environmental Situations Effecting Site (Specify What: May Include Mining, Flooding, Erosion, Pollution, Acid Rain, Weather, Isolation, Development, Etc.)

Dates:

Founding of Institution or Settlement 1876

Town and Addition Plated 1877 1886 Initial Construction of Structure 1924

Original Owners:

Name (Include Spouse if Known) Fred & Orene Meyers

Place of Origin

Date Arrived in S.D. 0000 In USA 0000

Occupation(s) Fred: salesman

Religious Affiliation

Social/Fraternal Affiliation

Other Previous Owners:

Names and Dates of Occupation

Structural History:

Architect's Name and

Date of Commission

Builder's Name

Pattern, Book and Number/Name

Historic Uses of the Site House

Changes in Use Apartments

Statement of Historical Significance: (Including Relation to Historic Context Topics and Study Units)

The Fred & Orene Meyer House has the potential to contribute to the West Boulevard Historic District. It is significant for its association with the growth and development of the West Boulevard neighborhood in Rapid City from 1878-1942. Built in 1924, the house corresponds to the rebuilding phase of residential development in Rapid City (1897-1929), a period in which the West Boulevard neighborhood rapidly grew in response to tremendous population growth in the city. The house helps to illustrate the varied economic status of the neighborhood's inhabitants during this era and serves as a representative example of residential architecture common at the time.

Miscellaneous Historical Information:

Research indicates the houses was built in 1924, around the time that Fred Meyers received water and sewer permits for the property. Mr. Meyers and his wife Orene were the original owners of the house and resided there until at least 1928.

Bibliography:

Oral Interview (Name, Date & Relationship to Site)

Atlas (Date & Publisher)

County History (Title & Pages)

Deed Abstract

Tax Records Assessors' Card: 1927

Sanborn-Ferris Maps (Dates)

1923: vacant; 1930: house & garage

Census Records

Historical Photos (Description & Date)

Manuscripts (Name & Date)

Directories (Type & Date)

R.L. Polk: 1928, lists Fred & Orene Meyers at this address

Other Sources Rapid City Public Works, Water Permit #1455 &
Sewer Permit #631: Fred Meyer, November 1924

General Information:

Building # 1

Site No. PN-RC -RC-WB-00447 Date of Construction c.1924 Photos 21-22

Function	Apartments	Plan Form	Rectangular	Height (Stories)	1.5
Style	Vernacular	Method of Construction	Wood-frame	Overall Condition	E

Additions & Alterations (Types & Dates)

Original rear porch (west) was replaced by an exterior staircase and vestibule at rear dormer: these were modern alterations likely for conversion of the house into apartments

Evaluation of Specific Elements:

Foundation: Materials	Brick masonry	Condition	E
-----------------------	---------------	-----------	---

Walls: Cladding	Clapboard siding	Condition	E
-----------------	------------------	-----------	---

Windows: General/ Unique	Type	Glazing Pattern	Condition	Location
G	Double-hung, wood-sash	1/1	E	

Doors: Type	Glazing Pattern	Condition	Location
Full light	4x3	E	East
Not visible			West

Roof: Form	Side gable	Materials	Asphalt shingles	Condition	E
------------	------------	-----------	------------------	-----------	---

Dormer: Type	Roof: shed-roofed	Condition	E
Location(s)	East & west slopes		

Chimneys/Ventilators: Materials	Brick chimney	Condition	E
Location(s)	Interior: centered on ridge		

Porches: Materials	Condition	Height (Stories)	Roof Configuration	Location
Open: hood & knee braces	E	1	Shed	East

Bays/Towers: Form	Condition	Height (Stories)	Location(s)
-------------------	-----------	------------------	-------------

Significant Exterior Details:

Roof: boxed eaves with partial returns

Front porch (east): lattice wall on east, and concrete stoop

Significant Interior Details:

Not accessed

Blgd#	Date	C/NC	Function	Photo#	Construction Method	Height
2	c.1924	C	Garage	23	Wood-frame	1

Individual Element Cond.

Overall Condition	G	Foundation: Materials-	Concrete	E
		Walls: Cladding-	Clapboard siding	E
Windows: Type & Glazing Pattern-			Fixed; 4 light	E
Doors: Type & Glazing Pattern-			Paneled folding (2); 1/2 light	E
Roof: Form & Materials-			Gable; asphalt shingles	E
Chimney/Vent: Material & Location-				

Significant Exterior Details

Significant Interior Details

Alterations & Dates

Change in Use

Site Plan: Indicate all door and window openings, roof shapes, and landscape features.



Indicate North

