


05VE015

Improvement Location Exhibit



Access Restriction — Note Violation

Utility and Minor Drainage Easements:
8' on the interior side of all lot lines


RECEIVED

JUN 30 2005

LEGAL: Lot 1, Block 2, Kensington Heights Subdivision
Rapid City, South Dakota
CLIENT: Darrell R Olson and Chong A Kim-Olson — 559 Field View Drive
Great Western Bank Mortgage

Rapid City Growth
Management Department

I, the Registered Land Surveyor in the State of South Dakota as signed hereon, do hereby certify that this exhibit was prepared by me or under my direct supervision. The boundary lines of the parcel of land shown and described hereon are the deed lines of the property as described on the record plat of said property. The location of the major improvements are calculated from information available at the time of inspection. The dimensions to the deed lines are approximate and should not be used to establish the true boundary. THIS EXHIBIT IS NOT SUITABLE FOR CONSTRUCTION PURPOSES. Easements or restrictions of miscellaneous record or private agreement are not shown hereon.



Copy of Title Commitment _____ Provided: Not Provided

P.O. Box 8154
Rapid City, SD 57709
Phone (605) 348-1538
Fax (605) 341-1112

**FISK LAND SURVEYING
& CONSULTING ENGINEERS, INC.**

SURVEYED: ML 6/21/05

DRAWN: CTM 6/23/05

PROJECT NO. 05-143