


IMPROVEMENT LOCATION EXHIBIT
& BOUNDARY SURVEY




— x — Indicates chainlink fence

Utility Easements: 8' on the interior sides of all side and rear lot lines.

Building Setbacks- 25' Front

See plat for record bearings and distances



- Indicates found 5/8" rebar with cap marked "1019"
 - ⊙ Indicates set 5/8 rebar with cap marked "RWF 6565"
 - ⊙ Indicates corner falls in chain link fence post
- WC Witness Corner

LEGAL: Lot 12, Block 1, County Heights Subdivision
Pennington County, South Dakota

CLIENT: John Barley, Jr. -- 4710 Hamlin Court

I, the Registered Land Surveyor in the State of South Dakota as signed hereon, do hereby certify that this drawing was prepared by me or under my direct supervision. The boundary lines of the parcel of land shown and described hereon are the deed lines of the property as described on the record plat of said property. The location of the major improvements are geometrically calculated from the nearest reliable property corners. This is a boundary survey and the precise property lines were determined at the time of this survey. The dimensions to the deed lines are shown to the degree of accuracy required to satisfy the needs of a lending institution or title company and should be used to establish the true boundary. Easements or restrictions of miscellaneous record or private agreements that are not known to me are not shown hereon.

Copy of Title Commitment _____ Provided: Not Provided



P.O.Box 8154
Rapid City, SD 57709
Phone (605) 348-1538
Fax (605) 341-1112

FISK LAND SURVEYING
& CONSULTING ENGINEERS, INC.

SURVEYED: RWF 3/11/03

DRAWN: CTM 3/17/03

PROJECT NO. 03-102